

0042



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Norman H. Bangertter
Governor
Dee C. Hansen
Executive Director
Dianne R. Nielson, Ph.D.
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

INSPECTION REPORT

INSPECTION DATE & TIME: February 24, 1989
12:30 p.m. to 2:30 p.m.

Permittee and/or Operators Name: North American Equities (NAE) (415)866-7186
Operator's Repr.: William Prince; Holme, Robert & Owen (801)521-5800
Business Address: 50 S. Main Street, Salt Lake City, UT 84114
Mine Name: Blazon #1 Mine Permit Number: INA/007/021
Type of Mining Activity: Underground XX Surface Other
County: Carbon
Company Official (s): None
State Official(s): Harold G. Sandbeck and Bill Malencik
Partial: Complete: XX Date of Last Inspection:
Weather Conditions: Clear and cold
Acreage: Permitted 320 Disturbed 1.5 Regraded Seeded Bonded 1.5
Enforcement Action: None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	(XX)	()	()	(XX)
2. SIGNS AND MARKERS	(XX)	()	()	()
3. TOPSOIL	(XX)	()	()	()
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	(XX)	()	()	()
b. DIVERSIONS	(XX)	()	()	()
c. SEDIMENT PONDS AND IMPOUNDMENTS	(XX)	()	()	()
d. OTHER SEDIMENT CONTROL MEASURES	(XX)	()	()	()
e. SURFACE AND GROUNDWATER MONITORING	(XX)	()	()	(XX)
f. EFFLUENT LIMITATIONS	(XX)	()	()	()
5. EXPLOSIVES	()	()	(XX)	()
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	(XX)	()	()	()
7. COAL PROCESSING WASTE	()	()	(XX)	()
8. NONCOAL WASTE	(XX)	()	()	()
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	(XX)	()	()	()
10. SLIDES AND OTHER DAMAGE	(XX)	()	()	()
11. CONTEMPORANEOUS RECLAMATION	(XX)	()	()	()
12. BACKFILLING AND GRADING	(XX)	()	()	()
13. REVEGETATION	(XX)	()	()	()
14. SUBSIDENCE CONTROL	(XX)	()	()	()
15. CESSATION OF OPERATIONS	(XX)	()	()	()
16. ROADS				
a. CONSTRUCTION	(XX)	()	()	()
b. DRAINAGE CONTROLS	(XX)	()	()	()
c. SURFACING	(XX)	()	()	()
d. MAINTENANCE	(XX)	()	()	()
17. OTHER TRANSPORTATION FACILITIES	()	()	(XX)	()
18. SUPPORT FACILITIES UTILITY INSTALLATIONS	(XX)	()	()	()

INSPECTION REPORT
(continuation sheet)

Page 2 of 2

PERMIT NUMBER: INA/007/021

DATE OF INSPECTION 02/24/89

(Comments are Numbered to Correspond with Topics Listed Above)

General Comments. The site was inaccessible. The undersigned inspector walked up to the gate and found no evidence of recent activity.

1. Permits.

Bond The bond was renewed and expires on June 30, 1989.

4. Hydrologic Balance:

e. Surface and Groundwater Monitoring.

The low flow 1988 December water data was received by the Division on February 9, 1989. No problems were noted. For additional information the reader is referred to the November 17, 1988 inspection report.

Copy of this Report:

Mailed to: Mr. William Prince (Holme, Robert & Owen), Price Office and

Mailed to: Brian Smith (OSM)

Given to: Sue Linner and Joe Helfrich - DOGM

Inspectors Signature and Number: *Samuel J. Jan* #27 Date: 02/27/89