2-10-89
7026

0045

SU

State of Utah
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Norman H. Bangerter
Governor
Dee C. Hansen
Executive Director
Dianne R. Nielson, Ph.D.
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

INSPECTION REPORT

INSPECTION DATE & TIME: January 31, 1989
8:30am - 9:00am

Permittee and/or Operators Name: North American Equities (NAE)
Operator Repr.: William Prince; Holme, Robert & Owen
Business Address: 50 South Main Street, Salt Lake City, Utah 84114
Mine Name: Blazon Permit Number: ACT/007/021
Type of Mining Activity: Underground X Surface ____ Other ____
County: Carbon
Company Official (s): None
State Official(s): Lynn Kunzler
Partial: X Complete: ____ Date of Last Inspection: December 14, 1988
Weather Conditions: Cold and clear.
Acreage: Permitted 320 Disturbed 1.5 Regraded ____ Seeded ____ Bonded 1.5
Enforcement Action: None.

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	( )	( )	( )	( )
2. SIGNS AND MARKERS	( )	( )	( )	( )
3. TOPSOIL	( )	( )	( )	( )
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	( )	( )	( )	( )
b. DIVERSIONS	( )	( )	( )	( )
c. SEDIMENT PONDS AND IMPOUNDMENTS	( )	( )	( )	( )
d. OTHER SEDIMENT CONTROL MEASURES	( )	( )	( )	( )
e. SURFACE AND GROUNDWATER MONITORING	( )	( )	( )	( )
f. EFFLUENT LIMITATIONS	( )	( )	( )	( )
5. EXPLOSIVES	( )	( )	( )	( )
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	( )	( )	( )	( )
7. COAL PROCESSING WASTE	( )	( )	( )	( )
8. NONCOAL WASTE	( )	( )	( )	( )
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	( )	( )	( )	( )
10. SLIDES AND OTHER DAMAGE	( )	( )	( )	( )
11. CONTEMPORANEOUS RECLAMATION	( )	( )	( )	( )
12. BACKFILLING AND GRADING	( )	( )	( )	( )
13. REVEGETATION	( )	( )	( )	( )
14. SUBSIDENCE CONTROL	( )	( )	( )	( )
15. CESSATION OF OPERATIONS	( )	( )	( )	( )
16. ROADS				
a. CONSTRUCTION	( )	( )	( )	( )
b. DRAINAGE CONTROLS	( )	( )	( )	( )
c. SURFACING	( )	( )	( )	( )
d. MAINTENANCE	( )	( )	( )	( )
17. OTHER TRANSPORTATION FACILITIES	( )	( )	( )	( )
18. SUPPORT FACILITIES UTILITY INSTALLATIONS	( )	( )	( )	( )

an equal opportunity employer

INSPECTION REPORT
(continuation sheet)

PERMIT NUMBER: ACT/007/021

DATE OF INSPECTION: 1/31/89

(Comments are Numbered to Correspond with Topics Listed Above)

The site was inaccessable due to snow accumulation. No activity has occurred on site since last inspection.

Copy of this Report:
Mailed to: Brian Smith - OSMRE, PFO
Given to: Joe Helfrich & Sue Linner - DOGM

Inspectors Signature and Number: #17 Date: 2-1-89