



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Norman H. Bangarter
Governor
Dee C. Hansen
Executive Director
Dianne R. Nielson, Ph.D.
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

DR7
gch

INSPECTION REPORT

INSPECTION DATE & TIME: October 25, 1990
4:00 pm to 5:00 pm

Permittee and/or Operators Name: North American Equities (NAE)(415)866-7186
Operator's Representative: %Adam Affleck; Holme, Roberts & Owen (801)521-580
Business Address: 50 S. Main Street, Salt Lake City, UT 84114
Mine Name: Blazon #1 Mine Permit Number: INA/007/021
Type of Mining Activity: Underground Surface Other
County: Carbon
Company Official (s): None
State Official(s): Randy Harden
Partial: Complete: Date of Last Inspection: September 7, 1990
Weather Conditions: Cloudy, Cool, Muddy
Acreage: Permitted 320 Disturbed 1.5 Regraded Seeded Bonded 1.5
Enforcement Action: None.

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	(X)	()	()	(X)
2. SIGNS AND MARKERS	()	()	()	()
3. TOPSOIL	()	()	()	()
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	()	()	()	()
b. DIVERSIONS	(X)	()	()	()
c. SEDIMENT PONDS AND IMPOUNDMENTS	(X)	()	()	(X)
d. OTHER SEDIMENT CONTROL MEASURES	(X)	()	()	(X)
e. SURFACE AND GROUNDWATER MONITORING	()	()	()	()
f. EFFLUENT LIMITATIONS	()	()	()	()
5. EXPLOSIVES	()	()	()	()
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	()	()	()	()
7. COAL PROCESSING WASTE	()	()	()	()
8. NONCOAL WASTE	()	()	()	()
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	()	()	()	()
10. SLIDES AND OTHER DAMAGE	()	()	()	()
11. CONTEMPORANEOUS RECLAMATION	()	()	()	()
12. BACKFILLING AND GRADING	()	()	()	()
13. REVEGETATION	(X)	()	()	(X)
14. SUBSIDENCE CONTROL	()	()	()	()
15. CESSATION OF OPERATIONS	()	()	()	()
16. ROADS				
a. CONSTRUCTION	()	()	()	()
b. DRAINAGE CONTROLS	()	()	()	()
c. SURFACING	()	()	()	()
d. MAINTENANCE	()	()	()	()
17. OTHER TRANSPORTATION FACILITIES	()	()	()	()
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	()	()	()	()

INSPECTION REPORT
(continuation sheet)

Page 2 of #2

PERMIT NUMBER: INA/007/021

DATE OF INSPECTION September 7, 1990

(Comments are Numbered to Correspond with Topics Listed Above)

1. PERMITS

NAE's Permit will expire on November 12, 1990. In accordance with the findings of the Board Hearing of October 25, 1990, NAE will not be required to submit application for permit renewal. The remaining reclamation activities, including monitoring and maintenance will be performed in accordance with the approved plan and with the performance standards of the regulations.

4. HYDROLOGIC BALANCE:

c. SEDIMENT PONDS AND IMPOUNDMENTS

No discharge from the sediment pond was occurring at the time of the inspection. Repairs to the sediment pond discharge have been completed by the operator and the sediment pond was found to be functioning in accordance with the approved design.

d. OTHER SEDIMENT CONTROL MEASURES

Straw bales and silt fences installed on the site were found to be in operating condition and no need for maintenance or repair of the facilities was noted.


13. REVEGETATION

NOV N90-13-3-1 was modified to allow sufficient time for the supplemental seeding of the cut slopes along the access road to the mine facilities. This seeding must be accomplished on or before 5:00 pm on November 16, 1990.

Copy of this Report:

Mailed to: Brian Smith - OSM, Mr. Adam Affleck - Holme, Roberts & Owen

Given to: Joe Helfrich - DOGM, Daron Haddock - DOGM

Inspectors Signature and Number: #13  Date: November 8, 1990