

7/11
13-3-1

gjk



UTAH
NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • 801-538-5340

NO. N90-17-2-2

notice of violation

To the following Permittee or Operator:

Name North American Equities

Mine Blazon #1 Mine Surface Underground Other

County Carbon State Utah Telephone (801) 521-5800

Mailing Address Gottlieb Roberts & Owens, 50 S. Main St, SLC UT 84114

State Permit No. ACT/007/021

Ownership Category State Federal Fee Mixed

Date of inspection Aug 14, 1990, 19__

Time of inspection 9:30 a.m. p.m. to 1:05 a.m. p.m.

Operator Name (other than Permittee) _____

Mailing Address _____

Under authority of the Utah Coal Mining and Reclamation Act, Section 40-10-1 et seq., **Utah Code Annotated**, 1953, the undersigned authorized representative of the Division of Oil, Gas & Mining has conducted an inspection of above mine on above date and has found violation(s) of the act, regulations or required permit condition(s) listed in attachment(s). This notice constitutes a separate Notice of Violation for each violation listed.

You must abate each of these violations within the designated abatement time. You are responsible for doing all work in a safe and workmanlike manner.

The undersigned representative finds that **cessation of mining** is is not expressly or in practical effect required by this notice. For this purpose, "mining" means extracting coal from the earth or a waste pile, and transporting it within or from the mine site.

This notice shall remain in effect until it expires as provided on reverse side of this form, or is modified, terminated or vacated by written notice of an authorized representative of the director of the Division of Oil, Gas & Mining. Time for abatement may be extended by authorized representative for good cause, if a request is made within a reasonable time before the end of abatement period.

Date of service/mailling Aug 14, 1990

Time of service/mailling 1:05 a.m. p.m.

Anthony Maggipochino
Permittee/Operator representative

Hydrogeologist (EarthFox Eng'g Inc)
Title

Anthony Maggipochino
Signature

Lynn Kunzler
Division of Oil, Gas & Mining representative

Senior Reclamation Biologist
Title

Lynn M. K.
Signature

#17
Identification Number

SEE REVERSE SIDE

WHITE-DOGM YELLOW-OSM PINK-PERMITTEE/OPERATOR GOLDENROD-NOV FILE



NOTICE OF VIOLATION NO. 190-17-2-2

Violation No. 1 of 2

Nature of violation

Failure to Pass runoff from Disturbed area through
Sediment Control

Provisions of act, regulations or permit violated

R614-301-742,
R614-301-752,

Portion of operation to which notice applies

- 1. Silt Fence along toe of Portal Slope.
- 2. Straw bales along road ditch

Remedial action required (including any interim steps)

- 1. remove sediment build up from section where silt fence
was overtopped (near south end of slope)
- 2. repair or replace silt fence with holes (near
middle and north end)
- 3. clean sediment from behind bales in road ditch to restore
function of bales, replace bales as needed.

Abatement time (including interim steps)

by August 31, 1990 (@ 4:00 PM)



NOTICE OF VIOLATION NO. N90-17-Z-2

Violation No. 2 of 2

Nature of violation

Failure to maintain culverts. ^{LMK.} ~~Failure to maintain culverts.~~

Provisions of act, regulations or permit violated

R614-301-742, 423, 2
R614-301-752

Portion of operation to which notice applies

1. Culvert in Ditch B in front of Little Snyder Drop Structure,
2. Road Culvert near toe of Sediment Pond
3. Road Culvert near gate.

Remedial action required (including any interim steps)

Restore drainage through culverts by removing debris and sediment.

Abatement time (including interim steps)

by Aug 31, 1990 at 4:00 PM