0024

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

0024

inspection report

Permit No. INA/007/021

Inspection Date June 14, 1990

Permittee/Operator Name North American Equities (NAE) (415) 866-7186

Business Address 50 S. Main Street, Salt Lake City, Utah 84114

City Salt Lake City State Utah Zip 84114

Mine Blazon Mine ☐ Surface ☒ Underground ☐ Other

County Carbon State

Company Official(s) Earth Fax

State Official(s) Harold Sandbeck and John Pappas

Time of inspection 9:00 ☒ a.m. ☐ p.m. to 10:00 ☐ a.m. ☒ p.m. ☐ Partial ☒ Complete

Date of last inspection May 14, 1990 Weather conditions Clear / Warm

Acreage 320 ☒ Permitted 1.5 ☒ Disturbed ☐ Regraded ☐ Seeded 1.5 ☒ Bonded

Enforcement Action None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☒	☐	☐	☐
2. Signs and markers	☒	☐	☐	☒
3. Topsoil	☒	☐	☐	☐
4. Hydrologic balance				
a Stream channel diversions	☒	☐	☐	☐
b Diversions	☒	☐	☐	☐
c Sediment ponds and impoundments	☒	☐	☐	☐
d Other sediment control measures	☒	☐	☐	☒
e Surface and groundwater monitoring	☒	☐	☐	☐
f Effluent limitations	☒	☐	☐	☐
5. Explosives	☐	☐	☒	☐
6. Development waste and spoil disposal	☒	☐	☐	☐
7. Coal processing waste	☐	☐	☒	☐
8. Noncoal waste	☒	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☒	☐	☐	☐
10. Slides and other damage	☒	☐	☐	☐
11. Contemporaneous reclamation	☒	☐	☐	☐
12. Backfilling and grading	☒	☐	☐	☐
13. Revegetation	☒	☐	☐	☐
14. Subsidence control	☒	☐	☐	☐
15. Cessation of operations	☒	☐	☐	☐
16. Roads				
a Construction	☒	☐	☐	☐
b Drainage controls	☒	☐	☐	☐
c Surfacing	☒	☐	☐	☐
d Maintenance	☒	☐	☐	☐
17. Other transportation facilities	☐	☐	☒	☐
18. Support facilities and utility installations	☒	☐	☐	☐

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. INA/007/021

Inspection Date June 14, 1990

Please number comments to correspond with topics on previous page.

2.) Signs and Markers

All signs and markers appeared to be in order.

4.d.) Hydrologic Balance – Other Sediment control measures

Earthfax, the operator's consultant, was on site to maintain strawbales and silt fences. The control structures appeared to be functioning properly.

Copy of report mailed to Mr. Adam Affleck (Holme, Roberts & Owen), Price Office, Brian Smith (OSM) and Carol Bjork (Earthfax Engineering, Inc)

Copy of report given to Daron Haddock and Joe Helfrich

Inspector's signature Howard R. Hancock No. 27

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

an equal opportunity employer