



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

John *AR7*

Norman H. Bangerter
Governor
Dee C. Hansen
Executive Director
Dianne R. Nielson, Ph.D.
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

INSPECTION REPORT

INSPECTION DATE & TIME: February 27, 1990
3:30 p.m. to 4:00 p.m.

Permittee and/or Operators Name: North American Equities (NAE) (415)866-7186
Operator's Repr.: William Prince; Holme, Robert & Owen (801)521-5800
Business Address: 50 S. Main Street, Salt Lake City, UT 84114
Mine Name: Blazon #1 Mine Permit Number: INA/007/021
Type of Mining Activity: Underground Surface Other
County: Carbon
Company Official (s): None
State Official(s): Harold G. Sandbeck
Partial: XXX Complete: Date of Last Inspection: 1/10/90
Weather Conditions: Clear and cold
Acreage: Permitted 320 Disturbed 1.5 Regraded Seeded Bonded 1.5
Enforcement Action: N90-27-2-1 (See Number 1)

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	()	(XX)	()	(XX)
2. SIGNS AND MARKERS	(XX)	()	()	()
3. TOPSOIL	()	()	()	()
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	(XX)	()	()	()
b. DIVERSIONS	(XX)	()	()	()
c. SEDIMENT PONDS AND IMPOUNDMENTS	(XX)	()	()	(XX)
d. OTHER SEDIMENT CONTROL MEASURES	(XX)	()	()	()
e. SURFACE AND GROUNDWATER MONITORING	()	()	()	()
f. EFFLUENT LIMITATIONS	()	()	()	()
5. EXPLOSIVES	()	()	()	()
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	()	()	()	()
7. COAL PROCESSING WASTE	()	()	()	()
8. NONCOAL WASTE	()	()	()	()
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	()	()	()	()
10. SLIDES AND OTHER DAMAGE	()	()	()	()
11. CONTEMPORANEOUS RECLAMATION	()	()	()	()
12. BACKFILLING AND GRADING	()	()	()	()
13. REVEGETATION	()	()	()	()
14. SUBSIDENCE CONTROL	()	()	()	()
15. CESSATION OF OPERATIONS	()	()	()	()
16. ROADS				
a. CONSTRUCTION	()	()	()	()
b. DRAINAGE CONTROLS	()	()	()	()
c. SURFACING	()	()	()	()
d. MAINTENANCE	()	()	()	()
17. OTHER TRANSPORTATION FACILITIES	()	()	()	()
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	()	()	()	()

INSPECTION REPORT
(continuation sheet)

Page 2 of 2

PERMIT NUMBER: INA/007021

DATE OF INSPECTION 2/27/90

(Comments are Numbered to Correspond with Topics Listed Above)

General Comments. The operator was unavailable to accompany the undersigned inspector on this partial inspection. Snow cover was in excess of 18 inches. Due to heavy snow cover the site was inaccessible.

1. Permits.

TDN 89-02-116-2: On February 7, 1990, OSM suspended further action regarding the inappropriate finding of this TDN for a period of 90 days. During this 90 day period, Utah's Board of Oil, Gas and Mining will hold a hearing concerning Blazon's bond release application. After the hearing, OSM will revisit the site.

N90-27-2-1: This violation was issued on February 27, 1990 for failure to amend the reclamation plan. The violation was mailed from the office on March 1, 1990. The abatement date is April 2, 1990.

Bond: The bond expires on June 30, 1990.

Insurance: The operator's insurance expires on November 22, 1990.

4. Hydrologic Balance.

c. Sediment Ponds and Impoundments.

The operator was informed (via telephone on March 16, 1990) to conduct a 1990 1st quarter pond inspection report before the end of March 1990.

Copy of this Report:

Mailed to: Mr. William Prince (Holme, Robert & Owen), Price Office

Mailed to: Brian Smith (OSM) and Carol Bjork (Earthfax Engineering, Inc)

Given to: Daron Haddock and Joe Helfrich - DOGM

Inspectors Signature and Number: Harold J. Hamilton #27 Date: 3/16/90