



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Handwritten initials/signature

Norman H. Bangertter
Governor
Dee C. Hansen
Executive Director
Dianne R. Nielson, Ph.D.
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

INSPECTION REPORT

INSPECTION DATE & TIME: 1/16/91
4:30pm

Permittee and/or Operator's Name: North American Equities
Business Address: c/o Adam Affleck, Holme, Roberts & Owen
(801) 521-5800
Mine Name: Blazon #1 Mine Permit Number: INA/007/021
Type of Mining Activity: Underground Surface Other
County: Carbon Company Official(s): None
State Official(s): Priscilla Burton
Federal Official(s): None
Partial: Complete Date of last Inspection: 12/17/90
Weather Conditions: Sunshine, cold, 3'snow on ground
Acreage: Permitted 320 Disturbed 2.5 Regraded 2.5 Seeded 2.5
Bonded 2.5 Enforcement Action: None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	()	()	()	()
2. SIGNS AND MARKERS	(x)	()	()	()
3. TOPSOIL	()	()	()	()
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	()	()	()	()
b. DIVERSIONS	()	()	()	()
c. SEDIMENT PONDS AND IMPOUNDMENTS	()	()	()	()
d. OTHER SEDIMENT CONTROL MEASURES	(x)	()	()	(x)
e. SURFACE AND GROUNDWATER MONITORING	()	()	()	()
f. EFFLUENT LIMITATIONS	()	()	()	()
5. EXPLOSIVES	()	()	()	()
6. DISPOSAL OF DEVELOPMENT WASTE & SPOIL	()	()	()	()
7. COAL PROCESSING WASTE	()	()	()	()
8. NONCOAL WASTE	()	()	()	()
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	()	()	()	()
10. SLIDES AND OTHER DAMAGE	(x)	()	()	(x)
11. CONTEMPORANEOUS RECLAMATION	()	()	()	()
12. BACKFILLING AND GRADING	()	()	()	()
13. REVEGETATION	()	()	()	()
14. SUBSIDENCE CONTROL	()	()	()	()
15. CESSATION OF OPERATIONS	()	()	()	()
16. ROADS				
a. CONSTRUCTION	()	()	()	()
b. DRAINAGE CONTROLS	()	()	()	()
c. SURFACING	()	()	()	()
d. MAINTENANCE	()	()	()	()
17. OTHER TRANSPORTATION FACILITIES	()	()	()	()
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	()	()	()	()

INSPECTION REPORT

(Continuation sheet)

Page 2 of 2

PERMIT NUMBER: INA/007/021

DATE OF INSPECTION: 1/16/91

(Comments are Numbered to Correspond with Topics Listed Above)

4. HYDROLOGIC BALANCE:

a. OTHER SEDIMENT CONTROL MEASURES

The silt fences were buried by snow. The culverts were clear of obstruction.

10. SLIDES AND OTHER DAMAGE:

The reclaimed slope appeared stable.

Copy of this Report:

Mailed to: Brian Smith - OSM,

Adam Affleck - Holme, Roberts & Owen

Given to: Daron Haddock - DOGM, Joe Helfrich - DOGM

Inspector's Signature & Number: Pasilla Burton #37 Date: 1/21/91