

0044

1020



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Norman H. Bangarter
Governor

Dee C. Hansen
Executive Director

Dianne R. Nielson, Ph.D.
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

INSPECTION REPORT

INSPECTION DATE & TIME: January 10, 1990
4:30 p.m. to 5:00 p.m.

Permittee and/or Operators Name: North American Equities (NAE) (415)866-7186
Operator's Repr.: William Prince; Holme, Robert & Owen (801)521-5800
Business Address: 50 S. Main Street, Salt Lake City, UT 84114
Mine Name: Blazon #1 Mine Permit Number: INA/007/021
Type of Mining Activity: Underground Surface Other
County: Carbon
Company Official (s): None
State Official(s): Harold G. Sandbeck
Partial: XXX Complete: Date of Last Inspection: 12/5/89
Weather Conditions: Clear and cool
Acreage: Permitted 320 Disturbed 1.5 Regraded Seeded Bonded 1.5
Enforcement Action: N90-27-1-1 (See Number 4e)

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	(XX)	()	()	(XX)
2. SIGNS AND MARKERS	(XX)	()	()	()
3. TOPSOIL	()	()	()	()
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	(XX)	()	()	()
b. DIVERSIONS	(XX)	()	()	()
c. SEDIMENT PONDS AND IMPOUNDMENTS	(XX)	()	()	(XX)
d. OTHER SEDIMENT CONTROL MEASURES	(XX)	()	()	()
e. SURFACE AND GROUNDWATER MONITORING	()	(XX)	()	(XX)
f. EFFLUENT LIMITATIONS	()	()	()	()
5. EXPLOSIVES	()	()	()	()
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	()	()	()	()
7. COAL PROCESSING WASTE	()	()	()	()
8. NONCOAL WASTE	()	()	()	()
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	()	()	()	()
10. SLIDES AND OTHER DAMAGE	()	()	()	()
11. CONTEMPORANEOUS RECLAMATION	()	()	()	()
12. BACKFILLING AND GRADING	()	()	()	()
13. REVEGETATION	()	()	()	()
14. SUBSIDENCE CONTROL	()	()	()	()
15. CESSATION OF OPERATIONS	()	()	()	()
16. ROADS				
a. CONSTRUCTION	()	()	()	()
b. DRAINAGE CONTROLS	()	()	()	()
c. SURFACING	()	()	()	()
d. MAINTENANCE	()	()	()	()
17. OTHER TRANSPORTATION FACILITIES	()	()	()	()
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	()	()	()	()

INSPECTION REPORT
(continuation sheet)

Page 2 of 2

PERMIT NUMBER: INA/007021

DATE OF INSPECTION 1/10/90

(Comments are Numbered to Correspond with Topics Listed Above)

General Comments. The operator was unavailable to accompany the undersigned inspector on this partial inspection. Snow cover was in excess of 18 inches.

1. Permits.

Bond

The renewed letter of credit was received by the Division on December 29, 1989. The bond expires on June 30, 1990.

Insurance

The operator's insurance expires on November 22, 1990.

4. Hydrologic Balance.

c. Sediment Ponds and Impoundments.

The 1989 4th quarter pond inspection report was inspected. No problems were noted.

e. Surface and Groundwater Monitoring.

N90-27-1-1 was issued on January 10, 1990 for failure to conduct surface water monitoring. The violation was terminated the same day.

Copy of this Report:

Mailed to: Mr. William Prince (Holme, Robert & Owen), Price Office ,
Mailed to: Brian Smith (OSM) and Carol Bjork (Earthfax Engineering, Inc)
Given to: Sue Linner and Joe Helfrich - DOGM

Inspectors Signature and Number: *Howard J. Handberg* #27 Date: 1/17/90