0001

Norman H. Bangerter
Governor
Dee C. Hansen
Executive Director
Dianne R. Nielson, Ph.D.
Division Director

State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

INSPECTION REPORT

INSPECTION DATE & TIME: December 20, 1991
10:30 am to 11:30 am

Permittee and/or Operators Name: North American Equities, (NAE) (415) 866-7186
Business Address: No Known Address or Resident Agent

Mine Name: Blazon #1 Mine Permit Number: INA/007/021
Type of Mining Activity: Underground X Surface ____ Other ____
County: Carbon County
Company Official(s): ____
State Official(s): Randy Harden
Partial: X Complete: ____ Date of Last Inspection: November 4, 1991
Weather Conditions: Cold and Snowing
Acreage: Permitted 320 Disturbed 4.5 Regraded 2.5 Seeded 2.5 Bonded 2.5
Enforcement Action: None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	( )	( )	(X)	(X)
2. SIGNS AND MARKERS	( )	( )	( )	( )
3. TOPSOIL	( )	( )	( )	( )
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	( )	( )	( )	( )
b. DIVERSIONS	( )	( )	( )	( )
c. SEDIMENT PONDS AND IMPOUNDMENTS	( )	( )	( )	( )
d. OTHER SEDIMENT CONTROL MEASURES	( )	( )	( )	( )
e. SURFACE AND GROUNDWATER MONITORING	( )	( )	( )	( )
f. EFFLUENT LIMITATIONS	( )	( )	( )	( )
5. EXPLOSIVES	( )	( )	( )	( )
6. DISPOSAL OF DEVELOPMENT WASTE & SPOIL	( )	( )	( )	( )
7. COAL PROCESSING WASTE	( )	( )	( )	( )
8. NONCOAL WASTE	( )	( )	( )	( )
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	( )	( )	( )	( )
10. SLIDES AND OTHER DAMAGE	( )	( )	( )	( )
11. CONTEMPORANEOUS RECLAMATION	( )	( )	( )	( )
12. BACKFILLING AND GRADING	( )	( )	( )	( )
13. REVEGETATION	( )	( )	( )	( )
14. SUBSIDENCE CONTROL	( )	( )	( )	( )
15. CESSATION OF OPERATIONS	( )	( )	( )	( )
16. ROADS				
a. CONSTRUCTION	( )	( )	( )	( )
b. DRAINAGE CONTROLS	( )	( )	( )	( )
c. SURFACING	( )	( )	( )	( )
d. MAINTENANCE	( )	( )	( )	( )
17. OTHER TRANSPORTATION FACILITIES	( )	( )	( )	( )
18. SUPPORT FACILITIES UTILITY INSTALLATIONS	( )	( )	( )	( )

INSPECTION REPORT
(continuation sheet)

PERMIT NUMBER: INA/007/021 DATE OF INSPECTION: December 20, 1991
(Comments are Numbered to Correspond with Topics Listed Above)

1. PERMITS

Two failure to abate cessation notices are still currently outstanding as a result of NOV 91-39-4-2, 1 of 2, and, 2 of 2. To date, the operator has declared insolvency, and has been unresponsive to all notices and orders submitted by the Division in regard to these violations.

Subsequent actions by the Division led to bond forfeiture in the amount of $38,000 on May 31, 1991.

CT Corporation System has notified the Division the according to their records, their statutory representation services were discontinued and all process sent to the last known address were returned as undeliverable. CT Corporation System does not have any other addresses in their files to which they can forward documents. CT has returned all of these documents and has filed resignation of agent in all states where permitted.

The minesite was inaccessible due to snow cover. Access by vehicle can only be made to the town of Clear Creek.

Copy of this Report:
Mailed to: Bernie Freeman - OSM
Given to: Daron Haddock - DOGM, Joe Helfrich - DOGM

Inspectors Signature & Number: # 13 Date: February 3, 1992