



# State of Utah

DEPARTMENT OF NATURAL RESOURCES  
DIVISION OF OIL, GAS AND MINING

Norman H. Bangertter  
Governor

Dee C. Hansen  
Executive Director

Dianne R. Nielson, Ph.D.  
Division Director

355 West North Temple  
3 Triad Center, Suite 350  
Salt Lake City, Utah 84180-1203  
801-538-5340

*John ORZ*

## INSPECTION REPORT

INSPECTION DATE & TIME: March 20, 1991

4:30 pm to 5:00 pm

Permittee and/or Operators Name: North American Equities, (NAE) (415) 866-7186  
 Business Address: %Adam Affleck, Holme, Roberts & Owen (801) 521-5800  
 Mine Name: Blazon #1 Mine Permit Number: INA/007/021  
 Type of Mining Activity: Underground  Surface  Other   
 County: Carbon County  
 Company Official(s): None  
 State Official(s): Randy Harden, Rick Summers  
 Partial:  Complete:  Date of Last Inspection: February 20, 1991  
 Weather Conditions: Cold, Partly Cloudy, approximately 4' of snow on the ground  
 Acreage: Permitted 320 Disturbed 4.5 Regraded 2.5 Seeded 2.5 Bonded 2.5  
 Enforcement Action: None

### COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	( )	( )	(X)	(X)
2. SIGNS AND MARKERS	(X)	( )	( )	( )
3. TOPSOIL	(X)	( )	( )	( )
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	(X)	( )	( )	( )
b. DIVERSIONS	(X)	( )	( )	( )
c. SEDIMENT PONDS AND IMPOUNDMENTS	(X)	( )	( )	( )
d. OTHER SEDIMENT CONTROL MEASURES	(X)	( )	( )	( )
e. SURFACE AND GROUNDWATER MONITORING	(X)	( )	( )	( )
f. EFFLUENT LIMITATIONS	(X)	( )	( )	( )
5. EXPLOSIVES	( )	( )	(X)	( )
6. DISPOSAL OF DEVELOPMENT WASTE & SPOIL	(X)	( )	( )	( )
7. COAL PROCESSING WASTE	( )	( )	(X)	( )
8. NONCOAL WASTE	(X)	( )	( )	( )
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	(X)	( )	( )	( )
10. SLIDES AND OTHER DAMAGE	(X)	( )	( )	( )
11. CONTEMPORANEOUS RECLAMATION	( )	( )	(X)	( )
12. BACKFILLING AND GRADING	(X)	( )	( )	( )
13. REVEGETATION	(X)	( )	( )	( )
14. SUBSIDENCE CONTROL	( )	( )	(X)	( )
15. CESSATION OF OPERATIONS	( )	( )	(X)	( )
16. ROADS				
a. CONSTRUCTION	(X)	( )	( )	( )
b. DRAINAGE CONTROLS	(X)	( )	( )	( )
c. SURFACING	(X)	( )	( )	( )
d. MAINTENANCE	(X)	( )	( )	( )
17. OTHER TRANSPORTATION FACILITIES	(X)	( )	( )	( )
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	(X)	( )	( )	( )

**INSPECTION REPORT**  
(continuation sheet)

Page 2 of 2

PERMIT NUMBER: INA/007/021 DATE OF INSPECTION: March 20, 1991  
(Comments are Numbered to Correspond with Topics Listed Above)

1. PERMITS

The site is currently under approximately 4 feet of snow. No vehicular access to the site is possible. Snow cover and depth made access to the site on foot impossible at the time of the inspection. Evidence from the access road to the mine site would indicate that no one has been to the site recently on foot or by any vehicle.

NAE's Permit Expired on November 12, 1990. By Board Order, the operator is not required to renew the Permit in order to complete reclamation activities. Results from the Board Order, dated February 28, 1991, are as follows:

1. NOV 90-13-4-1 is vacated.
2. NOV 90-28-6-1 is vacated.
3. Mr. Otani's objections to NAE's application for Phase I bond release are denied.
4. NAE's Bond is hereby partially release to the extent of \$10,400, leaving NAE's total bond to be \$38,000.


Bond release as a result of the Board Order will not occur until such time as the Reclamation Agreement has been provided by the operator.

The letter of credit for the site has been replaced by the operator. The current Irrevocable Letter of Credit is with United Bank of Denver, issued February 8, 1991, in the amount of \$48,400.00. Expiration date for the letter of credit is January 31, 1992.

Copy of this Report:

Mailed to: Brian Smith - OSM, Adam Affleck - Holme, Roberts & Owen

Given to: Daron Haddock - DOGM, Joe Helfrich - DOGM

Inspectors Signature & Number:  # 13 Date: April 25, 1991