



# State of Utah

DEPARTMENT OF NATURAL RESOURCES  
DIVISION OF OIL, GAS AND MINING

Norman H. Bangarter  
Governor

Dee C. Hansen  
Executive Director

Dianne R. Nielson, Ph.D.  
Division Director

355 West North Temple  
3 Triad Center, Suite 350  
Salt Lake City, Utah 84180-1203  
801-538-5340

007  
Jok

## INSPECTION REPORT

Permit No. ACT/007/021 Inspection Date: January 9, 1992  
 Permittee and/or Operators Name: North American Equities  
 Business Address: CT Corporation, 8th Floor, 50 W. Broadway  
 City: Salt Lake City State: Utah Zip: 84101  
 Mine Name: Blazon #1 Mine County: Carbon State: Utah  
 Type of Mining Activity: Underground XX Surface Other  
 Company Officials: Steve Tanner State Officials: Stephen J. Demczak  
 Time of Inspection: 10:00 a.m. - 11:00 a.m. Partial X Complete:       
 Acreage: Permitted 320 Disturbed 4.5 Regraded 2.5  
 Seeded 2.5 Bonded 2.5 Date Last Inspected: December 1991  
 Weather Conditions: Approx. 5 Degrees Enforcement Action: None

### COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	NOTES
1. <u>PERMITS</u>	( <u>X</u> )	( <u>    </u> )	( <u>    </u> )	( <u>X</u> )
2. <u>SIGNS AND MARKERS</u>	( <u>    </u> )			
3. <u>TOPSOIL</u>	( <u>    </u> )			
4. <u>HYDROLOGIC BALANCE:</u>				
a. <u>STREAM CHANNEL DIVERSIONS</u>	( <u>    </u> )			
b. <u>DIVERSIONS</u>	( <u>    </u> )			
c. <u>SEDIMENT PONDS AND IMPOUNDMENTS</u>	( <u>    </u> )			
d. <u>OTHER SEDIMENT CONTROL MEASURES</u>	( <u>    </u> )			
e. <u>SURFACE AND GROUNDWATER MONITORING</u>	( <u>    </u> )			
f. <u>EFFLUENT LIMITATIONS</u>	( <u>    </u> )			
5. <u>EXPLOSIVES</u>	( <u>    </u> )			
6. <u>DISPOSAL OF DEVELOPMENT WASTE AND SPOIL</u>	( <u>    </u> )			
7. <u>COAL PROCESSING WASTE</u>	( <u>    </u> )			
8. <u>NONCOAL WASTE</u>	( <u>    </u> )			
9. <u>PROTECTION OF FISH, WILDLIFE AND     RELATED ENVIRONMENTAL VALUES</u>	( <u>    </u> )			
10. <u>SLIDES AND OTHER DAMAGE</u>	( <u>    </u> )			
11. <u>CONTEMPORANEOUS RECLAMATION</u>	( <u>    </u> )			
12. <u>BACKFILLING AND GRADING</u>	( <u>    </u> )			
13. <u>REVEGETATION</u>	( <u>    </u> )			
14. <u>SUBSIDENCE CONTROL</u>	( <u>    </u> )			
15. <u>CESSATION OF OPERATIONS</u>	( <u>    </u> )			
16. <u>ROADS</u>				
a. <u>CONSTRUCTION</u>	( <u>    </u> )			
b. <u>DRAINAGE CONTROLS</u>	( <u>    </u> )			
c. <u>SURFACING</u>	( <u>    </u> )			
d. <u>MAINTENANCE</u>	( <u>    </u> )			
17. <u>OTHER TRANSPORTATION FACILITIES</u>	( <u>    </u> )			
18. <u>SUPPORT FACILITIES</u>				
<u>UTILITY INSTALLATIONS</u>	( <u>    </u> )			
19. <u>AVS Check</u>	( <u>    </u> )			

Permit No. ACT/007/021 Inspection Date January 9, 1992

(Comments are Numbered to Correspond with Topics Listed Above)

1. Permits -

- a. Blazon presently has a Cessation Order CF 91-39-1-2 for failure to abate violations N91-39-4-2, 1 of 2 and 2 of 2. This is concerning diversions and silt fence maintenance and has been unresponsive to all notices by the Division in regards to the violations.
- b. The Division has forfeited the bond for the amount of \$38,000 on May 31, 1991.

FIELD INSPECTION -

Mine site inaccessible due to heavy snowfall.

Copy of report:


Mailed to: North American Equities

Mailed to SLC for: Brian Smith (OSM) Joe Helfrich (DOGM)

Filed to: PFO

Date: January 13, 1992

Inspector's Signature and Number:

  
Stephen J. Demczak

#39