STATE OF UTAH
NATURAL RESOURCES
Division of Oil, Gas & Mining
3 Triad Center · Suite 350 · Salt Lake City, UT 84180-1203 · (801) 538-5340

0010

ACT/007/022 gl

inspection report

☑ Partial
☐ Complete
☐ Exploration

Inspection Date: June 9, 1995
Time: 1 : 00 ☐am ☑pm to 3 : 30 ☐am ☑pm
Date of Last Inspection: 5/4/95

Mine Name: C.V Spur County: Carbon Permit Number: Act 007/022
Permittee and/or Operator's Name: Mountain Coal Co/ Savage Industries Inc
Business Address: 555, 17th St. Rm 2170, Denver, Colo 80202
Type of Mining Activity: ☐ Underground ☐ Surface ☑ Prep. Plant ☐ Other
State Officials(s): Bill Malencik
Company Official(s): Boyd & Dustin Rhodes, Dan Guy & Dana Ballard
Federal Official(s): N/A
Weather Conditions: Clear - Temp 60°
Existing Acreage: Permitted-160 Disturbed-122 Regraded-____ Seeded-____ Bonded-122
Increased/Decreased: Permitted-____ Disturbed-____ Regraded-____ Seeded-____ Bonded-____
Status: ☐ Exploration / ☐ Active / ☐ Inactive / ☐ Temporary Cessation / ☐ Bond Forfeiture
☐ Reclamation (☐ Phase I / ☐ Phase II / ☐ Final Bond Release / ☐ Liability____Year)
☑ Followup pages 2 & 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

Instructions
1. Substantiate the elements on this inspection by checking the appropriate performance standard.
   a. For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
   b. For partial inspections check only the elements evaluated.
2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

	EVALUATED	N/A	COMMENTS	NOV/ENF
1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE	☑	☐	☑	☐
2. SIGNS AND MARKERS	☐	☐	☐	☐
3. TOPSOIL	☐	☐	☐	☐
4. HYDROLOGIC BALANCE:				
a. DIVERSIONS	☑	☐	☑	☐
b. SEDIMENT PONDS AND IMPOUNDMENTS	☑	☐	☑	☐
c. OTHER SEDIMENT CONTROL MEASURES	☑	☐	☐	☐
d. WATER MONITORING	☐	☐	☐	☐
e. EFFLUENT LIMITATIONS	☐	☐	☐	☐
5. EXPLOSIVES	☐	☑	☐	☐
6. DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES	☐	☐	☐	☐
7. COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS	☑	☐	☐	☐
8. NONCOAL WASTE	☑	☐	☐	☐
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	☐	☐	☐	☐
10. SLIDES AND OTHER DAMAGE	☐	☐	☐	☐
11. CONTEMPORANEOUS RECLAMATION	☐	☐	☐	☐
12. BACKFILLING AND GRADING	☐	☐	☐	☐
13. REVEGETATION	☐	☐	☐	☐
14. SUBSIDENCE CONTROL	☐	☑	☐	☐
15. CESSATION OF OPERATIONS	☐	☐	☐	☐
16. ROADS:				
a. CONSTRUCTION/MAINTENANCE/SURFACING	☑	☐	☑	☐
b. DRAINAGE CONTROLS	☑	☐	☑	☐
17. OTHER TRANSPORTATION FACILITIES	☐	☐	☐	☐
18. SUPPORT FACILITIES/UTILITY INSTALLATIONS	☐	☐	☐	☐
19. AVS CHECK (4th Quarter-April, May, June)____(date)	☐	☐	☐	☐
20. AIR QUALITY PERMIT	☐	☐	☐	☐
21. BONDING & INSURANCE	☐	☐	☐	☐

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. Act 007/022

Inspection Date 6/9/95

Please number comments to correspond with topics on previous page.

Permit. The permit is in the name and in the full control of Mtn Coal Co. Savage Industries is the operator and has a contract of sale to acquire the prep plant. The only pending matter to my knowledge in completing the permit transfer is Savage Ind. acquiring the necessary bond. Ms. P.B. Beville of the ARCO Denver office has kept the undersigned updated relative to bonding status.

Diversions. Several diversions were cleaned during the reporting period. The cleanout material associated with culvert and/or cleaning drepression/sumps at the culvert inlets and outlets was temporarily stored adjacent to the culvert. Instructed the operator to remove such material to the refuse pile

Sediment Ponds. All five sediment ponds and the water impoundment are contained water. No were discharging at the time of the inspection. The water impoundment and four sediment ponds are discharge into pond #6. It does not appear that pond 6 discharged during the current inspection period.

Copy of report mailed to

Copy of report given to

Inspector's signature No.

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE

UTAH NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. Act007/022

Inspection Date 6/9/95

Please number comments to correspond with topics on previous page.

Pond #6 was cleaned since the last inspection and sediment deposited and stored on the CV Spur refuse pile.

Refuse pile. Observed refuse pile. Some pond cleanout material has recently been added to and stored in the central portion of the pile. It needs to be spread and compacted.

No impounded runoff was observed on the pile. Observed the controlled runoff system on the top of the pile. The runoff on the top of the pile is primarily sheet flow and controlled by an exterior berm to prevent uncontrolled discharge over the outslope. The discharge from the top of the pile is accomodated by a culvert.

Roads. Roads have recently been graded. Gravel has been recently placed on the road near the office.

Road ditches were observed and some had been graded since the last inspection.

Copy of report mailed to MCC/Paige B. Beville; OSM/Donna Griffin; DOGM/Joe Helfrich

Copy of report ~~given to~~ filed Price Field Office

Inspector's signature Tim J. Gnalenich No. 26

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE

6/15/95