



STATE OF UTAH
NATURAL RESOURCES
Oil, Gas & Mining

Norman H. Bangerter, Governor
Dee C. Hansen, Executive Director
Dianne R. Nielson, Ph.D., Division Director

355 W. North Temple • 3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • 801-538-5340

INSPECTION REPORT

Permittee and/or Operators Name: BERNER CO. COAL COMPANY (BCCC)
 Business Address: P.O. Box 1378 PRICE UT 84501
 Mine Name: C.V. SPUR PREPARATION PLANT Permit Number: ACT/007/022
 Type of Mining Activity: Underground Surface Other PREPARATION PLANT
 County: CARBON
 Company Official(s): DAN GAY
 State Official(s): DAVID LOE
 Inspection Date and Time: 12/14/85 1:00-5:30 PM
 Partial: Complete: Date of Last Inspection: 10/29/85
 Weather Conditions: Clear Sunny & Cold
 Acreage: Permitted 117 Disturbed Regraded Seeded Bonded
 Enforcement Action: NONE

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	Comments
1. PERMITS	()	()	()	()
2. SIGNS AND MARKERS	()	()	()	()
3. TOPSOIL	()	()	()	()
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	()	()	()	()
b. DIVERSION'S	()	()	()	()
c. SEDIMENT PONDS AND IMPOUNDMENTS	()	()	()	()
d. OTHER SEDIMENT CONTROL MEASURES	()	()	()	()
e. SURFACE AND GROUNDWATER MONITORING	()	()	()	()
f. EFFLUENT LIMITATIONS	(X)	()	()	(X)
5. EXPLOSIVES	()	()	()	()
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	()	()	()	()
7. COAL PROCESSING WASTE	(X)	()	()	(X)
8. NONCOAL WASTE	()	()	()	()
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	()	()	()	()
10. SLIDES AND OTHER DAMAGE	()	()	()	()
11. CONTEMPORANEOUS RECLAMATION	()	()	()	()
12. BACKFILLING AND GRADING	()	()	()	()
13. REVEGETATION	()	()	()	()
14. SUBSIDENCE CONTROL	()	()	()	()
15. CESSATION OF OPERATIONS	()	()	()	()
16. ROADS				
a. CONSTRUCTION	()	()	()	()
b. DRAINAGE CONTROLS	()	()	()	()
d. SURFACING	()	()	()	()
e. MAINTENANCE	()	()	()	()
17. OTHER TRANSPORTATION FACILITIES	()	()	()	()
18. SUPPORT FACILITIES AND UTILITY INSTALLATIONS	()	()	()	()

INSPECTION REPORT
(Page 2)

Permit Number: ACT/007/022

Date of Inspection: 12/11/85

COMMENTS

(Comments are Numbered to Correspond with Topics Listed Above)

A.F. EFFLUENT LIMITATIONS

NPDES MONITORING REPORTS WERE AVAILABLE THROUGH 3rd QTR OF 1985,
THE REPORT INDICATED THAT THERE HAD BEEN NO DISCHARGE.

7. COAL PROCESSING WASTE

THE OPERATOR HAD REFUSE DISPOSAL SITE QUARTERLY INSPECTION REPORTS
AVAILABLE THROUGH THE 3rd QTR. OF 1985. THE REPORTS DID NOT
INDICATE ANY PROBLEMS WITH THE SITE. MR. GUY SAID HE HAD BEEN
TO THE SITE IN THE LAST FEW DAYS AND THAT EVERYTHING WAS OK AT THAT
TIME. HE IS GOING TO WAIT UNTIL THE END OF THE MONTH TO DO THE 4th QTR
INSPECTION. THE PREPARATION PLANT IS NOT ACTIVE AT THIS TIME SO THE
ONLY MATERIALS BEING DISPOSED OF AT THE SITE IS REJECT FROM CARBON
C.S. #2+7 WHICH CANNOT BE COVERED UNDERGROUND.

STATISTICS: SEE TOWER RESOURCES, CENTENNIAL PROJECT MEMO FOR 12/11/85
INSPECTION.

Copy of this Report:

Mailed to: DAN GUY, BCCC DONNA GRIFFIN, OSM

Given to: JOE HEURICH + KEN MAY

Inspectors Signature and Number: David J. #1

0365Q 1-2

12/17/85