0009

UTAH NATURAL RESOURCES
Oil, Gas & Mining
3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

inspection report

Permit No. ACT/007/022
Inspection Date 6/28/88

Permittee/Operator Name Beaver Creek Coal Company
Business Address P.O. Box 1378
City Price State Ut Zip 84501
Mine GV Spur ☐ Surface ☐ Underground ☒ Other
County Carbon State Ut
Company Official(s) Dan Guy
State Official(s) Jim Fricke, Rick Smith
Time of inspection 10:00 ☒ a.m. ☐ p.m. to 12:00 ☐ a.m. ☒ p.m. ☒ Partial ☐ Complete
Date of last inspection 5/10/88 Weather conditions cloudy
Acreage 160 ☒ Permitted 108 ☒ Disturbed ☐ Regraded ☐ Seeded 160 ☒ Bonded
Enforcement Action None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☐	☐	☐	☐
2. Signs and markers	☒	☐	☐	☐
3. Topsoil	☐	☐	☐	☐
4. Hydrologic balance				
— Stream channel diversions	☐	☐	☐	☐
b — Diversions	☒	☐	☐	☒
c — Sediment ponds and impoundments	☒	☐	☐	☒
— Other sediment control measures	☐	☐	☐	☐
— Surface and groundwater monitoring	☐	☐	☐	☐
— Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☐	☐	☐	☐
8. Noncoal waste	☐	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☒	☐	☐	☒
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
— Construction	☐	☐	☐	☐
— Drainage controls	☐	☐	☐	☐
— Surfacing	☐	☐	☐	☐
— Maintenance	☒	☐	☐	☐
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/007/022

Inspection Date 6/28/88

Please number comments to correspond with topics on previous page.

4b. Culverts were inspected and ~~in~~ were all functional. Several culverts will require weed removal from the inlet area.

4c. Ponds 1, 2, 3, 5 and 6 were inspected. All ponds are in a functional condition.

13. The vegetation test plot appears to have some successful ~~a~~ vegetation growing.

Copy of report mailed to Dan Guy (BCCC) & Brian Smith (OSM)

Copy of report given to Joe Helfrich CDOGM

Inspector's signature Jim Fricke No. 22

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE