

Document Information Form

Mine Number: C/007/022

File Name: Internal

To: DOGM

From:

Person N/A

Company N/A

Date Sent: N/A

Explanation:

REFUSE PILE INSPECTION REPORT

cc:

File in: C/007/022, 1992, Internal

- Refer to:
- Confidential
 - Shelf
 - Expandable

Date _____ For additional information

Route to Pass then file
ACT/007/022 #6

REFUSE PILE INSPECTION REPORT

MSHA SITE #1211-UT-9-0034

C.V. SPUR

QUARTER 1/92

ITEM	REMARKS
(1) Potential Safety Hazards	None Noted.
(2) Slope Stability	Stable - Berm intact around top. No erosion on side slope. Good drainage control.
(3) Removal of Topsoil and Organics	N/A - Some green vegetation showing up on test plots.
(4) Construction and Maintenance Performance Standards	Good - Pile well graded & compacted. Slope protected. Minor amount of piled material in center.
(5) Recommendations	Pile looks good. Cover outlet culvert. Grade out piled material.

I have performed the above inspection on this refuse pile and do hereby certify it to be a true and accurate representation of the pile at this time.

File in:
 Confidential
 Shelf
 Expandable
 Refer to Record No 0011 Date N/A
 In C1007/022, 1992 Internal
 For additional information

