



The State of Utah
 Department of
 Natural Resources
 Division of
 Oil, Gas & Mining

ROBERT L. MORGAN
Executive Director

LOWELL P. BRAXTON
Division Director

OLENE S. WALKER
Governor

GAYLE F. McKEACHNIE
Lieutenant Governor

Representatives Present During the Inspection:	
Company	Boyd Rhodes
Company	Dan Guy
OGM	Steve Demczak Environmental Scientist III

Inspection Report

Permit Number:	C0070022
Inspection Type:	COMPLETE
Inspection Date:	Tuesday, April 13, 2004
Start Date/Time:	04/13/2004 10:00:00 AM
End Date/Time:	04/13/2004 4:00:00 PM
Last Inspection:	Tuesday, March 09, 2004

Inspector: Steve Demczak, Environmental Scientist III

Weather: Cloudy, 40's

InspectionID Report Number: 239

Accepted by: dhaddock
 04/30/2004

Permittee: **SAVAGE SERVICES**

Operator: **SAVAGE SERVICES**

Site: **SAVAGE COAL TERMINAL**

Address: **6340 S 3000 E STE 600, SALT LAKE CITY UT 84121**

County: **CARBON**

Permit Type: **PERMANENT COAL PROGRAM**

Permit Status: **ACTIVE**

Current Acreages

160.00	Total Permitted
122.28	Total Disturbed
	Phase I
	Phase II
	Phase III

Mineral Ownership

- Federal
- State
- County
- Fee
- Other

Types of Operations

- Underground
- Surface
- Loadout
- Processing
- Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Permit Conditions- The permittee must submit water quality data, by using the electronic water quality data system.

The permittee has submitted permit renewal information to the Division. The task number is 1902.

No violations have been issued.

Inspector's Signature: _____

Date Tuesday, April 20, 2004

Steve Demczak, Environmental Scientist III

Inspector ID Number: 39

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining

1594 West North Temple, Suite 1210, PO Box 145801, Salt Lake City, UT 84114-5801
 telephone (801) 538-5340 facsimile (801) 359-3940 TTY (801) 538-7223 www.ogm.utah.gov

Utah!
Where ideas connect™

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENT

1. *Substantiate the elements on this inspection by checking the appropriate performance standard.*
 - a. *For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.*
 - b. *For PARTIAL inspections check only the elements evaluated.*
2. *Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.*
3. *Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.*
4. *Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.*

	Evaluated	Not Applicable	Comment	Enforcement
1. Permits, Change, Transfer, Renewal, Sale	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Signs and Markers	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Topsoil	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.a Hydrologic Balance: Diversions	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.b Hydrologic Balance: Sediment Ponds and Impoundments	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.c Hydrologic Balance: Other Sediment Control Measures	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.d Hydrologic Balance: Water Monitoring	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.e Hydrologic Balance: Effluent Limitations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
5. Explosives	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Disposal of Excess Spoil, Fills, Benches	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Coal Mine Waste, Refuse Piles, Impoundments	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
8. Noncoal Waste	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
9. Protection of Fish, Wildlife and Related Environmental Issues	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Slides and Other Damage	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Contemporaneous Reclamation	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Backfilling And Grading	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. Revegetation	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14. Subsidence Control	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. Cessation of Operations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16.a Roads: Construction, Maintenance, Surfacing	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16.b Roads: Drainage Controls	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
17. Other Transportation Facilities	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
18. Support Facilities, Utility Installations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
19. AVS Check	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
20. Air Quality Permit	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
21. Bonding and Insurance	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
22. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

1. Permits, Change, Transfer, Renewal, Sale

The permittee has submitted permit renewal information to the Division. The task is #1902.

2. Signs and Markers

The permittee has installed two identification signs at the main gates to the property. The signs meet the requirements of the R645 Coal Rules.

3. Topsoil

The topsoil pile was inspected with no signs of water or wind erosion. A small amount of vegetation has started to appear on the pile. Quantity of vegetation will be determined on the amount of rainfall the area receives. The pocking of the pile has some positive impacts to vegetative growth.

4.a Hydrologic Balance: Diversions

The diversions were spot inspected and would function as designed. Several diversions were cleaned out since the last inspection. Sediment had started to build-up within the diversion.

4.b Hydrologic Balance: Sediment Ponds and Impoundments

Sediment ponds were inspected with no hazardous conditions noticed during the inspection. No sediment pond was discharging during the inspection. The permittee plans in the summer to clean out several of the sediment ponds. The sediment pond was inspected for the first quarter by the permittee on March 24, 2004. No hazardous conditions were reported.

4.d Hydrologic Balance: Water Monitoring

The permittee has submitted the fourth quarter water information into the electronic water data system.

4.e Hydrologic Balance: Effluent Limitations

The UPDES permit was effective on May 1, 2003 and will expire on April 30, 2008. There were not discharges for the first quarter.

7. Coal Mine Waste, Refuse Piles, Impoundments

The permittee had graded the slopes of the refuse pile. Some erosion had occurred due to snow melt. The refuse pile for the first quarter was inspected on March 23, 2004. No hazardous conditions were reported.

8. Noncoal Waste

The disturbed area was clear of non-coal waste material.

18. Support Facilities, Utility Installations

No new support facilities were installed since the last inspection.

21. Bonding and Insurance

The permittee has renewed the insurance policy. This policy meets the minimum requirements of the R645 Coal Rules. The bonding amount is \$2,525,000.