

WATER QUALITY MEMORANDUM

Utah Coal Regulatory Program

OK

August 7, 2006

TO: Internal File

THRU: D. Wayne Hedberg, Permit Supervisor *DWH*

FROM: *DD* Dana Dean, P.E., Senior Reclamation Hydrologist

RE: 2005 Third Quarter Water Monitoring, Savage Services Corporation, Savage Coal Terminal, C/007/0022, Task #2515

The Savage Coal Terminal is an operating coal loadout where coal is crushed, screened, blended, and then loaded onto rail transport.

Pertinent water monitoring requirement information is in the MRP in Sections 7.16, and 7.2.5, and figure 7-15.

1. Was data submitted for all of the MRP required sites? YES NO

Springs –

The Permittee is not required to monitor any springs at the Savage Coal Terminal.

Streams –

The Permittee is required to sample CV-14-W for the parameters outlined in Figure 7-15 in the second and fourth quarter of each year.

The Permittee is not required to monitor any streams during the third quarter.

Wells–

The Permittee is required to sample CV-1-W for the parameters outlined in Figure 7-15 in the second and fourth quarter of each year.

The Permittee is not required to monitor any wells during the third quarter.

UPDES–

There is one active UPDES outfall at the Savage Coal Terminal, CV-15-W, or UTG040005-001. The Permittee is required to monitor this UPDES site monthly.

The Permittee monitored and reported the essential data for CV-15-W as required during

this quarter. The UPDES site recorded no flow during the period.

2. Were all required parameters reported for each site? YES NO
3. Were any irregularities found in the data? YES NO
4. On what date does the MRP require a five-year re-sampling of baseline water data.

There is no commitment in the MRP to resample for baseline parameters.

5. Based on your review, what further actions, if any, do you recommend?

No further actions are required at this time.