

SAVAGE COAL TERMINAL REFUSE PILE INSPECTION REPORT

MSHA SITE: *1211-UT-09-01444-01 QUARTER: 1-2011

ITEM	REMARKS
(1) Potential Safety Hazards	None Noted. No Water Impoundment.
(2) Slope Stability	Slopes appear stable.
(3) Removal of Topsoil/Organics.	N/A - No removal necessary.
(4) Construction and Maintenance Performance Standards.	Ditches - O.K. No Berms Needed - No Top Area.
(5) Recommendations/Comments.	Sign - O.K. Continuing to Load Out Pile from South and West End.

I have performed the above inspection on this refuse pile and do hereby certify it to be a true and accurate representation of the pile at this time.



RECEIVED

APR - 5 2011

OGM PRICE FIELD OFFICE

 Dan W. Guy 3/29/11
(Signature/Date)