

SAVAGE
P.O.Box 1001
Price, Utah 84501

C/007/0022
Received 2/2/15
Task ID #4795

February 2, 2015


Mr. Daron Haddock
Coal Regulatory Program Manager
Utah Division of Oil, Gas, & Mining
1594 West North Temple, Suite 1210
PO Box 145801
Salt Lake City, Utah 84114 – 5801

Dear Mr. Haddock:

Please find attached the Annual Report for the Savage Energy Terminal. If you have any questions, please contact me at 435-637-5664.

Thank you.

Sincerely,

A handwritten signature in black ink, appearing to read "Garth Nielsen", with a long horizontal flourish extending to the right.

Garth Nielsen
General Manager

Attachments

Print Form

Submit by Email

Reset Form

Annual Report

This Annual Report shows information the Division has for your mine. Submit the completed document and any additional information identified in the Appendices to the Division by the date specified in the cover letter. During a complete inspection an inspector will check and verify the information.

GENERAL INFORMATION

Company Name	Savage Services Corporation	Mine Name	Savage Coal Terminal
Permit Number	C/007/0022	Permit expiration Date	2019-08-07
Operator Name	Savage Coal Terminal	Phone Number	+1 (435) 637-5664
Mailing Address	P.O. Box 1001	Email	garthnielsen@savageservices.com
City	Price		
State	UT	Zip Code	84501

DOGM File Location or Annual Report Location

Excess Spoil Piles

- Required
 Not Required

Refuse Piles

- Required
 Not Required

Included in Appendix A

Impoundments

- Required
 Not Required

Included in Appendix A

Other:

OPERATOR COMMENTS

Reports included in Appendix A.

REVIEWER COMMENTS

- Met Requirements Did Not meet Requirements

COMMITMENTS AND CONDITIONS

The Permittee is responsible for ensuring annual technical commitments in the Mining and Reclamation Plan and conditions accepted with the permit are completed throughout the year. The Division has identified these commitments below and has provided space for you to report what you have done during the past year for each commitment. If additional written response is required, it should be filed as an attachment to this report.

Title: NOXIOUS WEED CONTROL

Objective: To control invasive species in and adjacent to the disturbed area. The permittee should obtain a list of noxious weeds from the county and invasive species from DWR.

Frequency: Ongoing treatment. Report annually

Status: Ongoing

Reports: Summarize treatment in Annual report.

Citation: MRP, Volume 1, Section 3.4.5.4 or .5, page 3-62a

Operator Comments

Past removal of Tamerisk and Russian Olive. No new removal needed in 2014.

Reviewer Comments Met Requirements Did Not Meet Requirements

FUTURE COMMITMENTS AND CONDITIONS

The following commitments are not required for the current annual report year, but will be required by the permittee in the future as indicated by the "status" field. These commitments are included for information only, and do not currently require action. If you feel that the commitment is no longer relevant or needs to be revised, please contact the Division.

Title: WASTE STREAM FROM PROCESSING PLANT
Objective: Provide documentation of chemical characteristics of process waste returned to site through analysis of parameters.
Frequency: Sample every 5,000 tons returned to site.
Status: Ongoing, report required if waste is returned to site. Or, state if reported in Dugout Annual Report.
Reports: Submit Laboratory analysis sheets with annual report.
Citation: MRP, Volume 1, Chapter 5, Appendix 5-2.

Title: FINAL RECLAMATION SOIL TESTING
Objective: To ensure vegetation establishment
Frequency: At final reclamation
Status: At reclamation
Reports: Discussions with DOGM and laboratory analysis reporting required at final reclamation.
Citation: MRP, Volume 1, Chapter 5, Section 542.200, page 50

Title: SEALING OF WELLS
Objective: Permanent closure of wells using measures required by DOGM to prevent access and prevent contamination of ground water.
Frequency: Seal wells when no longer needed.
Status: Ongoing
Reports: Report status when mining is terminated or wells are no longer needed.
Citation: MRP, Volume 2, Chapter 6, Section 631, page 5, and Volume 1, Chapter 5, page 46.

OPERATOR COMMENTS (OPTIONAL)

REVIEWER COMMENTS

REPORTING OF OTHER TECHNICAL DATA

Please list other technical data or information that was not included in the form above, but is required under the approved plan, which must be periodically submitted to the Division.

Please list attachments:

N/A

Reviewer Comments

MAPS

Copies of mine maps, current and up-to-date, are to be provided to the Division as an attachment to this report in accordance with the requirements of R645-301-525.240. The map copies shall be made in accordance with 30 CFR 75.1200 as required by MSHA. Mine maps are not considered confidential.

Map Name	Map Number	Included		Confidential	
		Yes	No	Yes	No
N/A		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Reviewer Comments Met Requirements Did Not Meet Requirements

2014 Annual Report

Appendix A

Certified Reports

Refuse Pile Inspections

Annual Impoundment Inspections


SAVAGE COAL TERMINAL REFUSE PILE INSPECTION REPORT

MSHA SITE: 1211-UT-09-01444-01


QUARTER: 1st - 2014

ITEM	REMARKS
(1) Potential Safety Hazards	None Noted. No Water Impoundment.
(2) Slope Stability	Stable. Most of Pile is gone.
(3) Removal of Topsoil/Organics.	N/A - No removal necessary.
(4) Construction and Maintenance Performance Standards.	Ditches - O.K. No Berms Needed - No Top Area.
(5) Recommendations/Comments	Very small amount of gob and sediment pond cleanout left. Sign O.K.

I have performed the above inspection on this refuse pile and do hereby certify it to be a true and accurate representation of the pile at this time.


Signature

03/29/14
Date




**SAVAGE COAL TERMINAL
REFUSE PILE INSPECTION REPORT**

MSHA SITE: 1211-UT-09-01444-01

QUARTER: 2nd - 2014

ITEM	REMARKS
(1) Potential Safety Hazards	None Noted.
(2) Slope Stability	Stable. Pile is gone.
(3) Removal of Topsoil/Organics.	N/A - No removal necessary.
(4) Construction and Maintenance Performance Standards.	Ditches - O.K.
(5) Recommendations/Comments	None. Pile has been removed.

I have performed the above inspection on this refuse pile and do hereby certify it to be a true and accurate representation of the pile at this time.



Signature

06/28/14

Date




**SAVAGE COAL TERMINAL
REFUSE PILE INSPECTION REPORT**

MSHA SITE: 1211-UT-09-01444-01

QUARTER: 3rd - 2014

ITEM	REMARKS
(1) Potential Safety Hazards	None Noted.
(2) Slope Stability	Stable. About 2 truckloads of refuse.
(3) Removal of Topsoil/Organics.	N/A - No removal necessary.
(4) Construction and Maintenance Performance Standards.	Ditches - O.K.
(5) Recommendations/Comments	None. Most of pile has been removed. Sign is O.K.

I have performed the above inspection on this refuse pile and do hereby certify it to be a true and accurate representation of the pile at this time.



Signature

09/29/14

Date




**SAVAGE COAL TERMINAL
REFUSE PILE INSPECTION REPORT**

MSHA SITE: 1211-UT-09-01444-01

QUARTER: 4th - 2014

ITEM	REMARKS
(1) Potential Safety Hazards	None Noted.
(2) Slope Stability	Stable. About 2 truckloads of refuse.
(3) Removal of Topsoil/Organics.	N/A - No removal necessary.
(4) Construction and Maintenance Performance Standards.	Ditches - O.K.
(5) Recommendations/Comments	None. Most of pile has been removed. Sign is O.K.


I have performed the above inspection on this refuse pile and do hereby certify it to be a true and accurate representation of the pile at this time.



Signature

10/28/14

Date



**SAVAGE SERVICES CORPORATION
2014 ANNUAL POND INSPECTION REPORT**

POND: Sediment Pond 1 **LOCATION:** Savage Coal Terminal

IMPOUNDMENTS	
(1) Stability	<i>Slopes Stable. Incised Pond</i>
(2) Structural Weakness/Erosion	<i>None Noted.</i>
(3) Potential Safety Hazards	<i>None Noted.</i>
(4) Depth of Impounded Water	<i>3.0' Water.</i>
(5) Existing Storage Capacity	<i>0.73 acre feet.</i>
(6) Monitoring Procedures	<i>Quarterly Inspection.</i>

SEDIMENT PONDS ONLY	
(7) Sediment Accumulation (Elevation)	<i>5486.00</i>
(8) 60% Sediment Cleanout Level (Elevation)	<i>5487.20</i>
(9) Principle Spillway (Elevation)	<i>5491.80</i>
(10) Emergency Spillway (Elevation)	<i>5491.80</i>
(11) Existing Sediment Capacity (To Cleanout)	<i>0.22 acre feet.</i>

GENERAL	
(12) Comments/Recommendations	<i>No Discharge.</i>

STATEMENT

I hereby certify that; I am experienced in the construction of impoundments; I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved design and meets or exceeds the minimum design requirements under all applicable federal, state and local regulations; and, that inspections and inspection reports are made by myself and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability.

Dan W. Guy
(Signature)

10/28/14
(Date)



**SAVAGE SERVICES CORPORATION
2014 ANNUAL POND INSPECTION REPORT**

POND: Sediment Pond 2 **LOCATION:** Savage Coal Terminal

IMPOUNDMENTS	
(1) Stability	<i>Slopes Stable. Incised Pond</i>
(2) Structural Weakness/Erosion	<i>None Noted.</i>
(3) Potential Safety Hazards	<i>None Noted.</i>
(4) Depth of Impounded Water	<i>2.0' Water</i>
(5) Existing Storage Capacity	<i>0.64 acre feet.</i>
(6) Monitoring Procedures	<i>Quarterly Inspection.</i>

SEDIMENT PONDS ONLY	
(7) Sediment Accumulation (Elevation)	<i>5484.90</i>
(8) 60% Sediment Cleanout Level (Elevation)	<i>5485.50</i>
(9) Principle Spillway (Elevation)	<i>5492.30</i>
(10) Emergency Spillway (Elevation)	<i>5492.30</i>
(11) Existing Sediment Capacity (To Cleanout)	<i>0.09 acre feet.</i>


GENERAL	
(12) Comments/Recommendations	<i>No Discharge.</i>

STATEMENT

I hereby certify that; I am experienced in the construction of impoundments; I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved design and meets or exceeds the minimum design requirements under all applicable federal, state and local regulations; and, that inspections and inspection reports are made by myself and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability.

Dan W. Guy
(Signature)

10/28/14
(Date)



**SAVAGE SERVICES CORPORATION
2014 ANNUAL POND INSPECTION REPORT**

POND: Sediment Pond 3 **LOCATION:** Savage Coal Terminal

IMPOUNDMENTS	
(1) Stability	<i>Slopes Stable. Incised Pond</i>
(2) Structural Weakness/Erosion	<i>None Noted.</i>
(3) Potential Safety Hazards	<i>None Noted.</i>
(4) Depth of Impounded Water	<i>N/A - Dry.</i>
(5) Existing Storage Capacity	<i>0.94 acre feet.</i>
(6) Monitoring Procedures	<i>Quarterly Inspection.</i>

SEDIMENT PONDS ONLY	
(7) Sediment Accumulation (Elevation)	<i>5483.60</i>
(8) 60% Sediment Cleanout Level (Elevation)	<i>5484.80</i>
(9) Principle Spillway (Elevation)	<i>5491.40</i>
(10) Emergency Spillway (Elevation)	<i>5491.40</i>
(11) Existing Sediment Capacity (To Cleanout)	<i>0.13 acre feet.</i>

GENERAL	
(12) Comments/Recommendations	<i>No Discharge.</i>

STATEMENT

I hereby certify that; I am experienced in the construction of impoundments; I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved design and meets or exceeds the minimum design requirements under all applicable federal, state and local regulations; and, that inspections and inspection reports are made by myself and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability.

Dan W. Guy
(Signature)

10/28/14
(Date)

