0003

File

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

inspection report

Permit No. PRO/007/033

Inspection Date 11/24 & 30/87

Permittee/Operator Name Andalex Resources, Inc.

Business Address P.O. Box 902

City Price State Ut. Zip 84501

Mine Wildcat Prep. Plant ☐ Surface ☐ Underground ☒ Other

County Carbon State Ut.

Company Official(s) Mike Glasson, John Pappas.

State Official(s) Bill Malencik

Time of inspection 9:00 ☒ a.m. ☐ p.m. to 1:00 ☐ a.m. ☒ p.m. ☒ Partial ☐ Complete

Date of last inspection 10/13/87 Weather conditions Clear/Cool/Site Dry.

Acreage — ☐ Permitted 60 ☒ Disturbed — ☐ Regraded — ☐ Seeded — ☐ Bonded

Enforcement Action None/ NOV 87-26-8-2 Abated

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☐	☒	☐	☐
2. Signs and markers	☒	☐	☐	☐
3. Topsoil	☒	☐	☐	☐
4. Hydrologic balance				
— Stream channel diversions	☐	☐	☐	☐
— Diversions	☒	☐	☐	☒
— Sediment ponds and impoundments	☒	☐	☐	☒
— Other sediment control measures	☐	☐	☐	☐
— Surface and groundwater monitoring	☐	☐	☐	☐
— Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☐	☐	☐	☐
8. Noncoal waste	☐	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☐	☐	☐	☐
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
— Construction	☐	☐	☐	☐
— Drainage controls	☐	☐	☐	☐
— Surfacing	☐	☐	☐	☐
— Maintenance	☒	☐	☐	☒
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE — DOGM YELLOW — OSM PINK — PERMITTEE/OPERATOR GOLDENROD — NOV FILE

INSPECTION REPORT COMMENTS

Permit No. PRO/007/033

Inspection Date 11/24 & 30/87

Please number comments to correspond with topics on previous page.

General Comments. The inspection covered parts of two days. 11/24 was pointed at abating the NOV and 11/30 finalized the partial inspection started on 11/24.

Diversions - State NOV 87-26-8-2, 2 of 2 was issued Oct. 21, 1987 and abated 11/24/87. The required work of cleaning numerous culverts together with providing erosion protection at some inlets & outlets was completed promptly and before the deadline date of Nov. 20, 1987, 4 p.m.

While the work met the performance standards as specified in the Utah Coal Mining Regulations some additional suggestions were made to Wildcat Officials Messrs Glasson & Pappas that would perhaps reduce the maintenance frequency.

The culvert draining the loadout pad needs to have better defined drainage in order to prevent the drainage from topping the road. The road ditch may be enlarged and/or a culvert installed across the road. Either way the water would end up in Sediment Pond A.

Copy of report mailed to _____

Copy of report given to _____

Inspector's signature _____ No. _____

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. PRO/007/033

Inspection Date 11/24 & 30/87

Please number comments to correspond with topics on previous page.

Sediment Ponds NOV 87-26-8-2, 1 of 2 issued 10/21/87 was abated 11/24/87. Action taken by the Mining Co. included installing an emergency spillway on all ponds A-E; F had two spillways. inlet & outlet protection pond certification, and embankment stabilization. All the work was performed timely. Since the emergency spillway on ponds C&D cross the haul road this work was completed on Saturday a non work day.

Road Maintenance One small piping hole appears to be starting on the north side of the haul road near the exit gate and adjacent to a guard rail. This is a routine maintenance item that was discussed with John Pappas.

Copy of report mailed to Mike Glasson, ADI; Salt Lake City For: Brian Smith OSM; Joe Helfrich DOGM

Copy of report ~~given to~~ filed PFO

Inspector's signature Tom J. Malencik No. 26

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE