VRE 6-16-87 0014 LPB

UTAH NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

inspection report

Permit No. PRO/007/~~034~~ 033

Inspection Date June 12, 1987

Permittee/Operator Name Andalex Resources, Inc.

Business Address P.O Box 902

City Price State Ut Zip 84501

Mine Wildcat Loadout ☒ Surface ☐ Underground ☐ Other

County Carbon State Ut

Company Official(s) Charley Adeleye & John Pappas

State Official(s) Wm. J Malencik

Time of inspection 9:30 ☒ a.m. ☐ p.m. to 11:30 ☒ a.m. ☐ p.m. ☐ Partial ☒ Complete

Date of last inspection May 22, 1987 Weather conditions Clear/Warm

Acreage ☐ Permitted 37 ☐ Disturbed ☐ Regraded ☐ Seeded ☐ Bonded

Enforcement Action None

Other Action: Item 2, page 2 of this report.

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☒	☐	☐	☐
2. Signs and markers	☒	☐	☐	☐
3. Topsoil	☒	☐	☐	☐
4. Hydrologic balance				
a – Stream channel diversions	☒	☐	☐	☐
b – Diversions	☒	☐	☐	☐
c – Sediment ponds and impoundments	☒	☐	☐	☒
d – Other sediment control measures	☒	☐	☐	☐
e – Surface and groundwater monitoring	☒	☐	☐	☐
f – Effluent limitations	☒	☐	☐	☐
5. Explosives	☐	☐	☒	☐
6. Development waste and spoil disposal	☐	☐	☒	☐
7. Coal processing waste	☒	☐	☐	☐
8. Noncoal waste	☒	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☒	☐	☐	☐
10. Slides and other damage	☐	☐	☒	☐
11. Contemporaneous reclamation	☐	☐	☒	☐
12. Backfilling and grading	☐	☐	☒	☐
13. Revegetation	☒	☐	☐	☐
14. Subsidence control	☐	☐	☒	☐
15. Cessation of operations	☐	☐	☒	☐
16. Roads				
a – Construction	☒	☐	☐	☐
b – Drainage controls	☒	☐	☐	☐
c – Surfacing	☒	☐	☐	☒
d – Maintenance	☒	☐	☐	☐
17. Other transportation facilities	☐	☐	☒	☐
18. Support facilities and utility installations	☐	☐	☒	☐

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

LPB

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. PR0/007/034

Inspection Date June 12, 1987

Please number comments to correspond with topics on previous page.

Introduction. The loadout was operational at the time of inspection. No significant compliance problems were detected.

Followup To Previous Inspections. Maintenance work requested in the May 22, 1987 inspection report was completed May 23 the day after inspection. Further, Mike Glasson by phone in the a.m of monday, May 25 advised the undersigned all the maintenance work had been completed.

1 Permits: and other paper work at the loadout were reviewed ie., R/W Permits & Amendments, U40827, BLM; Air Quality; NPDES, UT0024147, extension at 12/4/82; Bond; Appl filed with DOGM, 11/21/85

2 Signs & Markers are in place as required under current approvals. The title signs still carry the name of "Tower". New signs discussed in previous inspection reports have not yet been received. Mr. Glasson by copy of this report is requested to notify the undersigned when the new signs will be received & erected.

4 Sediment Ponds A-E were dry, no evidence of discharge & stable.

16 Road surfacing of the interior main haulage roads had been completed since the last report and looked good.

Copy of report mailed to Mike Glasson (ADI); Donna Griffin, OSM

Copy of report given to Joe Helerich

Inspector's signature Jim Smalenik 6/12/87 No. 26

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE