12-13-88 7460

0003

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

inspection report

Permit No. PRO/007/033

Inspection Date 11/29/88

Permittee/Operator Name Andalex Resources, Inc.

Business Address P.O. Box 902

City Price State Ut Zip 84501

Mine Wildcat headout ☐ Surface ☐ Underground ☒ Other

County Carbon State Ut

Company Official(s) Mike Glasson

State Official(s) Bill Malencik

Time of inspection 9:00 ☒ a.m. ☐ p.m. to 2:00 ☐ a.m. ☒ p.m. ☒ Partial ☐ Complete

Date of last inspection 11/16/88 Weather conditions Clear/Cold.

Acreage NA ☐ Permitted 60 ☐ Disturbed NA ☐ Regraded ~~NA~~ 60 ☐ Seeded NA. ☐ Bonded

Enforcement Action None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☒	☐	☐	☒
2. Signs and markers	☒	☐	☐	☒
3. Topsoil	☐	☐	☐	☐
4. Hydrologic balance				
— Stream channel diversions	☐	☐	☐	☐
— Diversions	☒	☐	☐	☒
— Sediment ponds and impoundments	☒	☐	☐	☐
— Other sediment control measures	☒	☐	☐	☐
— Surface and groundwater monitoring	☐	☐	☐	☐
— Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☒	☐	☐	☒
8. Noncoal waste	☐	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☒	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☐	☐	☐	☐
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
— Construction	☐	☐	☐	☐
— Drainage controls	☐	☐	☐	☐
— Surfacing	☐	☐	☐	☐
— Maintenance	☒	☐	☐	☐
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE — DOGM YELLOW — OSM PINK — PERMITTEE/OPERATOR GOLDENROD — NOV FILE

UTAH NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. PRO/007/033

Inspection Date 11/29/88

Please number comments to correspond with topics on previous page.

General Comments: This partial inspection was conducted by the undersigned and accompanied by Mike Glasson.

Permit. On 11/30/88 Division personnel met with Mike Glasson and a consultant to adjudicate comments on the MRP. Most of the matters were resolved, but required followup action by the operator.

Signs & Markers: Required signs & markers were in place.

Topsoil. Comments on the topsoil mentioned in the inspection of 11/16/88 are being adjudicated as a permit approval process. The issue relates to potential coal fines that may be blown on the topsoil pile.

Diversion. The breeched berm on Beaver Creeks property has been corrected and a diversion on BC land has been changed which should prevent a future problem.

Coal Processing Waste: The coal bony pile and drainage design around the pile was another item that was adjudicated at the 11/30/88 meeting mentioned above.

Copy of report mailed to Andalex Resources Inc.
" " " " " SLC FOR: OSM/Brian Smith; DOGM/Joe Helfrich

Copy of report ~~given~~ filed to PFO

Inspector's signature [signature] No. 26

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

12/9/88