11-20-89 0003

UTAH NATURAL RESOURCES
Oil, Gas & Mining
3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

RVS

inspection report

Permit No. ACT/007/033
Inspection Date 11/2/89

Permittee/Operator Name ANDALEX RESOURCES, INC.
Business Address P.O. BOX 902
City PRICE State UTAH Zip 84501
Mine WILDCAT LOADOUT FACILITY ☐ Surface ☐ Underground ☑ Other LOADOUT
County CARBON State UTAH
Company Official(s) BERT JEANSELME
State Official(s) PAMELA GRUBAUGH-LITTIG
Time of inspection 12:30 ☐ a.m. ☑ p.m. to ___:___ ☐ a.m. ☐ p.m. ☐ Partial ☑ Complete
Date of last inspection OCT. 2, 1989 Weather conditions SUNNY and Cool
Acreage 100 ☑ Permitted 60 ☑ Disturbed ☐ Regraded ☐ Seeded 60 ☑ Bonded
Enforcement Action

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☑	☐	☐	☑
2. Signs and markers	☑	☐	☐	☐
3. Topsoil	☑	☐	☐	☑
4. Hydrologic balance				
a. Stream channel diversions	☑	☐	☐	☐
b. Diversions	☑	☐	☐	☐
c. Sediment ponds and impoundments	☑	☐	☐	☑
d. Other sediment control measures	☑	☐	☐	☐
e. Surface and groundwater monitoring	☑	☐	☐	☑
f. Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☑	☐
6. Development waste and spoil disposal	☑	☐	☐	☑
7. Coal processing waste	☑	☐	☐	☐
8. Noncoal waste	☑	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☑	☐	☐	☐
10. Slides and other damage	☐	☐	☑	☐
11. Contemporaneous reclamation	☑	☐	☐	☐
12. Backfilling and grading	☐	☐	☑	☐
13. Revegetation	☑	☐	☐	☑
14. Subsidence control	☐	☐	☑	☐
15. Cessation of operations	☐	☐	☑	☐
16. Roads				
a. Construction	☑	☐	☐	☐
b. Drainage controls	☑	☐	☐	☐
c. Surfacing	☑	☐	☐	☐
d. Maintenance	☑	☐	☐	☐
17. Other transportation facilities	☑	☐	☐	☐
18. Support facilities and utility installations	☑	☐	☐	☐

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/007/033

Inspection Date 11/2/89

Please number comments to correspond with topics on previous page.

1. A permanent program permit was issued May 5, 1989. An irrevocable letter of credit with Pittsburg National Bank (#55412-IL) in the amount of $813,795 is posted for this site. Liability insurance ~~is held~~ issued by Red Republic Insurance Company (#2Y-51875) is effective until cancelled. The BLM-ROW #U-48072, granted for 30-years became effective 1/12/82 (a $50,000 bond was posted.) Utah Railway has a 23 acre lease for operator to utilize certain railway properties. DOH approved a waste water disposal system. An Air Quality approval order was issued 7/22/82. The UPDES permit was issued for this site 6/28/89.

3. A topsoil pile by POND E is bermed and will be seeded within the next few weeks.

4c. Sedimentation pond inspections were noted for the third quarter, 1989. No problems. POND E was completed October 12, 1989.

4e. Water monitoring reports were current.

6. Waste pile inspections were noted for third

BDH ~~tested~~ 6-16-89 by BOAQ.

Copy of report mailed to Mike Gleason, Brian Smith

Copy of report given to Joe Helfrich

Inspector's signature Pamela Grubaugh-Littig No. 20

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/007/033

Inspection Date 11/2/89

Please number comments to correspond with topics on previous page.

6. quarter, 1989. No problems noted.

13. There are four revegetation plots that have been recently prepared (tilled) and mulched (straw). Seeds were tested by an official 11/1/89. The operator is awaiting results before seeding. The plots are located east of unit train, across from trailer (east), by the substation and by Pond C. All of those sites should not be redisturbed by the operation.

Copy of report mailed to Mike Glasson (Andalex), Brian Smith (OSM)

Copy of report given to Joe Helfrich (DOGM)

Inspector's signature Pamela Grubaugh-Littig No. 20

11/3/89

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

DOGM/IR-2

an equal opportunity employer

11/86 001049