0009

UTAH NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

gdh RJS

inspection report

Permit No. ACT/007/033

Inspection Date Aug. 16, 1989

Permittee/Operator Name Andalex Resources, Inc.

Business Address P.O. Box 902

City Price State UT Zip 84501

Mine Wildcat Prep. Plant ☐ Surface ☐ Underground ☒ Other

County Carbon State UT

Company Official(s) John Pappas

State Official(s) Bill Wadsack

Time of inspection 1:30 ☐ a.m. ☒ p.m. to 2:30 ☐ a.m. ☒ p.m. ☒ Partial ☐ Complete

Date of last inspection July 25, 1989 Weather conditions Partly cloudy & warm

Acreage 100 ☒ Permitted 60 ☒ Disturbed ☐ Regraded ☐ Seeded 60 ☒ Bonded

Enforcement Action None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☒	☐	☐	☒
2. Signs and markers	☒	☐	☐	☐
3. Topsoil	☒	☐	☐	☐
4. Hydrologic balance				
a Stream channel diversions	☐	☐	☐	☐
b Diversions	☒	☐	☐	☒
c Sediment ponds and impoundments	☒	☐	☐	☒
d Other sediment control measures	☒	☐	☐	☐
e Surface and groundwater monitoring	☐	☐	☐	☐
f — Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☒	☐	☐	☐
8. Noncoal waste	☒	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☐	☐	☐	☐
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
— Construction	☐	☐	☐	☐
— Drainage controls	☐	☐	☐	☐
— Surfacing	☐	☐	☐	☐
— Maintenance	☐	☐	☐	☐
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE — DOGM YELLOW — OSM PINK — PERMITTEE/OPERATOR GOLDENROD — NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/007/033

Inspection Date Aug. 16, 1989

Please number comments to correspond with topics on previous page.

GENERAL: MR. JOHN PAPPAS WAS PARTY TO THIS PARTIAL INSPECTION. SITE WAS DRY ALTHOUGH RAIN HAD OCCURRED IN THE VICINITY THE PREVIOUS DAY (8/15).

1. PERMITS: ANDALEX RESOURCES RECEIVED AN APPROVAL FROM THE DIVISION (dated 8/10/89) FOR AN AMENDMENT TO THE WILDCAT LOADOUT FACILITY PERMIT. THE APPROVAL WAS FOR A SMALL CONCRETE PAD & SHOP. APPROVAL WAS ALSO GRANTED ON FOUR STIPULATION RESPONSES (7/25/89); STIPULATION UMC 817.46-(1)-(A&L) IS TO BE COMPLETED BY AUGUST 31, 1989.

4b. DIVERSIONS: DRAINAGE DITCHES & CULVERTS HAVE BEEN CLEANED (WHERE NECESSARY) OF THE DEBRIS & SILT FROM THE JULY 29 STORM.

Copy of report mailed to

Copy of report given to

Inspector's signature WAW No.

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/007/023

Inspection Date Aug. 16, 1989

Please number comments to correspond with topics on previous page.

4c. SED PONDS: WITH THE EXCEPTION OF POND E, ALL PONDS WERE DRY. RECONSTRUCTION OF POND E IS COVERED BY PERMIT STIPULATION UMC 817.46-(1)-(PGL). MR. PAPPAS IS AWARE OF THE AUGUST 31, 1989 DEADLINE. HOWEVER, THE POND CONTAINED WATER & MAY HAVE TO BE PUMPED TO FACILITATE DRYING.

EXCAVATED MATERIAL FROM POND E HAS BEEN TEMPORARILY STOCKPILED. ULTIMATE STORAGE AND/OR HANDLING PROCEDURES WERE QUESTIONED BY MR. PAPPAS; INFORMATION WILL BE RELAYED TO THE DIVISION'S TECHNICAL STAFF.

Copy of report mailed to JOE HELFRICH (D&M), BRIAN SMITH (OSM), MIKE GIBSON (ANDALEX)

Copy of report given to PFO

Inspector's signature William A. Warnock 8/16/89 No. 30

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE