2-2-89 7144 0032

UTAH NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

inspection report

Permit No. PRO/007/033

Inspection Date 1/19/89

Permittee/Operator Name Andalex Resources, Inc.

Business Address P.O. Box 902

City Price State Ut Zip 84501

Mine Wildcat Loadout Facility ☐ Surface ☐ Underground ☒ Other

County Carbon State Ut

Company Official(s) John Pappas

State Official(s) Bill Malencik

Time of inspection 2:00 ☐ a.m. ☒ p.m. to 5:00 ☐ a.m. ☒ p.m. ☒ Partial ☐ Complete

Date of last inspection 11/29/88 Weather conditions Clear/Cold

Acreage NA ☐ Permitted 60 ☐ Disturbed NA ☐ Regraded 60 ☐ Seeded N.A ☐ Bonded

Enforcement Action

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☒	☐	☐	☒
2. Signs and markers	☒	☐	☐	☐
3. Topsoil	☐	☐	☐	☐
4. Hydrologic balance				
— Stream channel diversions	☐	☐	☐	☐
— Diversions	☐	☐	☐	☐
— Sediment ponds and impoundments	☒	☐	☐	☐
— Other sediment control measures	☒	☐	☐	☒
— Surface and groundwater monitoring	☐	☐	☐	☐
— Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☒	☐	☐	☒
8. Noncoal waste	☐	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☐	☐	☐	☐
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
— Construction	☐	☐	☐	☐
— Drainage controls	☐	☐	☐	☐
— Surfacing	☐	☐	☐	☐
— Maintenance	☒	☐	☐	☒
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE

UTAH NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. PRO/007/033

Inspection Date 1/19/89

Please number comments to correspond with topics on previous page.

Permit. The Wildcat loadout facility is not currently permitted. The operator has submitted all the documents requested by the division and the current status is that the permit review is in the final stage.

Other Sediment Control. The site is snow covered except where the snow has been bladed. New straw bales have been installed in those areas that are included as small area exemptions in the proposed permit & not reporting to a sediment pond.

Coal Processing Waste: The "bony" coal waste pile was observed in relation to the proposed permit language and discussed with the operator. This item is currently under review by the Division.

Road. The haul road into the property was plowed together with other roads in the loadout pad. Some snow had been placed and/or plowed in one area near an environmental control measure called an impoundment that the undersigned suggested be removed to another area, ie, even though this is not considered a violation.

Copy of report mailed to Andalex Resources Inc/John Pappas.
SLC For: OSM/Brian Smith; DOGM/Joe Helfrich

Copy of report ~~given to~~ filed PFO

Inspector's signature Tom J. Malencik No. 26

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE

1/20/89.