0008

UTAH NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

Gph pgl

inspection report

Permit No. Act/007/033

Inspection Date 8/22/90

Permittee/Operator Name Andalex Resources, Inc.

Business Address P.O. Box 902

City Price State UT Zip 84501

Mine Wildcat Loadout ☐ Surface ☐ Underground ☒ Other

County Carbon State UT

Company Official(s) John Pappas

State Official(s) Bill Malencik & Susan White

Time of inspection 2:00 ☐ a.m. ☒ p.m. to 4:00 ☐ a.m. ☒ p.m. ☒ Partial ☐ Complete

Date of last inspection 7/20/90 Weather conditions Fair & Warm

Acreage 100 ☑ Permitted 60 ☑ Disturbed ☐ Regraded ☐ Seeded 60 ☑ Bonded

Enforcement Action None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☐	☐	☐	☐
2. Signs and markers	☐	☐	☐	☐
3. Topsoil	☐	☐	☐	☐
4. Hydrologic balance				
a. Stream channel diversions	☐	☐	☐	☐
b. Diversions	N/A	☐	☐	N/A
c. Sediment ponds and impoundments	☑	☐	☐	☑
d. Other sediment control measures	☐	☐	☐	☐
e. Surface and groundwater monitoring	☐	☐	☐	☐
f. Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☐	☐	☐	☐
8. Noncoal waste	☐	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☒	☐	☐	☒
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☒	☐	☐	☒
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
a. Construction	☐	☐	☐	☐
b. Drainage controls	☑	☐	☐	☑
c. Surfacing	☐	☐	☐	☐
d. Maintenance	☐	☐	☐	☐
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/007/033

Inspection Date 8/22/90

Please number comments to correspond with topics on previous page.

9,13. The Wildlife mitigation area south of the facility was observed. The P-J chaining and seeding project appeared in excellent condition. Grass, forb and shrubs species had germinated on site.

4c. The sediment were clean, stable, and showed evident of water retension. All sediment markers in the ponds were in place.

16 b. All drainage off the roads were in working order. The drainage ditch below the RR tracks between the office and silo could be redefine.

4 b. The design for the impoundment for the undisturbed drainage ditch is to be submitted to the Division 8/24/90. No work has been done on the impoundment or ditch

Copy of report mailed to Mike Glasson, Andalex; Brian Smith, OSM;

Copy of report given to Joe Helfrich, [redacted] DOGM

Inspector's signature Susan White No. 35

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE