0018

UTAH NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

gph pgl



M/60

# inspection report

Permit No. ACT/007/033
Inspection Date 4/3/90

Permittee/Operator Name Andalex Resources, Inc.
Business Address P.O. Box 902
City Price State Utah Zip 84501
Mine Wildcat Loadout ☐ Surface ☐ Underground ☑ Other
County Carbon State Utah
Company Official(s) John Pappas
State Official(s) Susan J. White & PAM Grubaugh-Littig
Time of inspection 12:15 ☐ a.m. ☑ p.m. to 1:30 ☐ a.m. ☑ p.m. ☑ Partial ☐ Complete
Date of last inspection 3/14/90 Weather conditions Warm & SUNNY
Acreage 100 ☑ Permitted 60 ☑ Disturbed ☐ Regraded ☐ Seeded 60 ☑ Bonded
Enforcement Action None

## COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

| | YES | NO | N/A | COMMENTS |
|---|---|---|---|---|
| 1. Permits | ☑ | ☐ | ☐ | ☐ |
| 2. Signs and markers | ☑ | ☐ | ☐ | ☐ |
| 3. Topsoil | ☑ | ☐ | ☐ | ☑ |
| 4. Hydrologic balance | | | | |
| a. Stream channel diversions | ☐ | ☐ | ☐ | ☐ |
| b. Diversions | ☐ | ☐ | ☐ | ☐ |
| c. Sediment ponds and impoundments | ☑ | ☐ | ☐ | ☑ |
| d. Other sediment control measures | ☐ | ☐ | ☐ | ☐ |
| e. Surface and groundwater monitoring | ☐ | ☐ | ☐ | ☐ |
| f. Effluent limitations | ☐ | ☐ | ☐ | ☐ |
| 5. Explosives | ☐ | ☐ | ☐ | ☐ |
| 6. Development waste and spoil disposal | ☑ | ☐ | ☐ | ☐ |
| 7. Coal processing waste | ☑ | ☐ | ☐ | ☐ |
| 8. Noncoal waste | ☐ | ☐ | ☐ | ☐ |
| 9. Protection of fish, wildlife, and related environmental values | ☐ | ☐ | ☐ | ☐ |
| 10. Slides and other damage | ☐ | ☐ | ☐ | ☐ |
| 11. Contemporaneous reclamation | ☐ | ☐ | ☐ | ☐ |
| 12. Backfilling and grading | ☐ | ☐ | ☐ | ☐ |
| 13. Revegetation | ☑ | ☐ | ☐ | ☐ |
| 14. Subsidence control | ☐ | ☐ | ☐ | ☐ |
| 15. Cessation of operations | ☐ | ☐ | ☐ | ☐ |
| 16. Roads | | | | |
| a. Construction | ☐ | ☐ | ☐ | ☐ |
| b. Drainage controls | ☐ | ☐ | ☐ | ☐ |
| c. Surfacing | ☐ | ☐ | ☐ | ☐ |
| d. Maintenance | ☐ | ☐ | ☐ | ☐ |
| 17. Other transportation facilities | ☐ | ☐ | ☐ | ☐ |
| 18. Support facilities and utility installations | ☐ | ☐ | ☐ | ☐ |

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining



## INSPECTION REPORT COMMENTS

Permit No. ACT/007/033

Inspection Date 4/3/90

Please number comments to correspond with topics on previous page.

4c. The inlets to the sedimentation ponds have been repaired. Belting has been installed to reduce erosion where the flow enters the pond.

3. The topsoil piles were observed. Vegetation was seeded last fall. Growth of grasses were noted.

Copy of report mailed to Mike Glasson (Andalex Resources), Brian Smith (DOGM)

Copy of report given to Joe Helfrich (DOGM)

Inspector's signature Pamela Grubaugh-Littig No. 20

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE