0019

UTAH NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

inspection report

Permit No. ACT/007/033

Inspection Date 3/14/90

Permittee/Operator Name Andalex Resources, Inc.

Business Address P.O. Box 902

City Price State Ut Zip 84501

Mine Wildcat Loadout ☐ Surface ☐ Underground ☒ Other

County Carbon State

Company Official(s) John Pappas

State Official(s) Bill Malencik, Susan White

Time of inspection 9:00 ☒ a.m. ☐ p.m. to 11:00 ☒ a.m. ☐ p.m. ☒ Partial ☐ Complete

Date of last inspection 2/9/90 Weather conditions Clear/Cool

Acreage 100 ☐ Permitted 60 ☐ Disturbed ☐ Regraded ☐ Seeded 60 ☐ Bonded

Enforcement Action None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☐	☐	☐	☐
2. Signs and markers	☒	☐	☐	☒
3. Topsoil	☒	☐	☐	☐
4. Hydrologic balance				
— Stream channel diversions	☐	☐	☐	☐
— Diversions	☒	☐	☐	☒
— Sediment ponds and impoundments	☒	☐	☐	☒
— Other sediment control measures	☒	☐	☐	☐
— Surface and groundwater monitoring	☐	☐	☐	☐
— Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☒	☐	☐	☐
8. Noncoal waste	☐	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☒	☐	☐	☒
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
— Construction	☐	☐	☐	☐
— Drainage controls	☐	☐	☐	☐
— Surfacing	☐	☐	☐	☐
— Maintenance	☐	☐	☐	☐
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/007/033

Inspection Date 3/14/90

Please number comments to correspond with topics on previous page.

General Comments The purpose of this partial was two fold: (1) to check environmental control measures and (2) to have new DOGM biologist Susan White meet with Wildcat personnel and get acquainted with the loadout.

Signs & Markers I.D. Signs and disturbed markers were in place.

Diversions The operator had graded some of the ditches and provided protection on some of the ditches that required heavy maintenance in the past. In summary

- Ditch D-1 previous lined with belting has now been replaced with a half round and berned on each side.
- UD-1 has been regraded near sediment pond F, however the operator stated he planned to install a 24" half round where the ditch discharges into the ephemeral stream. This work had not yet been started.

Sediment Pond. The half round nearest the railroad tracks had a piping hole that the operator repaired on site during the inspection

Copy of report mailed to

Copy of report given to

Inspector's signature No.

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. A07/007/033

Inspection Date 3/14/90

Please number comments to correspond with topics on previous page.

Revegetation The seeding of the new topsoil pile (sed pond E) and vegetation test plots were observed. The seeding on the test plots was performed by grain drill

Copy of report mailed to { Andalex: John Pappas
SLC For OSM/ Brian Smith, DOGM/Joe Helfrich

Copy of report ~~given~~ filed to RFO

Inspector's signature [signature] No. 26

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

3/19/90.