

0004



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Norman H. Bangarter
Governor

Dee C. Hansen
Executive Director

Dianne R. Nielson, Ph.D.
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

INSPECTION REPORT

INSPECTION DATE & TIME: 12:30 to 15:00, 14 September 1992

Permittee and/or Operator's Name: Andalex Resources
 Business Address: Post Office Box 902, Price, Utah 84501
 Mine Name: Wildcat Loadout Permit Number: ACT/007/033
 Type of Mining Activity: Underground: Surface: Other: X
 County: Carbon State: Utah
 Company Official(s): John Pappas (Andalex)
 State Officials(s): Hugh Klein (DOGM)
 Federal Official(s): NA
 Partial: X Complete: Date of last Inspection: 28 Aug. 1992
 Weather Conditions: Clear and warm, approximately 20°C
 Acreage:
 Permitted: 100 Disturbed: 60 Regraded: Seeded: Bonded: 60
 Enforcement Action: None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

| | YES | NO | N/A | COMMENTS |
|--|-----|-----|-----|----------|
| 1. PERMITS | () | () | () | () |
| 2. SIGNS AND MARKERS | (X) | () | () | (X) |
| 3. TOPSOIL | (X) | () | () | (X) |
| 4. HYDROLOGIC BALANCE: | | | | |
| a. STREAM CHANNEL DIVERSIONS | () | () | () | () |
| b. DIVERSIONS | (X) | () | () | (X) |
| c. SEDIMENT PONDS AND IMPOUNDMENTS | (X) | () | () | (X) |
| d. OTHER SEDIMENT CONTROL MEASURES | () | () | () | () |
| e. SURFACE AND GROUNDWATER MONITORING | (X) | () | () | (X) |
| f. EFFLUENT LIMITATIONS | () | () | () | () |
| 5. EXPLOSIVES | () | () | () | () |
| 6. DISPOSAL OF DEVELOPMENT WASTE & SPOIL | () | () | () | () |
| 7. COAL PROCESSING WASTE | () | () | () | () |
| 8. NONCOAL WASTE | () | () | () | () |
| 9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES | () | () | () | () |
| 10. SLIDES AND OTHER DAMAGE | () | () | () | () |
| 11. CONTEMPORANEOUS RECLAMATION | () | () | () | () |
| 12. BACKFILLING AND GRADING | () | () | () | () |
| 13. REVEGETATION | () | () | () | () |
| 14. SUBSIDENCE CONTROL | () | () | () | () |
| 15. CESSATION OF OPERATIONS | () | () | () | () |
| 16. ROADS | | | | |
| a. CONSTRUCTION | () | () | () | () |
| b. DRAINAGE CONTROLS | () | () | () | () |
| c. SURFACING | () | () | () | () |
| d. MAINTENANCE | () | () | () | () |
| 17. OTHER TRANSPORTATION FACILITIES | () | () | () | () |
| 18. SUPPORT FACILITIES | | | | |
| UTILITY INSTALLATIONS | (X) | () | () | (X) |

INSPECTION REPORT

(Continuation sheet)

Page 2 of 2

Permit Number ACT/007/033

Date of Inspection 14 September 1992

(Comments are Numbered to Correspond with Topics Listed Above)

General Comments

2)

Observed perimeter markers around the west side of the permit area. The perimeter is marked by orange fence posts.

3)

Inspected the east and west side topsoil piles.

4b)

French drains and down spouts draining from the railroad tracks to the lower permit area were inspected.

4c)

Ponds A, B, C, and F were inspected and all ponds were found to be dry.

4e)

The site's rain gage was inspected.

18)

Temporary generators were observed near the substation. The generators were being utilized because UP&L is in the process of replacing power lines and power poles in the area

Copy of this Report:

Mailed to: Mike Glasson (Andalex), Brian Smith (OSM-AFO)

Given to: Joe Helfrich (DOGM), Jesse Kelley (DOGM)

Inspector's Signature & Number: W. E. K.

#40

Date: 16 September 1992