



John Pappas

inspection report

Permit No. Oct/007/033
Inspection Date April 8, 1992

Permittee/Operator Name Andalex Resources, Inc.
 Business Address P.O. Box 902
 City Price Utah State _____ Zip 84501
 Mine Wildcat headout Surface Underground Other
 County Carbon State Ut
 Company Official(s) John Pappas
 State Official(s) Bill Malencik
 Time of Inspection 8:30 a.m. p.m. to 2:00 a.m. p.m. Partial Complete
 Date of last inspection 3/9/92 Weather conditions Clear/Warm/Dry Mine Site
 Acreage 100 Permitted 60 Disturbed Regraded Seeded 60 Bonded
 Enforcement Action None

✓ Item for Mr. Glenn's consideration.

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS		YES	NO	N/A	COMMENTS
1. Permits	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	9. Protection of fish, wildlife, and related environmental values	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. Signs and markers	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	10. Slides and other damage	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Topsoil	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	11. Contemporaneous reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Hydrologic balance					12. Backfilling and grading	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
- Stream channel diversions	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	13. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
- Diversions	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	14. Subsidence control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
- Sediment ponds and impoundments	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	15. Cessation of operations	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
- Other sediment control measures	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	16. Roads				
- Surface and groundwater monitoring	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	- Construction	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
- Effluent limitations	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	- Drainage controls	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Explosives	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	- Surfacing	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Development waste and spoil disposal	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	- Maintenance	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
7. Coal processing waste	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	17. Other transportation facilities	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Noncoal waste	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	18. Support facilities and utility installations	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

INSPECTION REPORT COMMENTS

Permit No. Act 10071033

Inspection Date April 8, 1992

Please number comments to correspond with topics on previous page.

General Comments. Operator has started routine spring cleaning. Violation N92-32-1-2, 2 of 2 was terminated 3/10/92.

Drainage. The operator has submitted a revised drainage plan to include a culvert/dumpsout in connection with a bermed area near the scale house. The plan has been approved by the Division. Many of the ditches have been graded recently. Some of the others need to have the weeds removed from the ditch.

Sediment Ponds. All six ponds were dry and no problems noted.

Refuse Pile. Checked the refuse pile. The operator stated that MSHA inspected the refuse pile recently and suggested a curb height berm be installed around the perimeter of the refuse pile. The operator should be aware that should this change be installed, he must be certain the "as built"/refuse pile design is correct and approved by the Division.

Protection of Fish, Wildlife et al. Mr. Dusty junior, has three eggs under the rail belt line. Last year no owl nesting at the site had taken place. Prior to that nesting had taken place for two consecutive years.

Roads. Roads had recently been graded and were in good condition.

Copy of report mailed to ADI/Mike Glassow; OSM/Bruce Smith; DOGM/ Joe Helfrich

Copy of report given to filed PFO

Inspector's signature Jim J. Malenik No. 26

WHITE - DOGM YELLOW - OSM PINK - PERMITEE/OPERATOR GOLDENROD - NOV FILE



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Norman H. Bangarter
Governor

Dee C. Hansen
Executive Director

Dianne R. Nielson, Ph.D.
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

April 7, 1992

TO: Pamela Grubaugh-Littig, Permit Supervisor ✓
FROM: Jesse Kelley, Reclamation Engineer JK
RE: Reclamation Plan Revision, Andalex Resources, Inc., Wildcat Loadout,
ACT/007/033, Folder #3, Carbon County, Utah
92 B

Synopsis

On March 6, 1992, the Division received from Mike Glasson of Andalex the revised bonding section of the PAP. This memorandum is this writer's review of this revised material.

Analysis

The bonding section of the PAP has been revised slightly to more clearly indicate that the refuse pile is included as part of the reclamation plan. This is discussed on page 70 of the submittal and this is the only change made to the original PAP.

Recommendations

It is recommended that the submittal be approved and included in the PAP.

jbe
007033.RPR