0018

UTAH NATURAL RESOURCES
Oil, Gas & Mining
3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

pgl gh

inspection report

Permit No. ACT/007/033

Inspection Date Jan. 7, 1992

Permittee/Operator Name Andalex Resources, Inc.

Business Address P.O. Box 902

City Price State Ut Zip 84501

Mine Wildcat Loadout ☐ Surface ☐ Underground ☒ Other

County Carbon State Ut

Company Official(s) John Pappas

State Official(s) Bill Malencik

Time of inspection 9:00 ☒ a.m. ☐ p.m. to 2:__ ☐ a.m. ☒ p.m. ☒ Partial ☐ Complete

Date of last inspection 12/17/91 Weather conditions Clear/Cool/Mine Site Snow Covered

Acreage 100 ☒ Permitted 60 ☒ Disturbed ☐ Regraded ☐ Seeded 60 ☒ Bonded

Enforcement Action None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☐	☐	☐	☐
2. Signs and markers	☒	☐	☐	☒
3. Topsoil	☐	☐	☐	☐
4. Hydrologic balance				
— Stream channel diversions	☐	☐	☐	☐
— Diversions	☒	☐	☐	☒
— Sediment ponds and impoundments	☒	☐	☐	☒
— Other sediment control measures	☐	☐	☐	☐
— Surface and groundwater monitoring	☐	☐	☐	☐
— Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☒	☐	☐	☒
8. Noncoal waste	☒	☐	☐	☒
9. Protection of fish, wildlife, and related environmental values	☒	☐	☐	☒
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☐	☐	☐	☐
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
— Construction	☐	☐	☐	☐
— Drainage controls	☐	☐	☐	☐
— Surfacing	☐	☐	☐	☐
— Maintenance	☒	☐	☐	☒
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☒	☐	☐	☒

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. Act 007/033

Inspection Date 1/7/92

Please number comments to correspond with topics on previous page.

General Comments: The loadout and contiguous areas had received about 8" of snow the previous day. The loadout disturbed areas were snow covered and untouched, except for the pad areas where snow removal had been completed.

Signs & Markers: I.D. signs were observed at each point of public access from a public road. The signs contained all the required information.

Perimeter markers were in place marking the disturbed area.

Safety signs (hard hat) and road signs were observed including topsoil signs and sediment pond signs.

Diversions: All diversions were snow covered ie, ditches. The culverts were checked and no problems noted. The culverts showed no evidence of recent discharge.

Sediment Ponds: All sediment ponds were snow covered. All sig. ponds were dry.

Coal Processing Waste: Refuse pile was stable. A new lift was started as evidenced by several stacks of bony.

Non Coal Waste: The mine site was clean and no pop cans or other debris was observed along the haul roads.

Copy of report mailed to

Copy of report given to

Inspector's signature No.

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. Act 007/033

Inspection Date 1/7/92

Please number comments to correspond with topics on previous page.

Protection Of Fish, Wildlife & Environment Snow removal was conducted in a manner where all the removed snow when melted would drain into the six sediment ponds. No unsightly snow piles were observed.

Roads Roads were covered with slush and draining into the road ditches

Support Facilities: The gates, buildings, and coal loading facilities were all functional and maintained

Copy of report mailed to ADI/Mike Glasson; OSM/Brain Smith; DOGM/Joe Helfrich

Copy of report ~~given~~ filed to PFO

Inspector's signature M. J. Thalencik No. 26

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE

1/7/92

DOGM/IR-2

an equal opportunity employer

11/86 001049