

E.I.S Hydrology  
Pond Inspection Report

ACT/015/004 # 6

POND: #4

LOCATION: Mill fork

<u>ITEM</u>	<u>REMARKS</u>
(1) Potential Safety Hazards	
(2) Slope Stability	
(3) Erosion	
(4) Construction and Maintenance Performance Standards	
(5) Recommendations/Comments	<u>Lead from school #4</u> <u>microem bridge</u> <u>NOT Passable</u>

I have performed the above inspection on this pond and do hereby certify it to be a true and accurate representation of the pond at this time.

[Signature]  
Inspector

3/5/94  
Date