

0016



# State of Utah

DEPARTMENT OF NATURAL RESOURCES  
DIVISION OF OIL, GAS AND MINING

INSPECTION REPORT

Norman H. Bangertor  
Governor  
Dee C. Hansen  
Executive Director  
Dianne R. Nielson, Ph.D.  
Division Director

355 West North Temple  
3 Triad Center, Suite 350  
Salt Lake City, Utah 84180-1203  
801-538-5340

Partial: XX Complete:      Exploration       
Inspection Date/Time: May 12, 1994/08:30Am-11:30Am  
Date of Last Inspection: April 14, 1994

Mine Name: Wildcat Loadout County: Carbon Permit Number: ACT/007/033  
Permittee and/or Operator's Name: Andalex Resources, Inc.  
Business Address: P.O. Box 902, Price, Utah 84501  
Type of Mining Activity: Underground      Surface      Prep. Plant XX Other       
Officials(s): State: Stephen J. Demczak Company: John Pappas  
Federal Official(s):      Weather Conditions: Warm 60's  
Existing Acreage: Permitted- 100 Disturbed- 60 Regraded-      Seeded-      Bonded- 60  
Increased/Decreased: Permitted-      Disturbed-      Regraded-      Seeded-      Bonded-       
Status: Exploration/XXXActive/    Inactive/    Temp Cessation/    Bond Forfeiture  
Reclamation (      Phase I/      Phase II/      Final Bond Release/      Liability      Year)

### REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

#### Instructions

- Substantiate the elements on this inspection by checking the appropriate performance standard.
  - For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
  - For partial inspections check only the elements evaluated.
- Document any noncompliance situation by referencing the NDV issued at the appropriate performance standard listed below.
- Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
- Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

	EVALUATED	N/A	COMMENTS	NOV/ENF
1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE	[ ]	[ ]	[ ]	[ ]
2. SIGNS AND MARKERS	[ ]	[ ]	[ ]	[ ]
3. TOPSOIL	[XX]	[ ]	[XX]	[ ]
4. HYDROLOGIC BALANCE:				
a. DIVERSIONS	[XX]	[ ]	[XX]	[ ]
b. SEDIMENT PONDS AND IMPOUNDMENTS	[XX]	[ ]	[ ]	[ ]
c. OTHER SEDIMENT CONTROL MEASURES	[ ]	[ ]	[ ]	[ ]
d. WATER MONITORING	[ ]	[ ]	[ ]	[ ]
e. EFFLUENT LIMITATIONS	[ ]	[ ]	[ ]	[ ]
5. EXPLOSIVES	[ ]	[ ]	[ ]	[ ]
6. DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES	[ ]	[ ]	[ ]	[ ]
7. COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS	[XX]	[ ]	[ ]	[ ]
8. NONCOAL WASTE	[ ]	[ ]	[ ]	[ ]
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	[ ]	[ ]	[ ]	[ ]
10. SLIDES AND OTHER DAMAGE	[ ]	[ ]	[ ]	[ ]
11. CONTEMPORANEOUS RECLAMATION	[ ]	[ ]	[ ]	[ ]
12. BACKFILLING AND GRADING	[ ]	[ ]	[ ]	[ ]
13. REVEGETATION	[XX]	[ ]	[XX]	[ ]
14. SUBSIDENCE CONTROL	[ ]	[ ]	[ ]	[ ]
15. CESSATION OF OPERATIONS	[ ]	[ ]	[ ]	[ ]
16. ROADS:				
a. CONSTRUCTION/MAINTENANCE/SURFACING	[ ]	[ ]	[ ]	[ ]
b. DRAINAGE CONTROLS	[ ]	[ ]	[ ]	[ ]
17. OTHER TRANSPORTATION FACILITIES	[ ]	[ ]	[ ]	[ ]
18. SUPPORT FACILITIES/UTILITY INSTALLATIONS	[ ]	[ ]	[ ]	[ ]
19. AVS CHECK (4th Quarter-April, May, June) <u>    </u> date	[ ]	[ ]	[ ]	[ ]
20. AIR QUALITY PERMIT	[ ]	[ ]	[ ]	[ ]
21. BONDING & INSURANCE	[ ]	[ ]	[ ]	[ ]

INSPECTION REPORT  
(Continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/007/033

DATE OF INSPECTION: May 12, 1994

(Comments are Numbered to Correspond with Topics Listed Above)

2. Topsoil -

The topsoil pile that is located by the Preparation Plant may be moved to eliminate the coal fines that are being blown on to the pile by the wind. The topsoil piles showed no signs of erosion.

4a. Diversions -

The diversions had been re-shaped the month prior to abate a Notice Of Violation. There were no signs of breaching or sediment build-up.

13. Revegetation -

Areas where the herbicide 2-4-D has been applied, there appears (by visual inspection) to be a higher percentage of grasses in these areas. The areas where no herbicides were applied there is an abundance of native weeds and a nominal amount of grasses.

NOTE This inspection report does not constitute an affidavit of compliance with the regularoty program of the Division of Oil, Gas, and Mining.

Copy of this Report:

Mailed to: Mike Glasson (Andalex Resources)


Mailed to: Bernie Freeman (OSM)

Given to: Joe Helfrich (DOGM)

Filed to: Price Field Office

Date: June 9, 1994

Inspector's Signature and Number:

  
Stephen J. Demczak

#39