

0013



State of Utah
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

INSPECTION REPORT

Handwritten initials 'JH'

Michael O. Leavitt
Governor
Ted Stewart
Executive Director
James W. Carter
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1200
801-538-5340
801-359-3940 (Fax)
801-538-5319 (TDD)

Partial: XX Complete: ___ Exploration: ___

Inspection Date & Time: 7/14/95 - 8:00A.M.-11:00A.M.

Date of Last Inspection: 6/22/95

Mine Name: Wildcat Loadout County: Carbon Permit Number: ACT/007/033

Permittee and/or Operator's Name: Andalex Resources, Inc.

Business Address: P.O. Box 902, Price, Utah 84501

Type of Mining Activity: Underground ___ Surface ___ Prep. Plant XXX Other ___

Company Official(s): John Pappas

State Officials(s): Stephen J. Demczak Federal Official(s):

Weather Conditions: Hot 90's

Existing Acreage: Permitted- 100 Disturbed- 63.7 Regraded- Seeded- Bonded- 60

Increased/Decreased: Permitted- Disturbed- Regraded- Seeded- Bonded-

Status: Exploration/ XXX Active/ Inactive/ Temporary Cessation/ Bond Forfeiture

Reclamation (Phase I/Phase II/Final Bond Release/Liability Year)

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

Instructions

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
a. For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
b. For partial inspections check only the elements evaluated.
2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

Table with 4 columns: EVALUATED, N/A, COMMENTS, NOV/ENF. Rows include: 1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE; 2. SIGNS AND MARKERS; 3. TOPSOIL; 4. HYDROLOGIC BALANCE; 5. EXPLOSIVES; 6. DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES; 7. COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS; 8. NONCOAL WASTE; 9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES; 10. SLIDES AND OTHER DAMAGE; 11. CONTEMPORANEOUS RECLAMATION; 12. BACKFILLING AND GRADING; 13. REVEGETATION; 14. SUBSIDENCE CONTROL; 15. CESSATION OF OPERATIONS; 16. ROADS; 17. OTHER TRANSPORTATION FACILITIES; 18. SUPPORT FACILITIES/UTILITY INSTALLATIONS; 19. AVS CHECK (4th Quarter-April, May, June) (date); 20. AIR QUALITY PERMIT; 21. BONDING & INSURANCE.



INSPECTION REPORT
(Continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/007/033

DATE OF INSPECTION: 07/14/95

(Comments are Numbered to Correspond with Topics Listed Above)

3. TOPSOIL -

The new topsoil pile had been seeded. The vegetation contains mostly weeds with very little grasses. The weeds have taken over the designed vegetation.

4A. DIVERSIONS -

The diversion behind the Genwal and Andalex coal stockpile needs to be cleaned out. Coal fines have started to accumulate within the diversion. The permittee has also contracted for a consultant to evaluate the design to the diversion to eliminate this problem.

4B. SEDIMENT PONDS -

The inlet to the sediment pond behind the Genwal and Andalex stock pile needs cleaning out. Coal fines have started to accumulate within the ditch. The operator has stated the ditch will be cleaned out.

4C. OTHER SEDIMENT CONTROL MEASURES -

The straw bales were in good shape with no sign of bypassing or failure of these structures. Designs of the structures appear to be functioning.

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas, and Mining.

Copy of this Report:


Mailed to: Mike Glasson (Andalex)

Donna Griffin (OSM)

Given to: Joe Helfrich (DOGM)

Filed to: Price Field Office

Date: August 2, 1995

Inspector's Signature:  #39
Stephen J. Demczak