



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Michael O. Leavitt
Governor
Kathleen Clarke
Executive Director
Lowell P. Braxton
Division Director

1594 West North Temple, Suite 1210
PO Box 145801
Salt Lake City, Utah 84114-5801
801-538-5340
801-359-3940 (Fax)
801-538-7223 (TDD)

INSPECTION REPORT

*PGL
buy
sh*

Partial: XXX Complete: _____ Exploration: _____
Inspection Date & Time: 03/29/2001 / 1:30p.m.-3:30p.m.
Date of Last Inspection: 03/29/2001

Mine Name: Wildcat Loadout County: Carbon Permit Number:
Permittee and/or Operator's Name: Andalex Resources, Inc.
Business Address: P.O. Box 902, Price, Utah 84501
Type of Mining Activity: Underground _____ Surface _____ Prep. Plant XXX Other _____
Company Official(s): Mike Glasson
State Official(s): Bill Malencik Federal Official(s): None
Weather Conditions: Partly Cloudy, temp 40's, Dry mine site
Existing Acreage: Permitted 100 Disturbed 63.7 Regraded _____ Seeded _____
Status: Active XXX

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

- Substantiate the elements on this inspection by checking the appropriate performance standard.
 - For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
 - For partial inspections check only the elements evaluated.
- Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
- Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
- Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

	EVALUATED	N/A	COMMENTS	NOV/ENF
1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. SIGNS AND MARKERS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. TOPSOIL	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4. HYDROLOGIC BALANCE:				
a. DIVERSIONS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
b. SEDIMENT PONDS AND IMPOUNDMENTS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
c. OTHER SEDIMENT CONTROL MEASURES	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
d. WATER MONITORING	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
e. EFFLUENT LIMITATIONS	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. EXPLOSIVES	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
8. NONCOAL WASTE	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL ISSUES	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. SLIDES AND OTHER DAMAGE	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. CONTEMPORANEOUS RECLAMATION	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. BACKFILLING AND GRADING	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. REVEGETATION	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14. SUBSIDENCE CONTROL	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. CESSATION OF OPERATIONS	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16. ROADS:				
a. CONSTRUCTION/MAINTENANCE/SURFACING	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
b. DRAINAGE CONTROLS	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
17. OTHER TRANSPORTATION FACILITIES	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
18. SUPPORT FACILITIES/UTILITY INSTALLATIONS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
19. AVS CHECK (4 th Quarter- April, May, June)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
20. AIR QUALITY PERMIT	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
21. BONDING & INSURANCE	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

INSPECTION REPORT

(Continuation sheet)

PERMIT NUMBER: C/007/033

DATE OF INSPECTION: 04/24/2001

(COMMENTS ARE NUMBERED TO CORRESPOND WITH TOPICS LISTED ABOVE)

GENERAL COMMENTS

Conducted a partial inspection of the Wildcat Loadout on April 24, 2001. There are two follow-up items that were mentioned in the last inspection that were taken care of:

- 1) The diversions on the north side of the property that was mentioned in the March report all have been regraded and they meet the coal rules.
- 2) Coal on the road adjacent to sediment ponds A and B was cleaned and the operator did a good job of cleaning the road area.

2. SIGNS AND MARKERS

Identification signs were noted off the county road that interfaces with the permit boundary. All sediment ponds each have a sign marking the sediment pond. All markers were noted and no problems were detected. This meets the coal rules.

3. TOPSOIL

Topsoil piles were noted and they had no wind or water erosion. The vegetation on the topsoil pile is six inches in height and has a sparse cover. A berm provides secondary protection. This meets the coal rules.

4A. HYDROLOGIC BALANCE: DIVERSIONS

The diversions were checked. The spring clean-up has all been completed. This meets the requirements of the coal rules.

4B. HYDROLOGIC BALANCE: SEDIMENT PONDS AND IMPOUNDMENTS

Sediment ponds were dry except for ponds C and F that had a small amount of runoff. The ponds were all stable. Ponds C and F were not discharging. This meets the coal rules.

4C. HYDROLOGIC BALANCE: OTHER SEDIMENT CONTROL MEASURES

Other sediment control includes straw bales south of the property. This meets the coal rules.

INSPECTION REPORT

(Continuation sheet)

PERMIT NUMBER: C/007/033

DATE OF INSPECTION: 04/24/2001

4D. HYDROLOGIC BALANCE: WATER MONITORING

The first quarter water monitoring was reviewed for WCW-1, WCW-2, WCW-3, and WCW-4. The field book was appropriately noted. All four stations were dry. This meets the coal rules.

7. COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS

Refuse pile was inspected and no problems were noted. The berm is axle height as required by MSHA. This meets the coal rules.

16A. ROADS: CONSTRUCTION/MAINTENANCE/SURFACING

Roads were inspected and were all in good condition. The haul roads were especially in good condition and were in a good state of repair.

Inspector's Signature: 
Wm. J. Malencik #26

Date: April 26, 2001

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas & Mining.

sd
cc: James Fulton, OSM
Mike Glasson, Andalex
Price Field office
O:\007033.WCL\Compliance\2001\p_0424.wpd