

# WILDCAT LOADOUT

C/007/0033

## 2001 ANNUAL REPORT

File in:

Confidential

Shelf

Expandable

Refer to Record No. 0001 Date 03/18/2002

In C/0070033/002 Channing

For additional information



**ANDALEX**  
RESOURCES, INC.

P.O. BOX 902  
PRICE, UTAH 84501  
PHONE (435) 637-5385  
FAX (435) 637-8860

**COPY**

March 28, 2002

**RECEIVED**

APR 01 2002

DIVISION OF  
OIL, GAS AND MINING

*Incoming*  
*a/007/019*

*Copy c/007/033*

Utah Coal Program  
Utah Division of Oil, Gas and Mining  
1594 West North Temple, Suite 1210  
P.O. Box 145801  
Salt Lake City, UT 84114-5801

Attn: Lowell P. Braxton  
Director

**Re: Annual Reports, Centennial, C007/019, Wildcat Loadout, C007/033**

Dear Mr. *Lowell* Braxton:

ANDALEX herewith submits two copies each of the annual reports for the above referenced permits.

Please call if you have any questions.

Sincerely,

Michael W. Glasson  
Environmental Coordinator

File in: *C/007/033 2002 Incoming*

Refer to:

- Confidential
- Shelf
- Expandable

Date: *03/28/02* for additional information

To enter text, click in the box and type your response. If a box already contains an entry select the entry and type the replacement. You can use the **tab** key to move from one field to the next. To select a check box, click in the box or type an x.

## GENERAL INFORMATION

Permitte Name	ANDALEX Resources, Inc.
Mine Name	Wildcat Loadout
Operator Name (If other than permittee)	
Permit Expiration Date	May 4, 2004
Permit Number	C007/033
Authorized Representative Title	Michael W. Glasson, Senior Geologist
Phone Number	(435) 637-5385
Fax Number	(435) 637-8860
E-mail Address	mglasson@andalex.com
Mailing Address	P.O. Box 902, Price, UT 84501
Resident Agent	Michael W. Glasson
Resident Agent Mailing Address	P.O. Box 902, Price, UT 84501
Number of Binders Submitted	1

## IDENTIFICATION OF OTHER PERMITS

Identify other permits that are required in conjunction with mining and reclamation activities.

Permit Type	ID Number	Description	Expiration Date
MSHA Mine ID(s)	42-01864	Wildcat Loadout	N/A
MSHA Impoundment(s)	None		
NPDES/UPDES Permit(s)	UTG040007	Wildcat Wash, 001-006	12/31/02
PSD Permit(s) (Air)	DAQE-896-99	Wildcat Loadout	N/A
<b>Other</b>			

RECEIVED

APR 11 2002

DIVISION OF  
OIL, GAS AND MINING

**CERTIFIED REPORTS**

List the certified inspection reports as required by the rules and under the approved plan that must be periodically submitted to the Division. Specify whether the information is included as Appendix A to this report or currently on file with the Division.

Certified Reports:	Required		Included or on file with DOGM		Comments
	Yes	No	Included	On File	
Excess Spoil Piles	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Refuse Piles	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Impoundments	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	

**REPORTING OF OTHER TECHNICAL DATA**

List other technical data and information as required under the approved plan, which must be periodically submitted to the Division. Specify whether the information is included as Appendix B to this report or currently on file with the Division.

Technical Data:	Required		Included or on file with DOGM		Comments
	Yes	No	Included	On file	
Mineralogical	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Subsidence Monitoring	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Vegetation Monitoring	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Raptor Survey	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Soils Monitoring	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Water Monitoring	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
First quarter	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
Second quarter	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
Third quarter	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
Fourth quarter	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
Geological / Geophysical	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Engineering	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Other Data	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	

**LEGAL, FINANCIAL, COMPLIANCE AND RELATED INFORMATION**

Change in administration or corporate structure can often bring about necessary changes to information found in the mining and reclamation plan. The Division is Requesting that each permittee review and update the legal, financial, compliance and related information in the plan as part of the annual report. Provide the department of Commerce, annual Report of Officers, or other equivalent information as necessary to ensure that the information provided in the plan is current. Provide any other change as necessary





**APPENDIX A**

**Certified Reports**

Excess Spoil Piles  
Refuse Piles  
Impoundments

As required under R645-301-514

**CONTENTS**

Refuse Pile Inspection  
Impoundment Inspection


## ANDALEX RESOURCES, INC. - WILDCAT LOADOUT REFUSE PILE INSPECTION REPORT

MSHA SITE: 1211-UT-09-01864-01 QUARTER: 04/2001

ITEM	REMARKS
(1) Potential Safety Hazards	None Noted.
(2) Slope Stability	Small Slopes - Stable.
(3) Removal of Topsoil/Organics	N/A - No new removal necessary.
(4) Construction and Maintenance Performance Standards	Sign - O.K. Ditches - O.K.
(5) Recommendations/Comments	Grade and Compact when possible. M.S.H.A. ID #42-01864 Minor Dumping on NE Corner.

I have performed the above inspection on this refuse pile and do hereby certify it to be a true and accurate representation of the pile at this time.



  
(Signature)

11/20/01  
(Date)

## ANDALEX RESOURCES, INC. - WILDCAT LOADOUT REFUSE PILE INSPECTION REPORT

MSHA SITE: 1211-UT-09-01864-01 QUARTER: 02/2001

ITEM	REMARKS
(1) Potential Safety Hazards	None Noted.
(2) Slope Stability	Small Slopes - Stable.
(3) Removal of Topsoil/Organics	N/A - No new removal necessary.
(4) Construction and Maintenance Performance Standards	Sign - O.K. Ditches - O.K.
(5) Recommendations/Comments	Grade and Compact when possible. M.S.H.A. ID #42-01864 New Dumping - Rock/Refuse North end.

I have performed the above inspection on this refuse pile and do hereby certify it to be a true and accurate representation of the pile at this time.



*Dan W. Guy*

(Signature)

06/29/01

(Date)

## ANDALEX RESOURCES, INC. - WILDCAT LOADOUT REFUSE PILE INSPECTION REPORT

MSHA SITE: 1211-UT-09-01864-01 QUARTER: 01/2001

ITEM	REMARKS
(1) Potential Safety Hazards	None Noted.
(2) Slope Stability	Small Slopes - Stable.
(3) Removal of Topsoil/Organics	N/A - No new removal necessary.
(4) Construction and Maintenance Performance Standards	Sign - O.K. Ditches - O.K.
(5) Recommendations/Comments	Grade and Compact when possible. Sign - O.K. M.S.H.A. ID #42-01864 New Dumping - Rock/Refuse/Fines North end.

I have performed the above inspection on this refuse pile and do hereby certify it to be a true and accurate representation of the pile at this time.



  
(Signature)

03/22/01  
(Date)

**ANDALEX RESOURCES, INC.**  
**2001 ANNUAL POND INSPECTION REPORT**

POND: *Sed. Pond "A"*LOCATION: *Wildcat*


<b>IMPOUNDMENTS</b>	
(1) <i>Stability</i>	<i>Slopes Stable.</i>
(2) <i>Structural Weakness/Erosion</i>	<i>None Noted.</i>
(3) <i>Potential Safety Hazards</i>	<i>None Noted.</i>
(4) <i>Depth of Impounded Water</i>	<i>Dry.</i>
(5) <i>Existing Storage Capacity</i>	<i>3.228 acre feet.</i>
(6) <i>Monitoring Procedures</i>	<i>U.P.D.E.S. Quarterly Inspection.</i>

<b>SEDIMENT PONDS ONLY</b>	
(7) <i>Sediment Accumulation (Elevation)</i>	<i>6142.00</i>
(8) <i>Sediment Cleanout Level (Elevation)</i>	<i>6144.00</i>
(9) <i>Principle Spillway (Elevation)</i>	<i>6149.00</i>
(10) <i>Emergency Spillway (Elevation)</i>	<i>6150.00</i>
(11) <i>Existing Sediment Capacity (To Cleanout)</i>	<i>0.918 acre feet.</i>

<b>GENERAL</b>	
(12) <i>Comments/Recommendations</i>	<i>Pond Cleaned. No Discharge. Sign OK.</i>

**STATEMENT**

*I hereby certify that; I am experienced in the construction of impoundments; I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved design and meets or exceeds the minimum design requirements under all applicable federal, state and local regulations; and, that inspections and inspection reports are made by myself and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability.*

  
 \_\_\_\_\_  
 (Signature)

11/20/01  
 \_\_\_\_\_  
 (Date)



**ANDALEX RESOURCES, INC.  
20010 ANNUAL POND INSPECTION REPORT**

POND: *Sed. Pond "B"*LOCATION: *Wildcat*

<b>IMPOUNDMENTS</b>	
(1) <i>Stability</i>	<i>Slopes Stable.</i>
(2) <i>Structural Weakness/Erosion</i>	<i>None Noted.</i>
(3) <i>Potential Safety Hazards</i>	<i>None Noted.</i>
(4) <i>Depth of Impounded Water</i>	<i>Dry.</i>
(5) <i>Existing Storage Capacity</i>	<i>0.282 acre feet.</i>
(6) <i>Monitoring Procedures</i>	<i>U.P.D.E.S. Quarterly Inspection.</i>

<b>SEDIMENT POINTS ONLY</b>	
(7) <i>Sediment Accumulation (Elevation)</i>	<i>6133.70</i>
(8) <i>Sediment Cleanout Level (Elevation)</i>	<i>6135.00</i>
(9) <i>Principle Spillway (Elevation)</i>	<i>6138.00</i>
(10) <i>Emergency Spillway (Elevation)</i>	<i>6139.00</i>
(11) <i>Existing Sediment Capacity (To Cleanout)</i>	<i>0.070 acre feet.</i>

<b>GENERAL</b>	
(12) <i>Comments/Recommendations</i>	<i>Pond dry. No Discharge. Sign OK.</i>

**STATEMENT**

*I hereby certify that; I am experienced in the construction of impoundments; I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved design and meets or exceeds the minimum design requirements under all applicable federal, state and local regulations; and, that inspections and inspection reports are made by myself and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability.*

*Dan W. Guy*  
\_\_\_\_\_  
(Signature)

*11/20/01*  
\_\_\_\_\_  
(Date)



**ANDALEX RESOURCES, INC.**  
**2001 ANNUAL POND INSPECTION REPORT**

POND: *Sed. Pond "C"*LOCATION: *Wildcat*

<b>IMPOUNDMENTS</b>	
(1) <i>Stability</i>	<i>Slopes Stable.</i>
(2) <i>Structural Weakness/Erosion</i>	<i>None Noted.</i>
(3) <i>Potential Safety Hazards</i>	<i>None Noted.</i>
(4) <i>Depth of Impounded Water</i>	<i>Dry.</i>
(5) <i>Existing Storage Capacity</i>	<i>3.837 acre feet.</i>
(6) <i>Monitoring Procedures</i>	<i>U.P.D.E.S. Quarterly Inspection.</i>

<b>SPILLWAYS</b>	
(7) <i>Sediment Accumulation (Elevation)</i>	<i>6131.13</i>
(8) <i>Sediment Cleanout Level (Elevation)</i>	<i>6131.50</i>
(9) <i>Principle Spillway (Elevation)</i>	<i>6137.00</i>
(10) <i>Emergency Spillway (Elevation)</i>	<i>6138.00</i>
(11) <i>Existing Sediment Capacity (To Cleanout)</i>	<i>0.033 acre feet.</i>

<b>DISCHARGE</b>	
(12) <i>Comments/Recommendations</i>	<i>No Discharge. Sign OK.</i>

**STATEMENT**

*I hereby certify that; I am experienced in the construction of impoundments; I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved design and meets or exceeds the minimum design requirements under all applicable federal, state and local regulations; and, that inspections and inspection reports are made by myself and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability.*

  
 (Signature)

11/20/01  
 (Date)



**ANDALEX RESOURCES, INC.  
2001 ANNUAL POND INSPECTION REPORT**

POND: Sed. Pond "D"LOCATION: Wildcat


<b>IMPOUNDMENTS</b>	
(1) Stability	Slopes Stable.
(2) Structural Weakness/Erosion	None Noted.
(3) Potential Safety Hazards	None Noted.
(4) Depth of Impounded Water	Dry.
(5) Existing Storage Capacity	0.508 acre feet.
(6) Monitoring Procedures	U.P.D.E.S. Quarterly Inspection.

<b>SEDIMENT PONDS ONLY</b>	
(7) Sediment Accumulation (Elevation)	6135.75
(8) Sediment Cleanout Level (Elevation)	6136.00
(9) Principle Spillway (Elevation)	6139.00
(10) Emergency Spillway (Elevation)	6140.00
(11) Existing Sediment Capacity (To Cleanout)	0.015 acre feet.

<b>GENERAL</b>	
(12) Comments/Recommendations	No Discharge. Sign OK.

**STATEMENT**

*I hereby certify that; I am experienced in the construction of impoundments; I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved design and meets or exceeds the minimum design requirements under all applicable federal, state and local regulations; and, that inspections and inspection reports are made by myself and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability.*

  
\_\_\_\_\_  
(Signature)

11/20/01  
\_\_\_\_\_  
(Date)



**ANDALEX RESOURCES, INC.  
2001 ANNUAL POND INSPECTION REPORT**

POND: *Sed. Pond "E"*LOCATION: *Wildcat*


<b>IMPOUNDMENTS</b>	
(1) <i>Stability</i>	<i>Slopes Stable.</i>
(2) <i>Structural Weakness/Erosion</i>	<i>None Noted.</i>
(3) <i>Potential Safety Hazards</i>	<i>None Noted.</i>
(4) <i>Depth of Impounded Water</i>	<i>N/A - Dry.</i>
(5) <i>Existing Storage Capacity</i>	<i>1.160 acre feet.</i>
(6) <i>Monitoring Procedures</i>	<i>U.P.D.E.S. Quarterly Inspection.</i>

<b>SEDIMENT PONDS ONLY</b>	
(7) <i>Sediment Accumulation (Elevation)</i>	<i>6141.90</i>
(8) <i>Sediment Cleanout Level (Elevation)</i>	<i>6142.50</i>
(9) <i>Principle Spillway (Elevation)</i>	<i>6145.00</i>
(10) <i>Emergency Spillway (Elevation)</i>	<i>6146.00</i>
(11) <i>Existing Sediment Capacity (To Cleanout)</i>	<i>0.052 acre feet.</i>

<b>GENERAL</b>	
(12) <i>Comments/Recommendations</i>	<i>No Discharge. Sign OK.</i>

**STATEMENT**

*I hereby certify that; I am experienced in the construction of impoundments; I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved design and meets or exceeds the minimum design requirements under all applicable federal, state and local regulations; and, that inspections and inspection reports are made by myself and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability.*

  
\_\_\_\_\_  
(Signature)

11/20/01  
(Date)



**ANDALEX RESOURCES, INC.  
2001 ANNUAL POND INSPECTION REPORT**

POND: Sed. Pond "F"LOCATION: Wildcat

<b>IMPOUNDMENTS</b>	
(1) Stability	Slopes Stable.
(2) Structural Weakness/Erosion	None Noted.
(3) Potential Safety Hazards	None Noted.
(4) Depth of Impounded Water	Dry.
(5) Existing Storage Capacity	0.984 acre feet.
(6) Monitoring Procedures	U.P.D.E.S. Quarterly Inspection.

<b>RECOMMENDATIONS (POND ONLY)</b>	
(7) Sediment Accumulation (Elevation)	6166.58
(8) Sediment Cleanout Level (Elevation)	6168.75
(9) Principle Spillway (Elevation)	6173.00
(10) Emergency Spillway (Elevation)	6174.00
(11) Existing Sediment Capacity (To Cleanout)	0.087 acre feet.

<b>GENERAL</b>	
(12) Comments/Recommendations	No Discharge. Pond Cleaned. Sign OK.

**STATEMENT**

*I hereby certify that; I am experienced in the construction of impoundments; I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved design and meets or exceeds the minimum design requirements under all applicable federal, state and local regulations; and, that inspections and inspection reports are made by myself and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability.*

  
\_\_\_\_\_  
(Signature)

11/20/01  
\_\_\_\_\_  
(Date)



**ANDALEX RESOURCES, INC.  
2001 ANNUAL POND INSPECTION REPORT**

**POND:** *Permanent Impoundment*      **LOCATION:** *Wildcat*


<b>IMPOUNDMENTS</b>	
(1) <i>Stability</i>	<i>Slopes Stable.</i>
(2) <i>Structural Weakness/Erosion</i>	<i>None Noted.</i>
(3) <i>Potential Safety Hazards</i>	<i>None Noted.</i>
(4) <i>Depth of Impounded Water</i>	<i>N/A - Dry.</i>
(5) <i>Existing Storage Capacity</i>	<i>0.370 acre feet. (Upper) 0.530 acre feet. (Lower)</i>
(6) <i>Monitoring Procedures</i>	<i>Quarterly Inspection.</i>

<b>SEDIMENT PONDS ONLY</b>	
(7) <i>Sediment Accumulation (Elevation)</i>	<i>N/A</i>
(8) <i>Sediment Cleanout Level (Elevation)</i>	<i>N/A</i>
(9) <i>Principle Spillway (Elevation)</i>	<i>N/A</i>
(10) <i>Emergency Spillway (Elevation)</i>	<i>N/A</i>
(11) <i>Existing Sediment Capacity (To Cleanout)</i>	<i>N/A</i>

<b>GENERAL</b>	
(12) <i>Comments/Recommendations</i>	<i>Reconstructed in 10/91. Permanent Impoundment. No Discharge.</i>

**STATEMENT**

*I hereby certify that; I am experienced in the construction of impoundments; I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved design and meets or exceeds the minimum design requirements under all applicable federal, state and local regulations; and, that inspections and inspection reports are made by myself and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability.*

  
\_\_\_\_\_  
(Signature)

11/20/01  
(Date)



**ANDALEX RESOURCES, INC.**  
**2001 ANNUAL POND INSPECTION REPORT**

POND: *Depression Area*LOCATION: *Wildcat*


<b>IMPOUNDMENTS</b>	
(1) <i>Stability</i>	<i>Railroad Slopes Stable.</i>
(2) <i>Structural Weakness/Erosion</i>	<i>None Noted.</i>
(3) <i>Potential Safety Hazards</i>	<i>None Noted.</i>
(4) <i>Depth of Impounded Water</i>	<i>Dry.</i>
(5) <i>Existing Storage Capacity</i>	<i>N/A - Some coal in area.</i>
(6) <i>Monitoring Procedures</i>	<i>Monitor for water depth for pumping.</i>

<b>SEDIMENT POND ONLY</b>	
(7) <i>Sediment Accumulation (Elevation)</i>	<i>N/A</i>
(8) <i>Sediment Cleanout Level (Elevation)</i>	<i>N/A</i>
(9) <i>Principle Spillway (Elevation)</i>	<i>N/A</i>
(10) <i>Emergency Spillway (Elevation)</i>	<i>N/A</i>
(11) <i>Existing Sediment Capacity (To Cleanout)</i>	<i>N/A</i>

<b>GENERAL</b>	
(12) <i>Comments/Recommendations</i>	<i>Depression area next to railroad. Coal stockpile.</i>

**STATEMENT**

*I hereby certify that; I am experienced in the construction of impoundments; I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved design and meets or exceeds the minimum design requirements under all applicable federal, state and local regulations; and, that inspections and inspection reports are made by myself and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability.*

  
 \_\_\_\_\_  
 (Signature)

11/20/01  
 \_\_\_\_\_  
 (Date)



**APPENDIX B**

**Reporting of Technical Data**

Including monitoring data, reports, maps, and other information  
As required under the approved plan or as required by the Division

In accordance with the requirement of R645-310-130 and R645-301-140

**CONTENTS**

NONE

**APPENDIX C**


**Legal Financial, Compliance and Related Information**

Annual Report of Officers  
As submitted to the Utah Department of Commerce

Other change in ownership and control information  
As required under R645-301-110

**CONTENTS**

Department of Commerce, Annual Report of Officers



**Utah Department of Commerce**

Name	Type	City	Status
ANDALEX RESOURCES, INC.	Corporation	SANDY UT	Active

**Principal Information**

Position	Name	Address	City	State
Director	DOUGLAS H SMITH	45 W 10000 S STE 401	SANDY	UT 84070
Director	PETER B GREEN	45 W 10000 S STE 401	SANDY	UT 84070
Director	RONALD C BEEDIE	45 W 10000 S STE 401	SANDY	UT 84070
President	DOUGLAS H SMITH	45 W 10000 S STE 401	SANDY	UT 84070
Registered Agent	JOHN S KIRKHAM	201 S MAIN ST STE 1100	SALT LAKE CITY	UT 84111
Secretary	JOHN BRADSHAW	45 W 10000S STE 401	SANDY	UT 84070
Vice President	SAMUEL C QUIGLEY	45 W 10000S STE 401	SANDY	UT 84070

Additional Principals on file at Division of Corporations:  
N

|

[Department of Commerce Home](#) | 
 [Division of Corporations Home](#) | 
 [Contact Us](#)  
[Utah.gov Home](#) | 
 [Utah.gov Terms of Use](#) | 
 [Utah.gov Privacy Policy](#) | 
 [Utah.gov Accessibility Policy](#)  
 Copyright © 2001 State of Utah - All rights reserved.

**APPENDIX D**

**Mine Maps**

As required under R645-302-525-270

**CONTENTS**

NONE

**APPENDIX E**

**Other Information**

In accordance with the requirements of R645-301 and R645-302

**CONTENTS**

NONE