

2002 ANNUAL REPORT

**ANDALEX RESOURCES, INC.
WILDCAT LOADOUT
C/007/033**

File in:

- Confidential
- Shelf
- Expandable

Refer to Record No 0002 Date 03/31/2003

In C/ 0070033 2003 Submitting

For additional information

RECEIVED

APR 24 2003

DIV. OF OIL, GAS & MINING

GENERAL INFORMATION

1. Permit Number	C/007/033
2. Mine Name	Wildcat Loadout
3. Permittee Name	Andalex Resources, Inc
4. Operator Name (if other than Permittee)	
5. Permit Expiration Date	
6. Permit Number	C/007/033
7. Company Representative, Title	Michael W. Glasson, Senior Geologist
8. Phone Number	(435) 637-5385
9. Fax Number	(435) 637-8860
10. E-mail Address	
11. Mailing Address	Andalex Resources, Inc. P.O. Box 902 Price, Utah 84501
12. Resident Agent, Title	Michael W. Glasson
13. Mailing Address	Andalex Resources, Inc. P.O. Box 902 Price, Utah 84501
14. Number of Binders Submitted	(2) 1- Salt Lake Office and 1- Price Field Office

IDENTIFICATION OF OTHER PERMITS

Identify other permits which are required in conjunction with mining and reclamation activities.

Permit Type	ID Number	Description	Expires on
1. MSHA Mine ID(s)	42-01864	Wildcat	N/A
2. MSHA Impoundment(s)	N/A		

2002 ANNUAL REPORT		Wildcat Loadout	C/007/033	Page 2
3. NPDES/UPDES Permit(s) (water)	UTG-040007	UPDES Permit		04/30/08
4. PSD (Air) Permit(s)	DAQE-013-03	Wildcat Loadout		N/A
5. Other: MSHA - Refuse Pile	1211-UT-09-01864-01	Refuse Pile		N/A
6.				

CERTIFIED REPORTS

List the certified inspection reports as required by the rules and under the approved plan which must be periodically submitted to the Division. Specify whether the information is included as APPENDIX A to this Annual Report or currently ON FILE with the Division.

Certified Reports:	Reports Required?		INCLUDED or ON FILE w/DOGM?		Comments
	YES	NO	Included	ON FILE	
1. Excess Spoil Piles		X			
2. Refuse Piles	X		X		Appendix A
3. Impoundments	X		X		Appendix A
4.					
5.					

REPORTING OF OTHER TECHNICAL DATA

List other technical data and information as required under the approved plan which must be periodically submitted to the Division. Specify whether the information is included as APPENDIX B to this Annual Report or currently ON FILE with the Division.

Technical Data:	Reports Required?		INCLUDED or ON FILE w/DOGM?		Comments
	YES	NO	Included	ON FILE	
1. Climatological Data		X			
2. Subsidence Monitoring Data		X			
3. Vegetation Monitoring Data		X			
4. Raptor Survey		X			
5. Soils Monitoring Data		X			
6. Water Monitoring Data	X			X	
First Quarter Report	X			X	

2002 ANNUAL REPORT		Wildcat Loadout		C/007/033	Page 3
Second Quarter Report	X			X	
Third Quarter Report	X			X	
Fourth Quarter Report	X			X	
7. Geological/Geophysical Data		X			
8. Engineering Data		X			
9. Other Data	N/A				
10. Non Coal Waste/Abandoned Underground Equipment					

LEGAL, FINANCIAL, COMPLIANCE AND RELATED INFORMATION

Changes in administration or corporate structure can often bring about necessary changes to information found in the mining and reclamation plan. The Division is requesting that each permittee review and update the legal, financial, compliance and related information in the plan as part of the Annual Report. Provide the Department of Commerce, Annual Report of Officers, or other equivalent information as necessary to ensure that the information provided in the plan is current. Provide any other changes as necessary regarding land ownership, lease acquisitions, legal results from appeals of violations, or other changes as necessary to update information required in the mining and reclamation plan. Include any certified financial statements, audits or worksheets which may be required to meet bonding requirements. Specify whether the information is currently ON FILE with the Division or included as APPENDIX C to this Annual Report.

Legal/Financial Data:	Report Required?		INCLUDED or ON FILE w/DOGM?		Comments
	YES	NO	Included	ON FILE	
1. Department of Commerce, Annual Report of Officers	X		X		Appendix C
2. Other					

MINE MAPS

Copies of mine maps, current and up-to-date through at least December 31, 1998, are to be provided to the Division as APPENDIX D to this Annual Report in accordance with the requirements of R645-301-525.270. These map copies shall be made in accordance with 30 CFR 75.1200, as required by MSHA. Upon request, mine maps shall be kept confidential by the Division.

Map Number(s)	Map Title / Description	Confidential?
N/A		

APPENDIX A

Certified Reports

Excess Spoil Piles
Refuse Piles
Impoundments

as required under R645-301-514

CONTENTS

Refuse Pile Inspections and Annual Impoundment Inspections

**ANDALEX RESOURCES, INC. - WILDCAT LOADOUT
REFUSE PILE INSPECTION REPORT**

MSHA SITE: 1211-UT-09-01864-01 QUARTER: 04/2002

ITEM	REMARKS
(1) Potential Safety Hazards	None Noted.
(2) Slope Stability	Small Slopes - Stable.
(3) Removal of Topsoil/Organics	N/A - No new removal necessary.
(4) Construction and Maintenance Performance Standards	Sign - O.K. Ditches - O.K.
(5) Recommendations/Comments	Some new dumping on west side. M.S.H.A. ID #42-01864 Mostly graded.

I have performed the above inspection on this refuse pile and do hereby certify it to be a true and accurate representation of the pile at this time.



Dan W. Cuy
(Signature)

11/12/02
(Date)

**ANDALEX RESOURCES, INC. - WILDCAT LOADOUT
REFUSE PILE INSPECTION REPORT**

MSHA SITE: 1211-UT-09-01864-01

QUARTER: 03/2002

ITEM	REMARKS
(1) Potential Safety Hazards	None Noted.
(2) Slope Stability	Small Slopes - Stable.
(3) Removal of Topsoil/Organics	N/A - No new removal necessary.
(4) Construction and Maintenance Performance Standards	Sign - O.K. Ditches - O.K.
(5) Recommendations/Comments	Some new dumping on west side. M.S.H.A. ID #42-01864 Mostly graded.

I have performed the above inspection on this refuse pile and do hereby certify it to be a true and accurate representation of the pile at this time.



Dan W. Guy

(Signature)

09/25/02

(Date)


**ANDALEX RESOURCES, INC. - WILDCAT LOADOUT
REFUSE PILE INSPECTION REPORT**

MSHA SITE: 1211-UT-09-01864-01 QUARTER: 02/2002

ITEM	REMARKS
(1) Potential Safety Hazards	None Noted.
(2) Slope Stability	Small Slopes - Stable.
(3) Removal of Topsoil/Organics	N/A - No new removal necessary.
(4) Construction and Maintenance Performance Standards	Sign - O.K. Ditches - O.K.
(5) Recommendations/Comments	Graded. M.S.H.A. ID #42-01864

I have performed the above inspection on this refuse pile and do hereby certify it to be a true and accurate representation of the pile at this time.





 (Signature)

 06/28/02
 (Date)

**ANDALEX RESOURCES, INC. - WILDCAT LOADOUT
REFUSE PILE INSPECTION REPORT**

MSHA SITE: 1211-UT-09-01864-01 QUARTER: 01/2002

ITEM	REMARKS
(1) Potential Safety Hazards	None Noted.
(2) Slope Stability	Small Slopes - Stable.
(3) Removal of Topsoil/Organics	N/A - No new removal necessary.
(4) Construction and Maintenance Performance Standards	Sign - O.K. Ditches - O.K.
(5) Recommendations/Comments	Grade and Compact when possible. M.S.H.A. ID #42-01864 Some New Dumping on East Side.

I have performed the above inspection on this refuse pile and do hereby certify it to be a true and accurate representation of the pile at this time.



Dan W. Guy
(Signature)

03/25/02
(Date)

ANDALEX RESOURCES, INC.
2002 ANNUAL POND INSPECTION REPORT

POND: Sed. Pond "A"

LOCATION: Wildcat

IMPOUNDMENT	
(1) Stability	Slopes Stable.
(2) Structural Weakness/Erosion	None Noted.
(3) Potential Safety Hazards	None Noted.
(4) Depth of Impounded Water	Damp.
(5) Existing Storage Capacity	3.228 acre feet.
(6) Monitoring Procedures	U.P.D.E.S. Quarterly Inspection.

SEDIMENT POND ONLY	
(7) Sediment Accumulation (Elevation)	6142.00
(8) Sediment Cleanout Level (Elevation)	6144.00
(9) Principle Spillway (Elevation)	6149.00
(10) Emergency Spillway (Elevation)	6150.00
(11) Existing Sediment Capacity (To Cleanout)	0.918 acre feet.

DISCHARGE	
(12) Comments/Recommendations	No Discharge. Sign OK.

STATEMENT

I hereby certify that; I am experienced in the construction of impoundments; I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved design and meets or exceeds the minimum design requirements under all applicable federal, state and local regulations; and, that inspections and inspection reports are made by myself and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability.



 (Signature)

11/12/02

 (Date)



Inserted 5/19/03 PWH
RECEIVED

ANDALEX RESOURCES, INC.
2002 ANNUAL POND INSPECTION REPORT

MAY - 7 2003
OGM PRICE FIELD OFFICE

POND: Sed. Pond "B" LOCATION: Wildcat


IMPOUNDMENTS	
(1) Stability	Slopes Stable.
(2) Structural Weakness/Erosion	None Noted.
(3) Potential Safety Hazards	None Noted.
(4) Depth of Impounded Water	Damp.
(5) Existing Storage Capacity	0.252 acre feet.
(6) Monitoring Procedures	U.P.D.E.S. Quarterly Inspection.

SEDIMENT PONDS ONLY	
(7) Sediment Accumulation (Elevation)	6134.25
(8) Sediment Cleanout Level (Elevation)	6135.00
(9) Principle Spillway (Elevation)	6138.00
(10) Emergency Spillway (Elevation)	6139.00
(11) Existing Sediment Capacity (To Cleanout)	0.040 acre feet.

GENERAL	
(12) Comments/Recommendations	Pond Damp. No Discharge. Sign OK.

STATEMENT

I hereby certify that; I am experienced in the construction of impoundments; I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved design and meets or exceeds the minimum design requirements under all applicable federal, state and local regulations; and, that inspections and inspection reports are made by myself and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability.


(Signature)

11/12/02
(Date)



Inserted 5/19/03 PHH

ANDALEX RESOURCES, INC.
2002 ANNUAL POND INSPECTION REPORT

POND: Sed. Pond "C"

LOCATION: Wildcat

IMPOUNDMENTS	
(1) Stability	Slopes Stable.
(2) Structural Weakness/Erosion	None Noted.
(3) Potential Safety Hazards	None Noted.
(4) Depth of Impounded Water	Damp.
(5) Existing Storage Capacity	3.826 acre feet.
(6) Monitoring Procedures	U.P.D.E.S. Quarterly Inspection.

SEDIMENT PARAMETERS	
(7) Sediment Accumulation (Elevation)	6131.25
(8) Sediment Cleanout Level (Elevation)	6131.50
(9) Principle Spillway (Elevation)	6137.00
(10) Emergency Spillway (Elevation)	6138.00
(11) Existing Sediment Capacity (To Cleanout)	0.022 acre feet.

GENERAL	
(12) Comments/Recommendations	No Discharge. Sign OK.

STATEMENT

I hereby certify that; I am experienced in the construction of impoundments; I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved design and meets or exceeds the minimum design requirements under all applicable federal, state and local regulations; and, that inspections and inspection reports are made by myself and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability.


(Signature)

11/12/02
(Date)



MAY - 7 2003

OGM PRICE FIELD OFFICE

ANDALEX RESOURCES, INC.
2002 ANNUAL POND INSPECTION REPORT

POND: Sed. Pond "D"

LOCATION: Wildcat


IMPOUNDMENTS	
(1) Stability	Slopes Stable.
(2) Structural Weakness/Erosion	None Noted.
(3) Potential Safety Hazards	None Noted.
(4) Depth of Impounded Water	6"
(5) Existing Storage Capacity	0.456 acre feet.
(6) Monitoring Procedures	U.P.D.E.S. Quarterly Inspection.

SEDIMENT PONDS ONLY	
(7) Sediment Accumulation (Elevation)	6135.58
(8) Sediment Cleanout Level (Elevation)	6136.00
(9) Principle Spillway (Elevation)	6139.00
(10) Emergency Spillway (Elevation)	6140.00
(11) Existing Sediment Capacity (To Cleanout)	0.025 acre feet.

GENERAL	
(12) Comments/Recommendations	No Discharge. Sign OK.

STATEMENT

I hereby certify that; I am experienced in the construction of impoundments; I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved design and meets or exceeds the minimum design requirements under all applicable federal, state and local regulations; and, that inspections and inspection reports are made by myself and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability.



 (Signature)

11/12/02

 (Date)



ANDALEX RESOURCES, INC.
2002 ANNUAL POND INSPECTION REPORT

POND: Sed. Pond "E"

LOCATION: Wildcat


IMPOUNDMENTS	
(1) <i>Stability</i>	<i>Slopes Stable.</i>
(2) <i>Structural Weakness/Erosion</i>	<i>None Noted.</i>
(3) <i>Potential Safety Hazards</i>	<i>None Noted.</i>
(4) <i>Depth of Impounded Water</i>	<i>3"</i>
(5) <i>Existing Storage Capacity</i>	<i>1.044 acre feet.</i>
(6) <i>Monitoring Procedures</i>	<i>U.P.D.E.S. Quarterly Inspection.</i>

SEDIMENT POND ONLY	
(7) <i>Sediment Accumulation (Elevation)</i>	<i>6141.96</i>
(8) <i>Sediment Cleanout Level (Elevation)</i>	<i>6142.50</i>
(9) <i>Principle Spillway (Elevation)</i>	<i>6145.00</i>
(10) <i>Emergency Spillway (Elevation)</i>	<i>6146.00</i>
(11) <i>Existing Sediment Capacity (To Cleanout)</i>	<i>0.047 acre feet.</i>

GENERAL	
(12) <i>Comments/Recommendations</i>	<i>No Discharge. Sign OK.</i>

STATEMENT

I hereby certify that; I am experienced in the construction of impoundments; I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved design and meets or exceeds the minimum design requirements under all applicable federal, state and local regulations; and, that inspections and inspection reports are made by myself and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability.



 (Signature)

11/12/02

 (Date)



ANDALEX RESOURCES, INC.
2002 ANNUAL POND INSPECTION REPORT

POND: Sed. Pond "F"

LOCATION: Wildcat

IMPOUNDMENTS	
(1) <i>Stability</i>	<i>Slopes Stable.</i>
(2) <i>Structural Weakness/Erosion</i>	<i>None Noted.</i>
(3) <i>Potential Safety Hazards</i>	<i>None Noted.</i>
(4) <i>Depth of Impounded Water</i>	<i>18"</i>
(5) <i>Existing Storage Capacity</i>	<i>0.699 acre feet.</i>
(6) <i>Monitoring Procedures</i>	<i>U.P.D.E.S. Quarterly Inspection.</i>

SEDIMENT POND ONLY	
(7) <i>Sediment Accumulation (Elevation)</i>	<i>6166.88</i>
(8) <i>Sediment Cleanout Level (Elevation)</i>	<i>6168.75</i>
(9) <i>Principle Spillway (Elevation)</i>	<i>6173.00</i>
(10) <i>Emergency Spillway (Elevation)</i>	<i>6174.00</i>
(11) <i>Existing Sediment Capacity (To Cleanout)</i>	<i>0.075 acre feet.</i>

COMMENTS	
(12) <i>Comments/Recommendations</i>	<i>No Discharge. Pond Cleaned. Sign OK.</i>

STATEMENT

I hereby certify that; I am experienced in the construction of impoundments; I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved design and meets or exceeds the minimum design requirements under all applicable federal, state and local regulations; and, that inspections and inspection reports are made by myself and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability.



 (Signature)

 11/12/02
 (Date)



ANDALEX RESOURCES, INC.
2002 ANNUAL POND INSPECTION REPORT

POND: Permanent Impoundment **LOCATION:** Wildcat

IMPOUNDMENTS	
(1) Stability	Slopes Stable.
(2) Structural Weakness/Erosion	None Noted.
(3) Potential Safety Hazards	None Noted.
(4) Depth of Impounded Water	N/A - Dry.
(5) Existing Storage Capacity	0.370 acre feet. (Upper) 0.530 acre feet. (Lower)
(6) Monitoring Procedures	Quarterly Inspection.

SEDIMENT POND(S) ONLY	
(7) Sediment Accumulation (Elevation)	N/A
(8) Sediment Cleanout Level (Elevation)	N/A
(9) Principle Spillway (Elevation)	N/A
(10) Emergency Spillway (Elevation)	N/A
(11) Existing Sediment Capacity (To Cleanout)	N/A

GENERAL	
(12) Comments/Recommendations	Reconstructed in 10/91. Permanent Impoundment. No Discharge.

STATEMENT

I hereby certify that; I am experienced in the construction of impoundments; I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved design and meets or exceeds the minimum design requirements under all applicable federal, state and local regulations; and, that inspections and inspection reports are made by myself and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability.



 (Signature)

11/12/02

 (Date)



ANDALEX RESOURCES, INC.
2002 ANNUAL POND INSPECTION REPORT

POND: Depression Area

LOCATION: Wildcat

IMPOUNDMENTS	
(1) Stability	Railroad Slopes Stable.
(2) Structural Weakness/Erosion	None Noted.
(3) Potential Safety Hazards	None Noted.
(4) Depth of Impounded Water	6"
(5) Existing Storage Capacity	N/A - Some coal in area.
(6) Monitoring Procedures	Monitor for water depth for pumping.

SEDIMENT POND ONLY	
(7) Sediment Accumulation (Elevation)	N/A
(8) Sediment Cleanout Level (Elevation)	N/A
(9) Principle Spillway (Elevation)	N/A
(10) Emergency Spillway (Elevation)	N/A
(11) Existing Sediment Capacity (To Cleanout)	N/A

(12) Comments/Recommendations	Depression area next to railroad. Coal stockpile.
-------------------------------	--

STATEMENT

I hereby certify that; I am experienced in the construction of impoundments; I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved design and meets or exceeds the minimum design requirements under all applicable federal, state and local regulations; and, that inspections and inspection reports are made by myself and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability.



 (Signature)

11/12/02

 (Date)



APPENDIX B

Reporting of Technical Data

including monitoring data, reports, maps, and other information
as required under the approved plan
or as required by the Division

in accordance with the requirements of R645-301-130 and R645-301-140.

CONTENTS

N/A

APPENDIX C

Legal, Financial, Compliance and Related Information


Annual Report of Officers

as submitted to the Utah Department of Commerce

and other changes in ownership and control information
as required under R645-301-110.

CONTENTS

Included



State Online Services

Agency List

Search Utah.gov

go


**Utah Department of
Commerce**

Name	Type	City	Status
ANDALEX RESOURCES, INC.	Corporation	SANDY UT	Active

Business Name: ANDALEX RESOURCES, INC.**Entity Number:** 713546-0143**Registration Date:** 3/1/1979**State of Origin:** DE**Address**

45 W 10000 S STE 401

SANDY UT 84070

Status**Status:** Active**Status Description:** Annual Report**This Status Date:** 3/2/2002**Last Renewed:** 1/10/2003**License Type:** Corporation - Foreign - Profit**Delinquent Date:** 3/1/2004

(Note: If your renewal is not received within 60 days of delinquency date your filing will expire.)

Registered Agent**Registered Agent:** JOHN S KIRKHAM**Address Line 1:** 201 S MAIN ST STE 1100**Address Line 2:****City:** SALT LAKE CITY**State:** UT**Zip:** 84111**Additional Information****NAICS Title:** 3111-Tobacco Manufacturing**Stock Class 1 Amount:** 0000002000**Stock Class 1 Type:** COMMON**Stock Class 2 Amount:** 0000000000