

INSPECTION REPORT

Partial XXX Complete Exploration
 Inspection Date: 04/09/2003 / Time: 12-2 PM
 Date of Last Inspection: 03/18/2003

Mine Name: Wildcat Loadout County: Carbon Permit Number: C/007/033
 Permittee and/or Operator's Name: Andalex Resources, Inc.
 Business Address: P.O. Box 902, Price, Utah 84501
 Company Official(s): Mr. Scott Dimick, Superintendent
 State Official(s): Peter Hess Federal Official(s): None
 Weather Conditions: Sunny, clear / Temperature in sixties, Fahrenheit
 Type of Mining Activity: Underground Surface Prep Plant XXX Other
 Existing Acreage: Permitted 100 Disturbed 63.7 Regraded Seeded
 Status: Active

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
 - b. For partial inspections check only the elements evaluated.
2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

	EVALUATED	N/A	COMMENTS	NOV/ENF
1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. SIGNS AND MARKERS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. TOPSOIL	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4. HYDROLOGIC BALANCE:				
a. DIVERSIONS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
b. SEDIMENT PONDS AND IMPOUNDMENTS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
c. OTHER SEDIMENT CONTROL MEASURES	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
d. WATER MONITORING	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
e. EFFLUENT LIMITATIONS	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. EXPLOSIVES	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
8. NONCOAL WASTE	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL ISSUES	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
10. SLIDES AND OTHER DAMAGE	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. CONTEMPORANEOUS RECLAMATION	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. BACKFILLING AND GRADING	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. REVEGETATION	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14. SUBSIDENCE CONTROL	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. CESSATION OF OPERATIONS	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16. ROADS:				
a. CONSTRUCTION/MAINTENANCE/SURFACING	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
b. DRAINAGE CONTROLS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
17. OTHER TRANSPORTATION FACILITIES	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
18. SUPPORT FACILITIES/UTILITY INSTALLATIONS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
19. AVS CHECK (4 th Quarter- April, May, June)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
20. AIR QUALITY PERMIT	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
21. BONDING & INSURANCE	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

INSPECTION REPORT
(Continuation Sheet)

PERMIT NUMBER: C/007/033

DATE OF INSPECTION: 04/09/2003

(COMMENTS ARE NUMBERED TO CORRESPOND WITH TOPICS LISTED ABOVE)

3. TOPSOIL

The topsoil pile adjacent to sediment pond "A" and the two piles north of sediment pond "F" were inspected. There is no visible evidence of sprouting on any of the piles.

4B. HYDROLOGIC BALANCE: SEDIMENT PONDS AND IMPOUNDMENTS

All of the site's ponds were observed as dry. There were no problems noted.

4D. HYDROLOGIC BALANCE: WATER MONITORING

Wildcat wash was observed to have no flow.

7. COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS

The waste rock disposal area was inspected; there were no problems noted relative to hazards or signs of instability. A few piles of end-dumped refuse were observed on the west side of the pile. A few pieces of brattice and other types of non-coal waste were observed. The MSHA identification sign is in place, as required.

9. PROTECTION OF FISH, WILDLIFE, AND RELATED ENVIRONMENTAL VALUES

The permittee utilizes an above ground storage tank for diesel fuel on the West side of the property (tank is NNW of the truck unloading grizzly). An area of discoloration approximately fifteen feet in diameter was observed beneath this tank, indicative of a diesel fuel spill. Mr. Dimick agreed to remove the contaminated soil and properly dispose of it. New material will replace the soil that will be removed.

19. AVS CHECK

A check of the applicant violator system by Division personnel on April 17, 2003 revealed that there have been no changes in corporate personnel within Andalex Resources, Inc. The AVS information was cross checked with information included in Chapter 1, page 7-A of the mining and reclamation plan for the Wildcat rail loading facility.

Inspector's Signature: _____ Date: May 1, 2003
Peter Hess #46

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas & Mining.

cc: James Fulton, OSM
Mike Glasson, Andalex
Price Field office

O:\007033.WCL\Compliance\2003\P_0409.doc