



The State of Utah
 Department of
 Natural Resources
 Division of
 Oil, Gas & Mining

ROBERT L. MORGAN
Executive Director
 LOWELL P. BRAXTON
Division Director

OLENE S. WALKER
Governor
 GAYLE F. McKEACHNIE
Lieutenant Governor

Representatives Present During the Inspection:		
OGM	Pete Hess	Environmental Scientist III
OGM	Scott Dimick	Superintendent
Company	Scott Dimick	Superintendent

Inspection Report

Permit Number:	C0070033
Inspection Type:	PARTIAL
Inspection Date:	Friday, May 14, 2004
Start Date/Time:	05/14/2004 10:00:00 AM
End Date/Time:	05/14/2004 11:20:00 AM
Last Inspection:	Tuesday, April 06, 2004

Inspector: Pete Hess, Environmental Scientist III
 Weather: Sunny, clear, temperature in 50's F.
 InspectionID Report Number: 269

Accepted by: pgrubaug
 06/01/2004

Permittee: **ANDALEX RESOURCES INC TOWER DIVISION**
 Operator: **ANDALEX RESOURCES INC TOWER DIVISION**
 Site: **WILDCAT LOADOUT**
 Address: **PO BOX 902, PRICE UT 84501**
 County: **CARBON**
 Permit Type: **PERMANENT COAL PROGRAM**
 Permit Status: **ACTIVE**

Current Acreages

100.00	Total Permitted
63.70	Total Disturbed
	Phase I
	Phase II
	Phase III

Mineral Ownership

- Federal
- State
- County
- Fee
- Other

Types of Operations

- Underground
- Surface
- Loadout
- Processing
- Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

The permittee continues to submit water monitoring information for the Wildcat permit area in an electronic fashion to the Division web site. This is a permit condition included as part of Attachment "A" of the current State permit issued by the DOGM. There are no pending compliance actions for the Wildcat permit area.

Inspector's Signature: _____

Date Friday, May 14, 2004

Pete Hess, Environmental Scientist III
 Inspector ID Number: 46

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining

Permit Number: C0070033
 Inspection Type: PARTIAL
 Inspection Date: Friday, May 14, 2004

Inspection Continuation Sheet

REVIEW OF PERMIT PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENT

1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

	Evaluated	Not Applicable	Comment	Enforcement
1. Permits, Change, Transfer, Renewal, Sale	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. Signs and Markers	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Topsoil	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.a Hydrologic Balance: Diversions	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.b Hydrologic Balance: Sediment Ponds and Impoundments	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.c Hydrologic Balance: Other Sediment Control Measures	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.d Hydrologic Balance: Water Monitoring	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.e Hydrologic Balance: Effluent Limitations	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Explosives	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Disposal of Excess Spoil, Fills, Benches	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Coal Mine Waste, Refuse Piles, Impoundments	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Noncoal Waste	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Protection of Fish, Wildlife and Related Environmental Issues	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Slides and Other Damage	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Contemporaneous Reclamation	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Backfilling And Grading	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14. Subsidence Control	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. Cessation of Operations	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16.a Roads: Construction, Maintenance, Surfacing	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16.b Roads: Drainage Controls	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
17. Other Transportation Facilities	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
18. Support Facilities, Utility Installations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
19. AVS Check	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
20. Air Quality Permit	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
21. Bonding and Insurance	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
22. Other	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>

3. Topsoil

All four of the sites topsoil storage areas were inspected this day. All signs are in place. All of the berms which collect any runoff from the piles are in place. Vegetation appears to be doing well, due to recent precipitation events. There was no evidence of coal fines on any of the piles.

4.b Hydrologic Balance: Sediment Ponds and Impoundments

Most of the sediment containments at the site were dry; a few contained a small amount of water. There were no hazards noted for any of the ponds.

4.d Hydrologic Balance: Water Monitoring

There was no flow observed in Wildcat Wash this day.

20. Air Quality Permit

A front end loader was loading coal into trucks on the coal stockpile pad located northwest of sediment pond "A". Dust was being thrown into suspension as the trucks ran over the pad area to the loading point. The permittee may want to consider watering the travel area to minimize this hazard.

22. Other

Vegetation appears to be doing well in most of the areas which are in close proximity to the coal stockpiles. Although coal fines (-100 mesh material) are visible on the soil surface where slight depressions exist, the fines do not appear to be having any impact on the vegetation itself. The County has seen some recent moisture over the last month.