

0001



State of Utah

Department of
Natural ResourcesMICHAEL R. STYLER
Executive DirectorDivision of
Oil, Gas & MiningJOHN R. BAZA
Division DirectorJON M. HUNTSMAN, JR.
GovernorGARY R. HERBERT
Lieutenant Governor

Representatives Present During the Inspection:

OGM Pete Hess Environmental Scientist III

Inspection Report

Permit Number:	C0070033
Inspection Type:	PARTIAL
Inspection Date:	Wednesday, January 02, 2008
Start Date/Time:	1/2/2008 12:45:00 PM
End Date/Time:	1/2/2008 1:30:00 PM
Last Inspection:	Thursday, December 18, 2008

Inspector: Pete Hess, Environmental Scientist IIIWeather: Cold, overcast; 18 degrees F.InspectionID Report Number: 1515

Accepted by: dhaddock

2/1/2008

Permittee: **ANDALEX RESOURCES INC TOWER DIVISION**Operator: **ANDALEX RESOURCES INC TOWER DIVISION**Site: **WILDCAT LOADOUT**Address: **6750 AIRPORT RD, PO BOX 902 PRICE UT 84501**County: **CARBON**Permit Type: **PERMANENT COAL PROGRAM**Permit Status: **ACTIVE**

Current Acreages

100.00	Total Permitted
63.70	Total Disturbed
	Phase I
	Phase II
	Phase III

Mineral Ownership

- Federal
 State
 County
 Fee
 Other

Types of Operations

- Underground
 Surface
 Loadout
 Processing
 Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

The Permittee is current relative to the required quarterly submittal of surface water monitoring data in an electronic form.

The response to Division Order DO-04 is due January 31, 2008. The Division has met several times with the Permittee to work out acceptable solutions relative to controlling fugitive dust on the primary haul roads inside the disturbed area boundary. The Permittee's response should incorporate those solutions.

The site remains under frozen compacted snow, and only operational haul roads and coal storage pads have been cleared.

This inspection was not capable of being completed; a Permittee representative was not available to conduct the inspection.

Inspector's Signature:

Date

Friday, February 01, 2008

Pete Hess, Environmental Scientist III

Inspector ID Number: 46

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

1594 West North Temple, Suite 1210, PO Box 145801, Salt Lake City, UT 84114-5801
 telephone (801) 538-5340 • facsimile (801) 359-3940 • TTY (801) 538-7458 • www.ogm.utah.gov

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

	Evaluated	Not Applicable	Comment	Enforcement
1. Permits, Change, Transfer, Renewal, Sale	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. Signs and Markers	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Topsoil	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.a Hydrologic Balance: Diversions	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.b Hydrologic Balance: Sediment Ponds and Impoundments	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.c Hydrologic Balance: Other Sediment Control Measures	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.d Hydrologic Balance: Water Monitoring	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.e Hydrologic Balance: Effluent Limitations	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Explosives	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Disposal of Excess Spoil, Fills, Benches	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Coal Mine Waste, Refuse Piles, Impoundments	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Noncoal Waste	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Protection of Fish, Wildlife and Related Environmental Issues	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Slides and Other Damage	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Contemporaneous Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Backfilling And Grading	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14. Subsidence Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. Cessation of Operations	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16.a Roads: Construction, Maintenance, Surfacing	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16.b Roads: Drainage Controls	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
17. Other Transportation Facilities	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
18. Support Facilities, Utility Installations	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
19. AVS Check	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
20. Air Quality Permit	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
21. Bonding and Insurance	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
22. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Permit Number: C0070033

Inspection Type: PARTIAL

Inspection Date: Wednesday, January 02, 2008

4.b Hydrologic Balance: Sediment Ponds and Impoundments

Ponds E and F, the permanent impoundment and the depression area were all snow covered. The depression area did not have coal stored within its watershed boundary this day. All other ponds contain frozen melt water. None of the ponds were close to discharge.