

## OGMCOAL - Wildcat Inspection Report 3/30/2011

---

**From:** Kevin Lundmark  
**To:** Dana Marrelli; Dave Shaver  
**Date:** 4/6/2011 3:30 PM  
**Subject:** Wildcat Inspection Report 3/30/2011  
**CC:** OGMCOAL; Pete Hess  
**Attachments:** 20110406162507.pdf

---

FYI

Kevin Lundmark  
Utah Department of Natural Resources  
Division of Oil, Gas & Mining  
[kevinlundmark@utah.gov](mailto:kevinlundmark@utah.gov)  
(801)538-5352



The State of Utah

Department of  
Natural Resources

Division of  
Oil, Gas & Mining

ROBERT L. MORGAN  
*Executive Director*

LOWELL P. BRAXTON  
*Division Director*

OLENE S. WALKER  
*Governor*

GAYLE F. McKEACHNIE  
*Lieutenant Governor*

# Inspection Report

Permit Number:	C0070033
Inspection Type:	TECHNICAL
Inspection Date:	Wednesday, March 30, 2011
Start Date/Time:	3/30/2011 1:20:00 PM
End Date/Time:	3/30/2011 1:50:00 PM
Last Inspection:	

Inspector: Kevin Lundmark

Weather: Mostly sunny, 50s

InspectionID Report Number: 2698

Accepted by: jhelfric  
4/4/2011

Permittee: **ANDALEX RESOURCES INC**  
 Operator: **ANDALEX RESOURCES INC**  
 Site: **WILDCAT LOADOUT**  
 Address: **PO BOX 910, EAST CARBON UT 84520-0910**  
 County: **CARBON**  
 Permit Type: **PERMANENT COAL PROGRAM**  
 Permit Status: **ACTIVE**

### Current Acreages

100.00	<b>Total Permitted</b>
78.45	<b>Total Disturbed</b>
	<b>Phase I</b>
	<b>Phase II</b>
	<b>Phase III</b>

### Mineral Ownership

- Federal
- State
- County
- Fee
- Other

### Types of Operations

- Underground
- Surface
- Loadout
- Processing
- Reprocessing

**Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:**

Division inspected Sediment Pond C to evaluate the amount and characteristics of sludge which has been transported to the pond from Crandall Canyon mine.

Inspector's Signature:

Date

Thursday, March 31, 2011

Kevin Lundmark,

Inspector ID Number: 63

**Note:** This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

1594 West North Temple, Suite 1210, PO Box 145801, Salt Lake City, UT 84114-5801  
telephone (801) 538-5340 facsimile (801) 359-3940 TTY (801) 538-7223 [www.ogm.utah.gov](http://www.ogm.utah.gov)

**Utah!**  
Where ideas connect™

**REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS**

1. Substantiate the elements on this inspection by checking the appropriate performance standard.
  - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
  - b. For PARTIAL inspections check only the elements evaluated.
2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

	Evaluated	Not Applicable	Comment	Enforcement
1. Permits, Change, Transfer, Renewal, Sale	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. Signs and Markers	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Topsoil	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.a Hydrologic Balance: Diversions	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.b Hydrologic Balance: Sediment Ponds and Impoundments	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.c Hydrologic Balance: Other Sediment Control Measures	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.d Hydrologic Balance: Water Monitoring	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.e Hydrologic Balance: Effluent Limitations	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Explosives	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Disposal of Excess Spoil, Fills, Benches	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Coal Mine Waste, Refuse Piles, Impoundments	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Noncoal Waste	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Protection of Fish, Wildlife and Related Environmental Issues	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Slides and Other Damage	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Contemporaneous Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Backfilling And Grading	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14. Subsidence Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. Cessation of Operations	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16.a Roads: Construction, Maintenance, Surfacing	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16.b Roads: Drainage Controls	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
17. Other Transportation Facilities	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
18. Support Facilities, Utility Installations	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
19. AVS Check	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
20. Air Quality Permit	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
21. Bonding and Insurance	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
22. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

**4.b Hydrologic Balance: Sediment Ponds and Impoundments**

Sediment Pond was observed to contain water in the NE half. Orange iron sludge was visible in the portion of the pond which did not contain free water. Sludge was wet and not suitable to walk on. Using a shovel, the sludge depth was investigated at several locations approximately 3 feet from the pond embankment. Sludge depth ranged from about 12 inches near the half-round inlet to about 2 inches elsewhere. The middle of the pond was not accessible.