



State of Utah
 DEPARTMENT OF NATURAL RESOURCES
 MICHAEL R. STYLER
Executive Director
Division of Oil, Gas and Mining
 JOHN R. BAZA
Division Director

Inspection Report

Permit Number:	C0070033
Inspection Type:	COMPLETE
Inspection Date:	Thursday, November 12, 2015
Start Date/Time:	11/12/2015 9:00:00 AM
End Date/Time:	11/12/2015 2:00:00 PM
Last Inspection:	Wednesday, October 14, 2015

Representatives Present During the Inspection:	
Company	Kit Pappas
OGM	Steve Demczak

Inspector: Steve Demczak
 Weather: Sunny, 40's
 InspectionID Report Number: 5359
 Accepted by: JHELFRIC
 11/17/2015

Permittee: **INTERMOUNTAIN POWER AGENCY**
 Operator: **WILD WEST EQUIPMENT & HAULING, LLC**
 Site: **WILDCAT LOADOUT**
 Address: **PO BOX 1, PRICE UT 84501**
 County: **CARBON**
 Permit Type: **PERMANENT COAL PROGRAM**
 Permit Status: **ACTIVE**

Current Acreages

111.62	Total Permitted
111.62	Total Disturbed
	Phase I
	Phase II
	Phase III

Mineral Ownership

- Federal
- State
- County
- Fee
- Other

Types of Operations

- Underground
- Surface
- Loadout
- Processing
- Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

There is relatively no coal on the ground.

The Wildcat Loadout is idle. At the time of the inspection there were no rail cars for the transportation of oil.

Stephen J. Demczak

Inspector's Signature:

Steve Demczak,
 Inspector ID Number: 39

Date Tuesday, November 17, 2015



REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

	Evaluated	Not Applicable	Comment	Enforcement
1. Permits, Change, Transfer, Renewal, Sale	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Signs and Markers	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Topsoil	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.a Hydrologic Balance: Diversions	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.b Hydrologic Balance: Sediment Ponds and Impoundments	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.c Hydrologic Balance: Other Sediment Control Measures	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.d Hydrologic Balance: Water Monitoring	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.e Hydrologic Balance: Effluent Limitations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
5. Explosives	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Disposal of Excess Spoil, Fills, Benches	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Coal Mine Waste, Refuse Piles, Impoundments	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
8. Noncoal Waste	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
9. Protection of Fish, Wildlife and Related Environmental Issues	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Slides and Other Damage	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Contemporaneous Reclamation	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Backfilling And Grading	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. Revegetation	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14. Subsidence Control	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. Cessation of Operations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
16.a Roads: Construction, Maintenance, Surfacing	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
16.b Roads: Drainage Controls	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
17. Other Transportation Facilities	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
18. Support Facilities, Utility Installations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
19. AVS Check	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
20. Air Quality Permit	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
21. Bonding and Insurance	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
22. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

1. Permits, Change, Transfer, Renewal, Sale

Wildcat Loadout has receive an approval by the Divisions for increasing the disturb area. The new disturb area is 111.62 acres. The previous disturb area was 88.62 acres. DOGM Permit remains in effect through May 5, 2019.

The UPDES permit remains in effect through August 31, 2018.

The current air quality permit DAQE - AN0113007-04 dated December 3, 2004

2. Signs and Markers

I inspected the identification sign at the main gate to the property. The information complies with the requirements of the R645 Coal Rules. See Picture

3. Topsoil

I inspected the topsoil piles which were stable with no signs of wind or water erosion. The topsoil is protected by a berm.

4.a Hydrologic Balance: Diversions

The diversions and culverts were inspected. They were open and would carry water to the sediment pond for the design storm event.

4.b Hydrologic Balance: Sediment Ponds and Impoundments

The permittee conducted a third quarter sediment pond inspection on Sept. 18, 2015. . No hazardous conditions were reported. I inspected the sediment ponds and they appear to be stable with no hazardous conditions. The sediment ponds contain little to no water. See Pictures

4.c Hydrologic Balance: Other Sediment Control Measures

The wind fence for coal fines was maintained. There is no coal at the facility at the present time.

4.d Hydrologic Balance: Water Monitoring

Quarterly water monitoring information is submitted to the Division in Salt Lake City and analyzed.

4.e Hydrologic Balance: Effluent Limitations

here was no discharge from the six UPDES point for the third quarter of 2015. It is unlikely a discharge will occur in the fourth quarter of 2015.

7. Coal Mine Waste, Refuse Piles, Impoundments

The permittee conducted a third quarter refuse pile inspection on July 20, 2015. No hazardous conditions were reported. I inspected the refuse pile and it was stable. No refuse has been added for some time.

8. Noncoal Waste

The facility was clear on trash and oil cans.

15. Cessation of Operations

The site is inactive at this time, but, could change at any time.

16.a Roads: Construction, Maintenance, Surfacing

Roads are well maintained.

16.b Roads: Drainage Controls

Road drainage controls such as diversions and culverts were open.

21. Bonding and Insurance

The Permittee, Intermountain Power Agency, has met the Division's requirements for self-insurance, R645-301-890.400. Wild West Equipment and Hauling also holds general liability insurance coverage for this site which remains in effect through July 1, 2016. Coverage amounts for the each occurrence and general aggregate categories are adequate.

NOTICE

WITHOUT PRIOR APPROVAL,
DELIVERIES, VENDORS,
AND JOB APPLICANTS:
CHECK IN AT MAIN
LOCATED AT MINE

ATTENTION

SIGN IN AT
SCALE HOUSE
PRIOR TO
PROCEEDING
ONTO PROPERTY

SPEED
LIMIT


5


WILDCAT LOAD OUT


OWNER: INTERMOUNTAIN POWER AGENCY
P.O. BOX 81111 - ROOM 1263
LOS ANGELES, CALIFORNIA 90061
PHONE: 313-387-0268
1000DM PERMIT NO. C 0007 033


OPERATOR:
WILD WEST EQUIPMENT & RENTALS, LLC
P.O. BOX 1
PRICE, UTAH 84503
PHONE: 435-472-2045
MSHA ID NO. 42-01664

















SACRAMENT
POINT
F