



# State of Utah

## DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER  
Executive Director

### Division of Oil, Gas and Mining

JOHN R. BAZA  
Division Director

# Inspection Report

Permit Number:	C0070033
Inspection Type:	COMPLETE
Inspection Date:	Tuesday, February 16, 2016
Start Date/Time:	2/16/2016 10:00:00 AM
End Date/Time:	2/16/2016 1:00:00 PM
Last Inspection:	Thursday, January 14, 2016

Representatives Present During the Inspection:	
Company	Kit Pappas
OGM	Steve Demczak

Inspector: Steve Demczak

Weather: Sunny, 40's, Partly Snow Covered, Muddy

InspectionID Report Number: 5445

Accepted by: JHELFRIC

2/22/2016

Permitee: **INTERMOUNTAIN POWER AGENCY**  
 Operator: **WILD WEST EQUIPMENT & HAULING, LLC**  
 Site: **WILDCAT LOADOUT**  
 Address: **PO BOX 1, PRICE UT 84501**  
 County: **CARBON**  
 Permit Type: **PERMANENT COAL PROGRAM**  
 Permit Status: **ACTIVE**

#### Current Acreages

111.62	<b>Total Permitted</b>
111.62	<b>Total Disturbed</b>
	<b>Phase I</b>
	<b>Phase II</b>
	<b>Phase III</b>

#### Mineral Ownership

- Federal
- State
- County
- Fee
- Other

#### Types of Operations

- Underground
- Surface
- Loadout
- Processing
- Reprocessing

#### Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

The loadout is not active. This could change when the Emery/Consol Permit is transferred.


No personnel are station at the loadout.

Stephen J. Demczak

Inspector's Signature:

Steve Demczak,  
Inspector ID Number: 39

Date Monday, February 22, 2016



**Note:** This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.  
 telephone (801) 538-5340 • facsimile (801) 359-3940 • TTY (801) 538-7458 • www.ogm.utah.gov

**REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS**

1. Substantiate the elements on this inspection by checking the appropriate performance standard.
  - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
  - b. For PARTIAL inspections check only the elements evaluated.
2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

	Evaluated	Not Applicable	Comment	Enforcement
1. Permits, Change, Transfer, Renewal, Sale	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Signs and Markers	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Topsoil	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.a Hydrologic Balance: Diversions	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.b Hydrologic Balance: Sediment Ponds and Impoundments	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.c Hydrologic Balance: Other Sediment Control Measures	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.d Hydrologic Balance: Water Monitoring	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.e Hydrologic Balance: Effluent Limitations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
5. Explosives	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Disposal of Excess Spoil, Fills, Benches	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Coal Mine Waste, Refuse Piles, Impoundments	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
8. Noncoal Waste	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
9. Protection of Fish, Wildlife and Related Environmental Issues	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
10. Slides and Other Damage	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Contemporaneous Reclamation	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Backfilling And Grading	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. Revegetation	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14. Subsidence Control	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. Cessation of Operations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
16.a Roads: Construction, Maintenance, Surfacing	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
16.b Roads: Drainage Controls	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
17. Other Transportation Facilities	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
18. Support Facilities, Utility Installations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
19. AVS Check	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
20. Air Quality Permit	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
21. Bonding and Insurance	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
22. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

## **1. Permits, Change, Transfer, Renewal, Sale**

The permittee has submitted to the Division an update to the Ownership and Control information in Chapter 1.

DOGMA Permit remains in effect through May 5, 2019.

The UPDES permit remains in effect through August 31, 2018.

The current Air Quality Permit DAQE - AN0113007-04 dated December 3, 2004

## **2. Signs and Markers**

I inspected the identification sign at the main gate to the property. The information complies with the requirements of the R645 Coal Rules. See Picture

## **3. Topsoil**

I inspected the topsoil piles which were stable with no signs of wind or water erosion. The topsoil piles are is protected by berms.

### **4.a Hydrologic Balance: Diversions**

The diversions and culverts were inspected. They were open or partly snow covered. Water in some of the diversions was being conveyed to the sediment ponds. See pictures

### **4.b Hydrologic Balance: Sediment Ponds and Impoundments**

The permittee conducted a fourth quarter sediment pond inspection on Sept. 18 and December 18, 2015. No hazardous conditions were reported. I inspected the sediment ponds and they appear to be stable with no hazardous conditions. The sediment ponds contain little to no water. See Pictures

### **4.d Hydrologic Balance: Water Monitoring**

Quarterly water monitoring information is submitted to the Division in Salt Lake City and analyzed.

### **4.e Hydrologic Balance: Effluent Limitations**

There were no UPDES discharges for the fourth quarter of 2015.

## **7. Coal Mine Waste, Refuse Piles, Impoundments**

The permittee conducted a fourth quarter refuse pile inspection on December 8, 2015. No hazardous conditions were reported. I inspected the refuse pile and it was stable. No refuse has been added for some time. The diversion around the refuse pile was functioning as designed.

## **8. Noncoal Waste**

The facility was clear of trash and oil cans.

**9. Protection of Fish, Wildlife and Related Environmental Issues**

Small ducks were swimming in the water, in a depression long the road. See Picture

**15. Cessation of Operations**

The site is inactive at this time, but, could change at any time.

**16.a Roads: Construction, Maintenance, Surfacing**

The roads were either still snow covered or extremely muddy.

**18. Support Facilities, Utility Installations**

No new additions to the support facility.

**19. AVS Check**

The permittee has submitted and update to ownership and control information to the Division.

**21. Bonding and Insurance**

The Permittee, Intermountain Power Agency, has met the Division's requirements for self-insurance, R645-301-890.400. Wild West Equipment and Hauling also holds general liability insurance coverage for this site which remains in effect through July 1, 2016. Coverage amounts for the each occurrence and general aggregate categories are adequate.

SRVEILLANCE  
CAMERAS  
IN USE

SPEED  
LIMIT  
5

ATT  
SIC  
SCAN  
PR  
PRO  
ONTO

### WILDCAT LOAD OUT

OWNER: INTERMOUNTAIN POWER AGENCY  
P.O. BOX 51111 - ROOM 1263  
LOS ANGELES, CALIFORNIA 90051  
PHONE: 213-367-0289  
UDOGM PERMIT NO. C/007/033

OPERATOR:  
WILD WEST EQUIPMENT & HAULING, LLC  
P.O. BOX 1  
PRICE, UTAH 84501  
PHONE: 435-472-3988  
MSHA ID NO. 42-01864

















SEDIMENT  
POND  
F



TOP SOIL  
STORAGE

TOP SOIL  
STORAGE









SRVEILLANCE  
CAMERAS  
IN USE

SPEED  
LIMIT  
5

ATT  
SIC  
SCAN  
PR  
PRO  
ONTO

**WILDCAT LOAD OUT**

OWNER: INTERMOUNTAIN POWER AGENCY  
P.O. BOX 51111 - ROOM 1263  
LOS ANGELES, CALIFORNIA 90051  
PHONE: 213-367-0289  
UDOGM PERMIT NO. C/007/033

OPERATOR:  
WILD WEST EQUIPMENT & HAULING, LLC  
P.O. BOX 1  
PRICE, UTAH 84501  
PHONE: 435-472-3988  
MSHA ID NO. 42-01864

















SEDIMENT  
POND  
F



TOP SOIL  
STORAGE

TOP SOIL  
STORAGE







