State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA
Division Director

GARY R. HERBERT
Governor

GREG BELL
Lieutenant Governor

Inspection Report

Permit Number:	**C0070033**
Inspection Type:	PARTIAL
Inspection Date:	Thursday, September 15, 2016
Start Date/Time:	9/15/2016 9:00:00 AM
End Date/Time:	9/15/2016 4:00:00 PM
Last Inspection:	Tuesday, August 16, 2016

Inspector: Steve Demczak,

Weather: Sunny, Low 80's, Dry Ground Conditions

InspectionID Report Number: 5642

Accepted by: DHADDOCK
9/30/2016

Representatives Present During the Inspection:

Company	Kit Pappas
OGM	Steve Demczak

Permitee: **INTERMOUNTAIN POWER AGENCY**
Operator: **WILD WEST EQUIPMENT & HAULING, LLC**
Site: **WILDCAT LOADOUT**
Address: **PO BOX 1, PRICE UT 84501**
County: **CARBON**
Permit Type: **PERMANENT COAL PROGRAM**
Permit Status: **ACTIVE**

Current Acreages

111.62	**Total Permitted**
111.62	**Total Disturbed**
	Phase I
	Phase II
	Phase III

Mineral Ownership

- [x] Federal
- [ ] State
- [ ] County
- [ ] Fee
- [ ] Other

Types of Operations

- [ ] Underground
- [ ] Surface
- [x] Loadout
- [x] Processing
- [ ] Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

The coal loadout facility was idle.

Stephen J. Demczak

Inspector's Signature:

Date Thursday, September 22, 2016

Steve Demczak,
Inspector ID Number: 39

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

1594 West North Temple, Suite 1210, PO Box 145801, Salt Lake City, UT 84114-5801
telephone (801) 538-5340 • facsimile (801) 359-3940 • TTY (801) 538-7458 • www.ogm.utah.gov

UTAH DNR OIL, GAS & MINING

Permit Number: C0070033
Inspection Type: PARTIAL
Inspection Date: Thursday, September 15, 2016

Inspection Continuation Sheet

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

1. *Substantiate the elements on this inspection by checking the appropriate performance standard.*
   a. *For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.*
   b. *For PARTIAL inspections check only the elements evaluated.*
2. *Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.*
3. *Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.*
4. *Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.*

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale	☑	☐	☑	☐
2.	Signs and Markers	☑	☐	☑	☐
3.	Topsoil	☑	☐	☑	☐
4.a	Hydrologic Balance: Diversions	☑	☐	☑	☐
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	☑	☐	☑	☐
4.c	Hydrologic Balance: Other Sediment Control Measures	☑	☐	☐	☐
4.d	Hydrologic Balance: Water Monitoring	☐	☐	☐	☐
4.e	Hydrologic Balance: Effluent Limitations	☐	☐	☐	☐
5.	Explosives	☐	☐	☐	☐
6.	Disposal of Excess Spoil, Fills, Benches	☐	☐	☐	☐
7.	Coal Mine Waste, Refuse Piles, Impoundments	☑	☐	☑	☐
8.	Noncoal Waste	☑	☐	☑	☐
9.	Protection of Fish, Wildlife and Related Environmental Issues	☐	☐	☐	☐
10.	Slides and Other Damage	☑	☐	☑	☐
11.	Contemporaneous Reclamation	☐	☐	☐	☐
12.	Backfilling And Grading	☐	☐	☐	☐
13.	Revegetation	☐	☐	☐	☐
14.	Subsidence Control	☐	☐	☐	☐
15.	Cessation of Operations	☐	☐	☐	☐
16.a	Roads: Construction, Maintenance, Surfacing	☐	☐	☐	☐
16.b	Roads: Drainage Controls	☑	☐	☑	☐
17.	Other Transportation Facilities	☐	☐	☐	☐
18.	Support Facilities, Utility Installations	☐	☐	☐	☐
19.	AVS Check	☐	☐	☐	☐
20.	Air Quality Permit	☐	☐	☐	☐
21.	Bonding and Insurance	☐	☐	☐	☐
22.	Other	☐	☐	☐	☐

1. Permits, Change, Transfer, Renewal, Sale

There are no amendments with the Division at this time.

2. Signs and Markers

I inspected the identification sign at the main gate. This sign meets the minimum requirements of the R645 Coal Rules. See Picture

3. Topsoil

The topsoil piles were stable with no signs of wind or water erosion. Some vegetation is growing on the piles.

4.a Hydrologic Balance: Diversions

I inspected several diversions and culverts within the permit area. These structures were open and functioning as designed.

4.b Hydrologic Balance: Sediment Ponds and Impoundments

The sediment ponds were inspected with no hazardous conditions noticed during the inspection. Inlets and outlets were open. Embankments appear to be stable. See pictures

7. Coal Mine Waste, Refuse Piles, Impoundments

I inspected the refuse pile with no hazardous conditions noticed during the inspection. Embankments appear to be stable.

8. Noncoal Waste

The site was clear of non-coal waste materials such as trash and oil cans.

10. Slides and Other Damage

No slides or other damage was noticed during the inspection.

16.b Roads: Drainage Controls

Diversions and culverts along the road were open and functioning as designed.

EILLANCE
MERAS
USE
5
WILDCAT LOAD OUT
OWNER: INTERMOUNTAIN POWER AGENCY
P.O. BOX 51111 - ROOM 1263
LOS ANGELES, CALIFORNIA 90051
PHONE: 213-367-0289
UDOGM PERMIT NO. C/007/033
OPERATOR:
WILD WEST EQUIPMENT & HAULING, LLC
P.O. BOX 1
PRICE, UTAH 84501
PHONE: 435-472-3988
MSHA ID NO. 42-01864



TOP SOIL
STORAGE AREA