



# State of Utah

## DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER  
Executive Director

### Division of Oil, Gas and Mining

JOHN R. BAZA  
Division Director

# Inspection Report

Permit Number:	C0070033
Inspection Type:	PARTIAL
Inspection Date:	Thursday, September 21, 2017
Start Date/Time:	9/21/2017 10:00:00 AM
End Date/Time:	9/22/2017 2:00:00 PM
Last Inspection:	Thursday, August 17, 2017

Representatives Present During the Inspection:	
Company	Kit Pappas
OGM	Steve Demczak

Inspector: Steve Demczak

Weather: Partly cloudy, 70's, Dry Ground Conditions

InspectionID Report Number: 5966

Accepted by: DHADDOCK  
10/17/2017

Permitee: **INTERMOUNTAIN POWER AGENCY**  
 Operator: **WILD WEST EQUIPMENT & HAULING, LLC**  
 Site: **WILDCAT LOADOUT**  
 Address: **PO BOX 1, PRICE UT 84501**  
 County: **CARBON**  
 Permit Type: **PERMANENT COAL PROGRAM**  
 Permit Status: **INACTIVE**

#### Current Acreages

111.62	<b>Total Permitted</b>
111.62	<b>Total Disturbed</b>
	<b>Phase I</b>
	<b>Phase II</b>
	<b>Phase III</b>

#### Mineral Ownership

- Federal
- State
- County
- Fee
- Other

#### Types of Operations

- Underground
- Surface
- Loadout
- Processing
- Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

The loadout is in temporary cessation. This can change depending on the coal market.

Stephen J. Demczak

Inspector's Signature:

Steve Demczak,  
Inspector ID Number: 39

Date Thursday, September 28, 2017



Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.  
 telephone (801) 538-5340 • facsimile (801) 359-3940 • TTY (801) 538-7458 • www.ogm.utah.gov

**REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS**

1. Substantiate the elements on this inspection by checking the appropriate performance standard.
  - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
  - b. For PARTIAL inspections check only the elements evaluated.
2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

	Evaluated	Not Applicable	Comment	Enforcement
1. Permits, Change, Transfer, Renewal, Sale	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Signs and Markers	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Topsoil	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.a Hydrologic Balance: Diversions	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.b Hydrologic Balance: Sediment Ponds and Impoundments	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.c Hydrologic Balance: Other Sediment Control Measures	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.d Hydrologic Balance: Water Monitoring	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.e Hydrologic Balance: Effluent Limitations	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Explosives	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Disposal of Excess Spoil, Fills, Benches	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Coal Mine Waste, Refuse Piles, Impoundments	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
8. Noncoal Waste	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
9. Protection of Fish, Wildlife and Related Environmental Issues	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Slides and Other Damage	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
11. Contemporaneous Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Backfilling And Grading	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14. Subsidence Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. Cessation of Operations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
16.a Roads: Construction, Maintenance, Surfacing	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16.b Roads: Drainage Controls	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
17. Other Transportation Facilities	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
18. Support Facilities, Utility Installations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
19. AVS Check	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
20. Air Quality Permit	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
21. Bonding and Insurance	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
22. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

**1. Permits, Change, Transfer, Renewal, Sale**

There are no permitting actions with the Division at this time.

**2. Signs and Markers**

The identification sign was inspected and it meets the requirements of the R645 Coal Rules. See Photo

**3. Topsoil**

I inspected the topsoil piles and I did not see any signs of wind or water erosion. The topsoil piles appear to be stable and protected by a berm. See Photo

**4.a Hydrologic Balance: Diversions**

I inspected diversions and culverts throughout the property. They were open and would function as designed during a storm event. The structures were recently re-graded and cleaned out of sediment. See photos

**4.b Hydrologic Balance: Sediment Ponds and Impoundments**

I inspected the sediment ponds throughout the property. They contained some water but were not discharging. It is unlikely these structures will discharge in the near future. The embankments appear to be stable. Inlets and outlets would function as designed. I did not see any hazardous conditions to these structures.

**4.c Hydrologic Balance: Other Sediment Control Measures**

Silt fences and wattles were inspected and comply with the requirement of the R645 Coal Rules.

**7. Coal Mine Waste, Refuse Piles, Impoundments**

I inspected the refuse pile and it appears to be stable. I did not notice any hazardous conditions to the embankments. The refuse pile has been inactive for several years. See Photos

**8. Noncoal Waste**

The property was clear of non-coal waste materials such as oil, trash and grease cans.

**10. Slides and Other Damage**

No slides or other damage was noticed during the inspection. The Loadout appears to be stable.

**15. Cessation of Operations**

The loadout is not active at this time.

Permit Number: C0070033  
Inspection Type: PARTIAL  
Inspection Date: Thursday, September 21, 2017

**16.b Roads: Drainage Controls**

I inspected the road diversions and culverts throughout the property. They were functioning as designed. See Photos

**18. Support Facilities, Utility Installations**

No new facilities constructed since the last inspection.

CLOSED  
TO COAL  
SALES  
TODAY

SPEED  
LIMIT  
5

**NOTICE**  
WITHOUT PRIOR APPROVAL  
REMOVED, REWORKED, MOVED,  
AND JOB SPECIFIED MUST  
CHECK IN AT MAIN OFFICE  
LOCATED AT WIND 2716.

  
SURVEILLANCE  
CAMERAS  
IN USE

LIMIT

5

## WILDCAT LOAD OUT

OWNER: INTERMOUNTAIN POWER AGENCY  
P.O. BOX 51111 - ROOM 1263  
LOS ANGELES, CALIFORNIA 90051  
PHONE: 213-367-0289  
UDOGM PERMIT NO. C/007/033

OPERATOR:  
WILD WEST EQUIPMENT & HAULING, LLC  
P.O. BOX 1  
PRICE, UTAH 84501  
PHONE: 435-72-3988  
MSHA ID NO. 42-01864







SPEED  
LIMIT  
5







TO  
STANDARD  
POST

























