



State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA
Division Director

Inspection Report

Permit Number:	C0070033
Inspection Type:	COMPLETE
Inspection Date:	Wednesday, November 15, 2017
Start Date/Time:	11/15/2017 10:30:00 AM
End Date/Time:	11/15/2017 3:00:00 PM
Last Inspection:	Thursday, October 26, 2017

Representatives Present During the Inspection:	
Company	Kit Pappas
OGM	Steve Demczak

Inspector: Steve Demczak

Weather: Sunny, 50's, Dry Conditions

InspectionID Report Number: 6008

Accepted by: DHADDOCK

11/21/2017

Permitee: **INTERMOUNTAIN POWER AGENCY**
 Operator: **WILD WEST EQUIPMENT & HAULING, LLC**
 Site: **WILDCAT LOADOUT**
 Address: **PO BOX 1, PRICE UT 84501**
 County: **CARBON**
 Permit Type: **PERMANENT COAL PROGRAM**
 Permit Status: **INACTIVE**

Current Acreages

111.62	Total Permitted
111.62	Total Disturbed
	Phase I
	Phase II
	Phase III

Mineral Ownership

- Federal
- State
- County
- Fee
- Other

Types of Operations

- Underground
- Surface
- Loadout
- Processing
- Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

The Loadout is idle and needs major electrical repair due to vandalism.

Stephen J. Demczak

Inspector's Signature:

Steve Demczak,
Inspector ID Number: 39

Date Wednesday, November 15, 2017



REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

	Evaluated	Not Applicable	Comment	Enforcement
1. Permits, Change, Transfer, Renewal, Sale	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Signs and Markers	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Topsoil	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.a Hydrologic Balance: Diversions	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.b Hydrologic Balance: Sediment Ponds and Impoundments	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.c Hydrologic Balance: Other Sediment Control Measures	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.d Hydrologic Balance: Water Monitoring	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.e Hydrologic Balance: Effluent Limitations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
5. Explosives	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Disposal of Excess Spoil, Fills, Benches	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Coal Mine Waste, Refuse Piles, Impoundments	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
8. Noncoal Waste	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
9. Protection of Fish, Wildlife and Related Environmental Issues	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Slides and Other Damage	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
11. Contemporaneous Reclamation	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Backfilling And Grading	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. Revegetation	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14. Subsidence Control	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. Cessation of Operations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
16.a Roads: Construction, Maintenance, Surfacing	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
16.b Roads: Drainage Controls	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
17. Other Transportation Facilities	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
18. Support Facilities, Utility Installations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
19. AVS Check	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
20. Air Quality Permit	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
21. Bonding and Insurance	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
22. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

1. Permits, Change, Transfer, Renewal, Sale

The permittee is working on the mid-term completeness response which is due December 4th, 2017.

DOGM Permit remains in effect through May 5, 2019.

The UPDES permit #UTG040007 remains in effect through August 31, 2018.

The current Air Quality Permit DAQE - AN0113007-04 dated December 3, 2004

Air Quality Permit – DAQE AN0113004

SPCC Plan – Last review on October 17, 2016, P.E Certified

2. Signs and Markers

The identification sign was inspected and it meets the requirements of the R645 Coal Rules. See Photo

3. Topsoil

I inspected the topsoil piles and I did not see any signs of wind or water erosion. The topsoil piles appear to be stable and protected by a berm.

4.a Hydrologic Balance: Diversions

The diversions and culverts were open and functioning as designed. Sediment has started to fill within these structures. By next spring a major clean of ditches and diversions will be needed. Some diversions were recently cleaned. Many of the diversions are covered with weeds which causes the slowing down of the water and the depositing of sediment occurs.

4.b Hydrologic Balance: Sediment Ponds and Impoundments

I inspected the sediment ponds throughout the property. They contained some water but were not discharging. It is unlikely these structures will discharge in the near future. The embankments appear to be stable. Inlets and outlets would function as designed. I did not see any hazardous conditions to these structures. The permittee conducted a third quarter sediment pond inspection on September 18, 2017. No hazardous conditions were reported.

4.c Hydrologic Balance: Other Sediment Control Measures

Wattles were inspected and comply with the requirement of the R645 Coal Rules.

4.d Hydrologic Balance: Water Monitoring

Water monitoring information is taken by the permittee and is sent electronically to the Division in Salt Lake City. This information is reviewed and analyzed by the Division staff. A report is written.

4.e Hydrologic Balance: Effluent Limitations

No discharge had occurred for the third quarter.

7. Coal Mine Waste, Refuse Piles, Impoundments

I inspected the refuse pile and it appears to be stable. I did not notice any hazardous conditions to the embankments. The refuse pile is active. The permittee conducted a third quarter refuse pile inspection on September 18, 2017. This document is P.E. certified. No hazardous conditions were reported. See Photos

8. Noncoal Waste

The property was clear of non-coal waste materials such as oil, trash and grease cans.

10. Slides and Other Damage

No slides or other damage was notice during the inspection. The Loadout appears to be stable.

15. Cessation of Operations

This site is in "Temporary Cessation".

16.a Roads: Construction, Maintenance, Surfacing

The roads were compacted with no dust control problem.

16.b Roads: Drainage Controls

I inspected the road diversions and culverts throughout the property. They were functioning as designed. Some of the diversions have some sediment build-up within. Diversions will need cleaning out in the near future.

19. AVS Check

AVS checks are made in Salt Lake City.

21. Bonding and Insurance

The Permittee, Intermountain Power Agency, has met the Division's requirements for self-insurance, R645-301-890.400. Wild West Equipment and Hauling also holds general liability insurance coverage for this site which remains in effect through June 10, 2018. Coverage amounts for the each occurrence and general aggregate categories are adequate.

The Wildcat loadout is bonded for \$1,481,000

SURVEILLANCE
CAMERAS
IN USE

SPEED
LIMIT
5

WILDCAT LOAD OUT

OWNER: INTERMOUNTAIN POWER AGENCY
P.O. BOX 51111 - ROOM 1263
LOS ANGELES, CALIFORNIA 90051
PHONE: 213-367-0289
UDOGM PERMIT NO. C/007/033

OPERATOR:
WILD WEST EQUIPMENT & HAULING, LLC
P.O. BOX 1
PRICE, UTAH 84501
PHONE: 435-472-3988
MSHA ID NO. 42-01864

ATTN:
SILVER
SCALP
P
PRO
ONTO













EQUINE
POND



















