



State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA
Division Director

Inspection Report

Permit Number:	C0070033
Inspection Type:	PARTIAL
Inspection Date:	Tuesday, July 2, 2019
Start Date/Time:	7/2/2019 10:00:00 AM
End Date/Time:	7/2/2019 2:00:00 PM
Last Inspection:	Tuesday, June 18, 2019

Representatives Present During the Inspection:
OGM Steve Demczak

Inspector: Steve Demczak

Weather: Sunny, 80's, Dry Conditions

InspectionID Report Number: 6474

Accepted by: SCHRISTE

7/29/2019

Permittee: **COAL ENERGY GROUP 2, LLC**
 Operator: **COAL ENERGY GROUP 2, LLC**
 Site: **WILDCAT LOADOUT**
 Address: **6602 ILEX CIRCLE, NAPLES FL 34109**
 County: **CARBON**
 Permit Type: **PERMANENT COAL PROGRAM**
 Permit Status: **INACTIVE**

Current Acreages

111.62	Total Permitted
111.62	Total Disturbed
	Phase I
	Phase II
	Phase III

Mineral Ownership

- Federal
- State
- County
- Fee
- Other

Types of Operations

- Underground
- Surface
- Loadout
- Processing
- Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Lee Tweddel was on the inspection for the company.
The site is idle.

Stephen J. Demczak

Inspector's Signature:

Steve Demczak,
Inspector ID Number: 39

Date Tuesday, July 16, 2019



REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

	Evaluated	Not Applicable	Comment	Enforcement
1. Permits, Change, Transfer, Renewal, Sale	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Signs and Markers	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Topsoil	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.a Hydrologic Balance: Diversions	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.b Hydrologic Balance: Sediment Ponds and Impoundments	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.c Hydrologic Balance: Other Sediment Control Measures	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.d Hydrologic Balance: Water Monitoring	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.e Hydrologic Balance: Effluent Limitations	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Explosives	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Disposal of Excess Spoil, Fills, Benches	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Coal Mine Waste, Refuse Piles, Impoundments	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
8. Noncoal Waste	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
9. Protection of Fish, Wildlife and Related Environmental Issues	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Slides and Other Damage	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
11. Contemporaneous Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Backfilling And Grading	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14. Subsidence Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. Cessation of Operations	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16.a Roads: Construction, Maintenance, Surfacing	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
16.b Roads: Drainage Controls	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
17. Other Transportation Facilities	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
18. Support Facilities, Utility Installations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
19. AVS check	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
20. Air Quality Permit	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
21. Bonding and Insurance	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
22. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

1. Permits, Change, Transfer, Renewal, Sale

There are no permitting actions with the Division at this time.

2. Signs and Markers

The identification sign was inspected and it meets the requirements of the R645 Coal Rules. See Photo

3. Topsoil

I inspected the topsoil piles and I did not see any signs of wind or water erosion. The topsoil piles appear to be stable and protected by a berm. See Photo

4.a Hydrologic Balance: Diversions

I inspected diversions and culverts throughout the property. They were open and would function as design during a storm event. The structures were recently re-graded and clean out of sediment. See photos

4.b Hydrologic Balance: Sediment Ponds and Impoundments

I inspected the sediment ponds throughout the property. The ponds contained little to no water and were not discharging. It is unlikely these structures will discharge in the near future. The embankments appear to be stable. Inlets and outlets would function as design. I did not see any hazardous conditions to these structures.

7. Coal Mine Waste, Refuse Piles, Impoundments

I inspected the refuse pile and it appears to be stable. I did not notice any hazardous conditions to the embankments. The refuse pile has been inactive for several years. See Photos

8. Noncoal Waste

The property was clear of non-coal waste materials such as oil, trash and grease cans.

10. Slides and Other Damage

No slides or other damage was notice during the inspection. The Loadout appears to be stable.

16.a Roads: Construction, Maintenance, Surfacing

The roads were compacted with no dust control problem.

16.b Roads: Drainage Controls

I inspected the road diversions and culverts throughout the property. They were functioning as design. See Photos

Permit Number: C0070033
Inspection Type: PARTIAL
Inspection Date: Tuesday, July 2, 2019

18. Support Facilities, Utility Installations

No new facilities constructed since the last inspection.

NO
SURVEILLANCE
CAMERAS
IN USE

SPEED
LIMIT
5

ATTENTION
SIGN IN AT
SCALE HOUSE
PRIOR TO
PROCEEDING
ONTO PROPERTY

NOTICE
WITHOUT PRIOR APPOINTMENT
DELIVERIES, VENDORS, VISITORS,
AND JOB APPLICANTS MUST
CHECK IN AT MAIN OFFICE
LOCATED AT MINE SITE.

WILDCAT LOADOUT

OWNER: COAL ENERGY GROUP, L.L.C.
EAGLE 11430013
NAPLES 11430014
MORSE 11430015
LIBOJA 11430016

OWNER: COAL ENERGY GROUP, L.L.C.
ANDERSON 11430017
NAPLES 11430018
MORSE 11430019
NASH 11430020



WILDCAT LOADOUT

OWNER: COAL ENERGY GROUP 2, LLC
6602 ILEX CIRCLE
NAPLES, FLORIDA 34109
PHONE: 239-825-2332
UDOGM PERMIT NO. C/007/033

OWNER: COAL ENERGY GROUP 2, LLC
6602 ILEX CIRCLE
NAPLES, FLORIDA 34109
PHONE: 239-825-2332
MSHA ID NO. 42-01864















22 1/2 MI N
POND





TOP SOIL
STORAGE

TOP S
STOR



