



State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA
Division Director

Inspection Report

Permit Number:	C0070033
Inspection Type:	COMPLETE OVERSITE
Inspection Date:	Wednesday, October 30, 2019
Start Date/Time:	10/30/2019 9:00:00 AM
End Date/Time:	10/30/2019 4:00:00 PM
Last Inspection:	Thursday, October 3, 2019

Representatives Present During the Inspection:	
OSM	Tom Medlin
OGM	Steve Demczak
Company	Lee Tweddel
Company	Larry Johnson

Inspector: Steve Demczak

Weather: Sunny, 30's Slightly Snow Covered

InspectionID Report Number: 6554

Accepted by: SCHRISTE

11/4/2019

Permittee: **COAL ENERGY GROUP 2, LLC**
 Operator: **COAL ENERGY GROUP 2, LLC**
 Site: **WILDCAT LOADOUT**
 Address: **6602 ILEX CIRCLE, NAPLES FL 34109**
 County: **CARBON**
 Permit Type: **PERMANENT COAL PROGRAM**
 Permit Status: **INACTIVE**

Current Acreages

111.62	Total Permitted
111.62	Total Disturbed
	Phase I
	Phase II
	Phase III

Mineral Ownership

- Federal
- State
- County
- Fee
- Other

Types of Operations

- Underground
- Surface
- Loadout
- Processing
- Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

he loadout was idle. This loadout will be used when Kinney Mines opens up and begins to mine coal.

The permittee needs to get a Storm water, Pollution, Prevention Plan from DWQ.

Stephen J. Demczak

Inspector's Signature:

Steve Demczak,
Inspector ID Number: 39

Date Wednesday, October 30, 2019



Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining. telephone (801) 538-5340 • facsimile (801) 359-3940 • TTY (801) 538-7458 • www.ogm.utah.gov

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

	Evaluated	Not Applicable	Comment	Enforcement
1. Permits, Change, Transfer, Renewal, Sale	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Signs and Markers	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Topsoil	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.a Hydrologic Balance: Diversions	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.b Hydrologic Balance: Sediment Ponds and Impoundments	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.c Hydrologic Balance: Other Sediment Control Measures	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.d Hydrologic Balance: Water Monitoring	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.e Hydrologic Balance: Effluent Limitations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
5. Explosives	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Disposal of Excess Spoil, Fills, Benches	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Coal Mine Waste, Refuse Piles, Impoundments	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
8. Noncoal Waste	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
9. Protection of Fish, Wildlife and Related Environmental Issues	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Slides and Other Damage	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
11. Contemporaneous Reclamation	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Backfilling And Grading	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. Revegetation	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14. Subsidence Control	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. Cessation of Operations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
16.a Roads: Construction, Maintenance, Surfacing	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
16.b Roads: Drainage Controls	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
17. Other Transportation Facilities	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
18. Support Facilities, Utility Installations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
19. AVS check	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
20. Air Quality Permit	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
21. Bonding and Insurance	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
22. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

1. Permits, Change, Transfer, Renewal, Sale

Sediment pond inspection – Annual Certification Dec 20, 2018 and 4th quarter inspection, P.E Certified, no hazardous conditions were reported.

SPCC Plan – October 10, 2016

UPDES Permit – UTG-040007, March 31, 2024

Air quality, DAQE -GN101130011-19

Bond - \$1,192,000 Surety bond, RLI Insurance Copany , Policy # Ro6001354

DOGM Permit - EXP May 5, 2019, renewal has been submitted to Division Insurance – Arch Insurance Co., EPO 13570200, Expire on Sept. 1. 2019,

BLM Rental Fee – was paid for 2019

Business License – Carbon County #74102, Exp 12/31/19

2. Signs and Markers

The identification sign was inspected and it meets the requirements of the R645 Coal Rules. See Photo

3. Topsoil

I inspected the topsoil piles and I did not see any signs of wind or water erosion. The topsoil piles appear to be stable and protected by a berm. See Photo

4.a Hydrologic Balance: Diversions

I inspected diversions and culverts throughout the property. They were open and would function as design in a storm event. There are a few tumble weeds at the inlets and outlets of diversions and culverts. These will be clean out in the Spring. See Photos.

4.b Hydrologic Balance: Sediment Ponds and Impoundments

I inspected the sediment ponds throughout the property. They contained some water but were not discharging. It is unlikely these structures will discharge in the near future. The embankments appear to be stable. Inlets and outlets would function as design. I did not see any hazardous conditions to these structures. The permittee conducted a third quarter sediment pond inspections on September 23, 2019. No hazardous conditions were reported.

4.d Hydrologic Balance: Water Monitoring

Water monitoring information is taken by the permittee and is sent electronically to the Division in Salt Lake City. This information is reviewed and analyzed by the Division staff. A report is written. The permittee was in compliance with the UPDES permit for the third quarter.

4.e Hydrologic Balance: Effluent Limitations

No discharge for the third quarter.

7. Coal Mine Waste, Refuse Piles, Impoundments

I inspected the refuse pile and it appears to be stable. I did not notice any hazardous conditions to the embankments. The refuse pile is inactive. The permittee conducted a third quarter refuse pile inspection on September 23, 2019. This document is P.E. certified. No hazardous conditions were reported. See Photos

8. Noncoal Waste

The site was clean of non-coal waste materials such as trash, oil cans, wood and scrap materials.

10. Slides and Other Damage

No slides or other damage was notice during the inspection. The Loadout appears to be stable.

15. Cessation of Operations

16.a Roads: Construction, Maintenance, Surfacing

The roads were compacted with no dust control problem.

16.b Roads: Drainage Controls

I inspected the road diversions and culverts throughout the property. They were functioning as design. Some tumble weeds at inlets and outlets. Permittee had clean out weeds, but , more weed fill diversions after windstorm.

18. Support Facilities, Utility Installations

No new facilities constructed since the last inspection.

19. AVS check

AVS checks are made in Salt Lake City.

20. Air Quality Permit

21. Bonding and Insurance

The insurance Company affording coverage is Arch Insurance Co. The policy number is #EPO1037502-01. This policy will expire on August 31, 2019. The Surety bond is for the amount of \$1,192,000.

NOTICE
NO ENTRY
WITHOUT PRIOR APPOINTMENT
DELIVERIES, VENDORS, VISITORS,
AND JOB APPLICANTS MUST
CHECK IN AT MAIN OFFICE
LOCATED AT MINE SITE.

SURVEILLANCE
CAMERAS
IN USE

**SPEED
LIMIT
5**

ATTENTION
SIGN IN AT
SCALE HOUSE
BEFORE TO
PROCEEDING
ONTO PROPERTY

WILDCAT LOADOUT
OWNER: COAL ENERGY GROUP S.L.C.
800 S EX 0900
TAPPAH, KANECA, AZ85
PHONE: 208-625-2302
REGISTRATION NO: C207033
OWNER: COAL ENERGY GROUP S.L.C.
800 S EX 0900
TAPPAH, KANECA, AZ85
PHONE: 208-625-2302
REGISTRATION NO: C207033

NOTICE
WITHOUT PRIOR APPOINTMENT
DELIVERIES, VENDORS, VISITORS,
AND JOB APPLICANTS MUST
CHECK IN AT MAIN OFFICE
LOCATED AT MINE SITE.











SEDIMENT
POND
F







TOP SOIL
STORAGE





INTERMOUNTAIN POWER AGENCY (PERMITTEE) & SUBSIDIARY CO.
**Intermountain
Power Agency**
MSHA ID
42-01864







