0001

Document Information Form

Mine Number: C/007/034

File Name: Incoming

To: DOGM

From:

Person N/A

Company United States Department of the Interior

Date Sent: N/A

Explanation:

Mine Site Evaluation Inspection Report

cc:

File in:
C/ 007 , 034 , **Incoming**
Refer to:
- ☐ **Confidential**
- ☐ **Shelf**
- ☐ **Expandable**

Date _____ For additional information

United States Department of the Interior
Office of Surface Mining
Mine Site Evaluation Inspection Report

For Office Use Only

1a (Y Y M M):
1b (Batch):
1c (Report):

2. Name of Permittee: SOLDIER CREEK CL CO

3. Street Address: PO BOX 1

4. City: PRICE

5. State: UT

6. Zip Code: 84501

7. Area Code: 801

8. Telephone Number: 637-6360

9. MSHA Number: 42-00077-

10. Date of Inspection (Y Y M M D D): 870723

11. State Permit Number: PRO/007/034

12. Name of Mine: BANNING SIDING LDOUT

13. County Code: 007

14. State Code: UT

15. Strata:

16. State Area Office: 01

17. OSM Field Office No.: 02

18. OSM Area Office No.:

19. OSM Sample No.: 0139

20. Type of Inspection (Code): C

21. Joint Inspection Yes: X No:

22. Inspector's ID No.: 006

23. Status

A	01	Type of Permit
B	A	Mine Status (Code)
C	34	Type of Facility (Code)
D	00000.0	Number of Permitted Acres
E	00025.0	Number of Disturbed Acres

24. Type of Activity (check applicable boxes).

A	☐	Steep Slope	E	☐	Anthracite
B	☐	Mountain Top Removal	F	■	Federal Lands
C	☐	Prime Farmlands	G	☐	Indian Lands
D	☐	Alluvial Valley Floors	H	☐	Other

25. Performance Standards (Codes)

Instructions: Indicate compliance code. For any standard marked 2 or 3 provide narrative to support this determination.

Standards That Limit the Effects to the Permit Area

A	3	Distance Prohibitions
B	3	Mining Within Permit Boundaries
C	1	Signs and Markers
D	1	Sediment Control Measures
E	3	Design and Certification Requirements—Sediment Control
F	1	Effluent Limits
G	3	Surface Water Monitoring
H	3	Ground Water Monitoring
I	3	Blasting Procedures
J	1	Haul/Access Road Design and Maintenance
K	3	Refuse Impoundments
L	3	Other: Specify

Standards That Assure Reclamation Quality and Timeliness

M	1	Topsoil Handling
N	1	Backfilling and Grading
O	1	Following Reclamation Schedule
P	1	Revegetation Requirements
Q	3	Disposal of Excess Spoil
R	3	Har
S	3	Hig
T	3	Dov
U	1	Pos
V	3	Ces
W	3	Oth

File in:
- ☐ **Confidential**
- ☐ **Shelf**
- ☐ **Expandable**

Refer to Record No 0001 **Date** _____
In C/ 007 , 034 , **Incoming**
For additional information

Distribution: Original - Field Office, Green - Headquarters, Blue - State's Copy, Yellow - Inspector's Copy, Pink - File Copy

United States Department of the Interior
Office of Surface Mining
Mine Site Evaluation Inspection Report

For Office Use Only

1a (Y Y M M):
1b (Batch):
1c (Report):

2. Name of Permittee: SOLDIER CREEK CL CO

3. Street Address: PO BOX 1

4. City: PRICE

5. State: UT

6. Zip Code: 84501

7. Area Code: 801

8. Telephone Number: 637-6360

9. MSHA Number: 42-00077-

10. Date of Inspection (Y Y M M D D): 870723

11. State Permit Number: PRO/007/034

12. Name of Mine: BANNING SIDING LDOUT

13. County Code: 007

14. State Code: UT

15. Strata:

16. State Area Office: 01

17. OSM Field Office No.: 02

18. OSM Area Office No.:

19. OSM Sample No.: 0139

20. Type of Inspection (Code): C

21. Joint Inspection Yes: X No:

22. Inspector's ID No.: 006

23. Status

A	01	Type of Permit
B	A	Mine Status (Code)
C	34	Type of Facility (Code)
D	00000.0	Number of Permitted Acres
E	00025.0	Number of Disturbed Acres

24. Type of Activity (check applicable boxes).

A	☐	Steep Slope	E	☐	Anthracite
B	☐	Mountain Top Removal	F	■	Federal Lands
C	☐	Prime Farmlands	G	☐	Indian Lands
D	☐	Alluvial Valley Floors	H	☐	Other

25. Performance Standards (Codes)

Instructions: Indicate compliance code. For any standard marked 2 or 3 provide narrative to support this determination.

Standards That Limit the Effects to the Permit Area

A	3	Distance Prohibitions
B	3	Mining Within Permit Boundaries
C	1	Signs and Markers
D	1	Sediment Control Measures
E	3	Design and Certification Requirements—Sediment Control
F	1	Effluent Limits
G	3	Surface Water Monitoring
H	3	Ground Water Monitoring
I	3	Blasting Procedures
J	1	Haul/Access Road Design and Maintenance
K	3	Refuse Impoundments
L	3	Other: Specify _____

Standards That Assure Reclamation Quality and Timeliness

M	1	Topsoil Handling
N	1	Backfilling and Grading
O	1	Following Reclamation Schedule
P	1	Revegetation Requirements
Q	3	Disposal of Excess Spoil
R	3	Handling of Acid or Toxic Materials
S	3	Highwall Elimination
T	3	Downslope Spoil Disposal
U	1	Post Mining Land Use
V	3	Cessation of Operations: Temporary
W	3	Other _____

United States Department of the Interior
Office of Surface Mining
Mine Site Evaluation Inspection Report

26. State Permit Number AR0107134

27. Date of Inspection (Y Y M M D D) 870923

28. Do mining and reclamation activities on the site comply with the plans in the permit? Yes ☐ No ☐
If no, provide narrative to support this determination. N/A

29. Indicate number of complete and partial inspections conducted by the State to date for this annual review period:

29a. 00 Number of Completes 29b. 03 Number of Partials

30. Indicate number of complete and partial inspections required by the State during this annual review period:

30a. 00 Number of Completes 30b. 02 Number of Partials

31. Has inspection frequency been met?

31a. Yes ☒ No ☐ Completes 31b. Yes ☒ No ☐ Partials

32. FEDERAL ENFORCEMENT INFORMATION. [Enter violation number. Check appropriate box(es)]

	Ten-Day Notice No.	Notice of Violation No.	Cessation Order No.	Violation Codes
A	☐	☐	☐	Authorizations to Operate
B	☐	☐	☐	Signs and Markers
C	☐	☐	☐	Backfilling and Grading
D	☐	☐	☐	Highwall Elimination
E	☐	☐	☐	Rills and Gullies
F	☐	☐	☐	Improper Fills
G	☐	N/A	☐	Topsoil Handling
H	☐	☐	☐	Sediment Ponds
I	☐	☐	☐	Effluent Limits
J	☐	☐	☐	Water Monitoring
K	☐	N/A	☐	Buffer Zones
L	☐	☐	☐	Roads
M	☐	☐	☐	Dams
N	☐	☐	☐	Blasting
O	☐	☐	☐	Revegetation
P	☐	☐	☐	Spoil on the Downslope
Q	☐	☐	☐	Mining Without Permit
R	☐	☐	☐	Exceeding Permit Limits
S	☐	☐	☐	Distance Prohibitions
T	☐	☐	☐	Toxic Materials
U	☐	☐	☐	Other Violations

United States Department of the Interior

Mine Site Evaluator

33. Name of Authorized Representative *(print or type)*

Signature of Authorized Representative	Date
	09/23/87
Signature of Reviewing Official	**Date**
	9/28/87

02 0
07 5
02 0
01 0

MSEIR NARRATIVE

PERMIT NUMBER PRO/002/034
INSPECTION DATE 09/23/87

General Summary:

This is OSM's first inspection, a complete, conducted with Chris Allen (Operator), Boyd Rhodes (Operator), and Holland Shepherd (DOGM). Ground conditions were dry.

Following, is the permitting status:

No approved plan exists for this facility. A submittal date of 12/31/87 is currently set for the entire permit application.

Following, is the bonding status:

No bond is posted for the area yet.

Following, is the drainage control status:

No diversions or ponds are yet required. No stream buffer zones or stream channel diversions exist. Currently, all disturbed area drainage is passing through sumps and straw bale check dams - crude siltation structures but adequate til permit approval.

Following, is the water monitoring status:

No surface or ground water sampling is required yet by DOGM. The NPDES permit exists but was not available for review.

Following, is the field status:

This loadout facility handles all coal from Soldier Creek Coal Company's Soldier Canyon Mine. Crushing and loading onto trains is active.

Following, is the enforcement action status:

No state or federal enforcement actions are outstanding.