12-28-87 0001

file SU

UTAH NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

inspection report

Permit No. PRO/007/034

Inspection Date 12-17-87

Permittee/Operator Name Soldier Creek Coal Co.

Business Address PO Box I

City Price State Utah Zip 84501

Mine Banning Siding Prep. Plant ☐ Surface ☐ Underground ☑ Other

County Carbon State Utah

Company Official(s) Chris Allen

State Official(s) Holland Shepherd, Daron Haddock

Time of inspection 9:00 ☑ a.m. ☐ p.m. to 11:00 ☑ a.m. ☐ p.m. ☐ Partial ☑ Complete

Date of last inspection 11-24-87 Weather conditions cloudy, cold

Acreage 36.0 ☐ Permitted 20.9 ☐ Disturbed 0 ☐ Regraded 0 ☐ Seeded N/A ☐ Bonded

Enforcement Action none

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☑	☐	☐	☑
2. Signs and markers	☑	☐	☐	☐
3. Topsoil	☐	☐	☑	☐
4. Hydrologic balance				
— Stream channel diversions	☐	☐	☑	☐
— Diversions	☐	☐	☑	☐
— Sediment ponds and impoundments	☐	☐	☑	☐
— Other sediment control measures	☑	☐	☐	☐
— Surface and groundwater monitoring	☐	☐	☑	☐
— Effluent limitations	☑	☐	☐	☑
5. Explosives	☐	☐	☑	☐
6. Development waste and spoil disposal	☐	☐	☑	☐
7. Coal processing waste	☐	☐	☑	☐
8. Noncoal waste	☑	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☑	☐	☐	☐
10. Slides and other damage	☐	☐	☑	☐
11. Contemporaneous reclamation	☐	☐	☑	☐
12. Backfilling and grading	☐	☐	☑	☐
13. Revegetation	☐	☐	☑	☐
14. Subsidence control	☐	☐	☑	☐
15. Cessation of operations	☐	☐	☑	☐
16. Roads				
— Construction	☐	☐	☑	☐
— Drainage controls	☑	☐	☐	☑
— Surfacing	☑	☐	☐	☐
— Maintenance	☑	☐	☐	☐
17. Other transportation facilities	☑	☐	☐	☐
18. Support facilities and utility installations	☑	☐	☐	☐

WHITE — DOGM YELLOW — OSM PINK — PERMITTEE/OPERATOR GOLDENROD — NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. PRO/007/034

Inspection Date 12-17-87

Please number comments to correspond with topics on previous page.

1. Permits:

Mr. Allen indicated that the Banning Siding PAP will be submitted by the end of this month. The Division and operator had agreed earlier that the PAP would be submitted at the end of December 1987.

4. f. Effluent Limitations:

The operator's UPDES discharge point 001 has been recorded as having no discharge last quarter or the previous ~~last~~ 3 quarters. Mr. Allen indicated that water is pumped, periodically, from a tank below the grizzly. The water drains to a settling facility where it evaporates. When the site is upgraded to meet permit specifications, the holding tank water will be pumped directly into the wash adjacent to the ~~[illegible]~~ plant site.

16. Road ~~Maintenance~~, Drainage Controls:

I asked Mr. Allen to remove some debris from the vicinity of the outlet of the 48" culvert on the operator's haul road.

Copy of report mailed to Chris Allen (SCCC), Brian Smith (OSM)

Copy of report given to Joe Helfrich (DOGM), Daron Haddock (DOGM)

Inspector's signature [signature] 12-21-87 No. 9

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE